

Past to colla



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/12/2019

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB111Z
Case Reference Number	BUS/10/19/5018
Registration Date	13/8/2009
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	Jia Xuguang
Type of Accident	Head to Rear
Accident Date and Time	16/10/2019 7:30 PM
Accident Reported Date and Time	17/10/2019 11:10 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24104298
Special Instruction to ARC, if any	SMB111Z-REAR PORTION SHA3693E (TP) INSURED WITH III
Prepared Date and Time	13/11/2019 10:28 AM
Chassis Number	WEB63442021000241
Mileage	
Work Shop	
Repair Completion Date and Time	

\$750

1 day

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$602.00	\$432.00
Total Spare Part Cost	\$50.33	\$50.33
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,182.33	\$747.33
Lump Sum Total	\$0.00	\$750.00
Number of Repair Days	2.0	1.0
Prepared / Adjusted By	Jeong Choon Hwee	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	13/11/2019 10:36 AM	13/11/2019 4:08 PM
Signature		
Remarks		Lump sum repair, Take after paint photo

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/12/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	\$530.00	\$265.00
Total Labour	\$530.00	\$265.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$602.00	\$432.00
Total Spray Painting & Panel Beating	\$602.00	\$432.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009519	Body		REFLEX REFLECTOR,RED FOR MB OC500LE	1.00	\$69.90	10.00	\$62.91	Replace	Replace
6009366	Body		BUMPER,REAR,FIBREG LASS,FOR MB OC500 BUS	1.00	\$1,863.00	100.00	\$0.00	Repair	Repair
6009369	BODY RH		COVER,LAMP,REAR,RH, FOR MB OC500 BUS	1.00	\$1,242.00	100.00	\$0.00	Repair	Repair
Total					\$3,174.90		\$62.91		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685582
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/11/2019

User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	\$530.00	\$265.00
Total Labour	\$530.00	\$265.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$602.00	\$432.00
Total Spray Painting & Panel Beating	\$602.00	\$432.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009519	Body		REFLEX REFLECTOR,RED FOR MB OC500LE	1.00	\$69.90	10.00	\$62.91	Replace	Replace
6009366	Body		BUMPER REAR FIBREGLASS FOR MB OC500 BUS	1.00	\$1,863.00	100.00	\$0.00	Repair	Repair
6009369	BODY RH		COVER,LAMP REAR,RH, FOR MB OC500 BUS	1.00	\$1,242.00	100.00	\$0.00	Repair	Repair
Total					\$3,174.90		\$62.91		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair day - 1 day

Sun Pin.

13/11/2019

TP without prejudice.

Lump Sum
~~8/P~~ Repair
After spray photo.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662523
Accident Reporting Number : 68662672

Date Generated : 13/11/2019

User ID : JeongCH

Section A - Accident Details

Registration Number	SMB111Z
Case Reference Number	BUS/10-19/5018
Registration Date	8/13/2009
Company Type	SMRT Buses Ltd
Make	MFRCDFDS
Model	MBOC500
Name of Driver	Ja Xuguang
Type of Accident	Head to Rear
Accident Date and Time	10/16/2019 7:30 PM
Accident Reported Date and Time	10/17/2019 11:10 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC if any	SMB111Z-REAR PORTION SHA3693E (TP) INSURED WITH III
Prepared Date and Time	11/13/2019 10:28 AM
Chassis Number	WEB63442021000241
Mileage	
Wreck Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$602.00	\$432.00
Total Spare Part Cost	\$50.33	\$62.91
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,182.33	\$759.91
Lump Sum Total	\$0.00	\$750.00
Number of Repair Days	2.0	1.0
Prepared / Adjusted By	Jeong Choon Hwee	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	13/11/2019 10:36 AM	13/11/2019 4:08 PM
Signature		
Remarks	Lump sum repair. Take after paint photo	

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	