





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/11/2019

User ID : JeongCH

Section A - Accident Details	
Registration Number	SMB111Z
Case Reference Number	BUS/10/19/5018
Registration Date	8/13/2009
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	Jia Xuguang
Type of Accident	Head to Rear
Accident Date and Time	10/16/2019 7:30 PM
Accident Reported Date and Time	10/17/2019 11:10 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC,if any	SMB111Z-REAR PORTION SHA3693E ( TP ) INSURED WITH III
Prepared Date and Time	11/13/2019 10:28 AM
Chassis Number	WEB63442021000241
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$0.00
Total Spray Cost	\$602.00	\$0.00
Total Spare Part Cost	\$50.33	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,182.33	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	2.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	13/11/2019 10:36 AM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/11/2019

User ID : JeongCH

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope				Quotation from AR				Adjusted by Surveyor, if applicable	
TO REPAIR RH REAR PORTION				\$530.00					
Total Labour				\$530.00					
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
TO PUTTY & RESPRAY				\$602.00					
Total Spray Painting & Panel Beating				\$602.00					
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009519	Body		REFLEX REFLECTOR,RED FOR MB OC500LE	1.00	\$69.90	10.00	\$62.91	Replace	
6009366	Body		BUMPER,REAR:FIBREG LASS,FOR MB OC500 BUS	1.00	\$1,863.00	100.00	\$0.00	Repair	
6009369	BODY RH		COVER,LAMP:REAR,RH, FOR MB OC500 BUS	1.00	\$1,242.00	100.00	\$0.00	Repair	
Total					\$3,174.90		\$62.91		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									