

ASS. REC. BY:

REF: CS/FCI/9020253/Uvd3/n2

Special Instruction:

Junior: McKILLASSIGNMENT (Office)From (Person): Karen Tanof FCIDate/Time: 12:54pm @ 14/11/19

Estimated Cost:

Bill to:

OH / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIN 2539HInsured: SHC 8456E

at Workshop in/s

Z-one AutomotiveTel: 6634 2112

of

11 Calki Bukit Ave 6 #01-57 Autobay

Policy No:

Claim No: D19007209MF8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 12/11/2019

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time: 2:17pm @ 14/11/19

Person Contacted:

ShahVehicle IN/OUT

Date/Time

Action/Instruction

Johny/11 ✓SIN 2539H - XSHC 8456E - CS/CI/19010934 / AccsDon: 17/6/1915/11/19Sent E-Mail to Insurance (Pending Estimate)18/11/19Email preli revised to FCI

ASS. REC. BY:

Title:

Fol/

M/CUS

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJN 25394

Yr Regn:

209

Type: M.Cy / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Toyota Rush

c.c. 1495

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

242582

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

J200 E0023549

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Incident / Jammed / Leaked / Burnt or

Brake: Incident / Jammed / Leaked / Burnt or

Modi: Nil / STD / STD A/Rim or

Tyre Size:

F:

215/65 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MMC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

12/11/19

D.O.A.

14/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

for unt. 1-9-2-2029 LTA 23762

18/11/19 4/s \$6200 confirmed with AM Sway (Red 64RS.95, SIM)

MV: \$42K (EST) LTA: \$23,762 NV: \$18,238

RECEIVED 19 NOV 2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

18/11 - typist

Report Format:

aws

Lump Sum / 1st/2nd/3rd

6200/-

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Insp (\$)

☐

: Asst Insp (\$)

Survey Fee:

Transportation:

S + RS \$1

Purpos

Advers

TOTAL

2415-30

170+30

50

50

85

385



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007209MFSH

Our ref: CS/FCI19020253/Uvd3

DATE: 18/11/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO SJN 2539H

We thank for your instruction on 14/11/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 14/11/2019 at the premises of M/s Z-ONE AUTOMOTIVE PTE LTD

Workshop Estimate Amount : S\$12,685.95

Revised Estimate Amount : S\$6,200.00 (LUMP SUM)

"Check" Items Amount : S\$


Market Value : S\$

LTA Reimbursement Value : S\$

Nett Value : S\$

Description of Damage:

The vehicle sustained damages at the rear n/s portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	13-11-2019	Our Ref No. D19007209MFSH
Accident Date	12-11-2019	Claim Type. Third Party
Insured Vehicle	SHC8456E	Third Party Vehicle. SJN2539H
Survey Location	1 KAKI BUKIT AVE 6 BLK D #01-87 AUTOBAY@KAKI BUKIT	
Contact Person.	GWEN TAY	
Contact No.	66342112/66342292/ 0	Fax No. 66342122
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	Z-ONE AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 18 November 2019 3:56 PM
To: Yvonne Wong (LKK Auto); 'CWS Motor Claims'
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19007209MFSH/1-SJN 2539H
Attachments: SJN 2539H PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJN 2539H
Date of survey: 14/11/2019
Number of days (estimated) : 6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yvonne Wong (LKK Auto) <yvonnewong@lkkauto.com>
Sent: Friday, 15 November 2019 12:22 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19007209MFSH/1

Afternoon Karen

Please be informed that we have inspected the vehicle SJN2539H on 14/11/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, November 14, 2019 2:25 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19007209MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Thursday, 14 November 2019 12:54 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19007209MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System


Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Friday, November 15, 2019 12:22 PM
To: 'CWS Motor Claims'
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19007209MFSH/1

Afternoon Karen

Please be informed that we have inspected the vehicle SJN2539H on 14/11/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, November 14, 2019 2:25 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19007209MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 14 November 2019 12:54 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19007209MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System


Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Google Home.

Hands-free help around the house.

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2018 A5 Cabriolet 2.0A TFSI S-Tronic Design, \$191.8K.



1 Owner, Done Only 12,125km,
5 Years Unlimited Mileage
Warranty By Agent
Faster Auto Trading Started



Browse by Category ▼

Sort by Date Posted ▼

6 vehicles

rush

Advanced Search 🔍

	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection	rush	Any	Any	2009	Any	Any	Any
	Toyota Rush 1.5A X (COE till 10/2024)	\$33,800	\$6,810 /yr	11-Nov-2009	1,495 cc	107,676 km	SUV
(Pearl White Unit!) Vehicle Fully Done Up In Showroom Condition With Premium Grooming And Brand New Paint Coat. Purchase Comes With 6 Months Engine And Gearbox Protection Plan With 24/7 Roadside Assistance Coverage. Genuine Deal With No Gimmick. Bank And L...							
Sincere Motoring Pte Ltd							
Posted: 13-Nov-2019 Tags: 2009 Toyota Rush, 2009 toyota rush, Toyota Rush, toyota rush, Toyota, Rush, rush, Used Toyota							
	Toyota Rush 1.5A X (New 5-yr COE)	\$32,888	\$6,570 /yr	25-Nov-2009	1,495 cc	-	SUV
Easily Maintain SUV! Low Maintenance Cost, Very Well Maintained By Previous Owner! Free Basic Grooming Upon Collection Date! High Loan And High Vaule Trade In Avail! Best Loan Rates In Town! Try Out Our Latest V.T.A.C Loan Services! Extended Warranty By Our Ve...							
Posted: 12-Nov-2019 Tags: 2009 Toyota Rush, 2009 toyota rush, Toyota Rush, toyota rush, Toyota, Rush, rush, Used Toyota							
	Toyota Rush 1.5A X (COE till 08/2024)	\$34,000	\$7,090 /yr	04-Sep-2009	1,495 cc	126,025 km	SUV
New Arrival! Excellent Condition As Many Wear And Tear Parts Are Replaced. No Repair Needed! Buy With Confidence! Purchase Comes With FREE Warranty And Servicing. Loan Support Is Available. (Viewing Arrangement Is Available Till 9PM Daily).							
Posted: 04-Nov-2019 Tags: 2009 Toyota Rush, 2009 toyota rush, Toyota Rush, toyota rush, Toyota, Rush, rush, Used Toyota							
	Toyota Rush 1.5A X (COE till 10/2029)	\$48,800	\$4,900 /yr	12-Nov-2009	1,495 cc	-	SUV
Efizzig Motor Traders. Roxy Square Carmart Level 5. We Provide In House And Other Financial Services To Meet Your Budget. Call Us Or Even Better, Come On Down Now And Decide For Yourself.							
Posted: 21-Oct-2019 Tags: 2009 Toyota Rush, 2009 toyota rush, Toyota Rush, toyota rush, Toyota, Rush, rush, Used Toyota							

**GET YOUR
COE
RENEWAL
LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and approval in 2 days without effort! Enquire today.

Toyota Rush 1.5A X (New 5-yr) \$34,800 \$6,950 /yr 27-Oct-2009 1,495 cc 101,000 km SUV

Compare

/In House Loan, 100% Loan Available! Attractive Interest Rate! Trade In Welcome! Cheapest In The Market! Extremely Well

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 516B

Vehicle Details

Vehicle No.: SJN2539H
Vehicle to be Exported: No
Intended Deregistration Date: 15 Nov 2019
Vehicle Make: TOYOTA
Vehicle Model: RUSH 1.5X A
Primary Colour: Grey
Manufacturing Year: 2008
Engine No.: 3SZ2176632
Chassis No.: J200E0023549
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$13,473.00
Original Registration Date: 10 Feb 2009
First Registration Date: 10 Feb 2009
Transfer Count: 1
Actual ARF Paid: \$13,473.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 09 Feb 2029
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
PQP Paid: \$25,727.00
COE Rebate Amount: \$23,762.00
Total Rebate Amount: \$23,762.00

The information contained herein is correct as at 15 Nov 2019

OK



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

Lau Tiam Aik
Blk474 Segar Road #04-308 Singapore 670474

Contact: 9366 4778

ESTIMATE

Code: C101939

Date in: 13/11/2019

Vehicle Num.: SJN2539H

Model: TOYOTA RUSH 1.5X A

Chassis/Eng#: J200E0023549/3SZ2176632

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
Rear Bumper <i>DIJ ✓</i>	1	441.70	441.70 ✓
Rear Bumper No. Plate Lamp L/R <i>MAX</i>	2	69.00	138.00 X
Rear Bumper Side Reflector L/R <i>M/S one lpc</i>	2	59.10	118.20 lpc
Rear Bumper Side Retainer L/R <i>M/S both lpc</i>	2	65.10	130.20 lpc
Rear Bumper Towing Cover <i>1 X</i>	1	60.10	60.10 X
Rear End Panel (Inner) <i>RX</i>	1	494.70	494.70 X
Rear End Panel (Outer) <i>both 20 ✓</i>	1	367.80	367.80 ✓
Rear End Panel Inner Top Garnish <i>Tw ✓</i>	1	124.10	124.10 ✓
Rear End Panel Inner Top Garnish Clips <i>1 X</i>	3	8.90	26.70 X
Rear Exhaust Center Pipe <i>2 X</i>	1	1556.70	1,556.70 X
Rear Exhaust Silencer Box <i>both 1 ✓</i>	1	786.80	786.80 ✓
Rear Exhaust Silencer Box Rubber Mounting <i>1 X</i>	2	55.10	110.20 X
Rear Tailgate <i>5.13.07 ✓</i>	1	971.80	971.80 ✓
Rear Tailgate 'Rush' Emblem <i>me ✓ 66.50</i>	1	110.00	110.00 ✓
Rear Tailgate 'Toyota' Emblem <i>me ✓</i>	1	56.00	56.00 ✓
Rear Tailgate Checker <i>1 X</i>	1	191.00	191.00 X
Rear Tailgate Hinge <i>1 X</i>	2	61.00	122.00 X



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

Rear Tailgate Inner Trimboard	Re/cu ✓	1	490.10	490.10 ✓
Rear Tailgate Lock Striker	117	1	55.00	55.00 X
Rear Tailgate Mechanism Lock	shhd ✓	1	309.10	309.10 ✓
Rear Tailgate Outer Handle	11 X	1	210.10	210.10 X
Rear Tailgate Rubber Guide Stopper	111 ✓	2	23.10	46.20 ✓
Rear Tailgate Spare Tyre Bracket	Bul ✓	1	410.00	410.00 ✓
Rear Tailgate Spare Tyre Cover	111 ✓	1	1687.00	1,687.00 ✓
Rear Tailgate Spare Tyre Retainer Lock	111 X	1	48.80	48.80 X
Rear Tailgate Weather Strip	111 ✓	1	335.50	335.50 ✓
Rear Taillamp L/R	N/5 cng 111 X	2	480.00	960.00 111 X
Rear Taillamp Stay Clips L/R	111 X	2	5.90	11.80 X

Subtotal before discount

10,369.60

Percentage discount 25%

2,592.40

Sub-total 1

7,777.20

Rear Bumper Clips (Set)(SN)	111 ✓	1	30.00	30.00 ✓
Rear Bumper No. Plate (SN)	111 405. ✓	1	25.00	25.00 ✓
Rear Bumper No. Plate Garnish (SN)	111	1	50.00	50.00 } 40
Rear Bumper Reverse Sensor (Set)(SN)	shhd 200	1 set	350.00	350.00 200
Rear Tailgate Inner Trimboard Clips (Set)(SN)	111 ✓	1	30.00	30.00 ✓
Rear Tailgate Spare Tyre (SN)	811 X	1	280.00	280.00 X

page 2



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg ; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

Rear Tailgate Spare Tyre Cover Lock (SN) <i>nan</i>	1	60.00	60.00	<i>X</i>
Rear Tailgate Windscreen Sealant (SN) <i>nan</i>	1	80.00	80.00	<i>40</i>
Subtotal before discount			905.00	
Percentage discount: 0%			0.00	
Sub-total 2			905.00	
Parts-total			8,682.20	

LABOUR

Description	Price	
Diagnose, replace and/or repair to rectify rear portion electrical system for proper functioning.	120.00	<i>30</i>
To remove, refix / renew reverse sensor assy and rectify for proper functioning.	120.00	<i>50</i>
To remove, reinstall rear tailgate windscreen to FR	150.00	<i>120</i>
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. to FR	100.00	<i>60</i>
To transfer tailgate/bootlid mechanism and wiring assy (to FR)	150.00	<i>60</i>
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,400.00	<i>1100</i>
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	150.00	<i>60</i>
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,600.00	<i>1000</i>
To apply anti-rust chemical (Tuff-Kote) on repaired and replaced panel.	120.00	<i>60</i>
Labour Total	3,910.00	
Parts & Labour Total	12,592.20	
	12,685.95	<i>2540</i>

LKX Auto Consultants hereby notify the Receiver of the following:

- * Estimated repair cost for spray painting
- * To change damaged part(s) to new one
- * Replacement with 100% to construction
- * The replacement is for a "Value-Adjusted" base
- * Replacement part(s) is a brand
- * Replacement part(s) must be covered and is subject to approval from Insurance Company

Acknowledged by Receiver

Signature:

Date:

P-6581.90
252
P-4936.42
S.N-340.00
L-2540.00
7816.22
6253.13



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg ; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

ESTIMATE

Lau Tiam Aik
Blk474 Segar Road
#04-308 Singapore 670474

Contact: 9366 4778

Code : C101939

Date In: 13/11/2019

Vehicle Num. : SJN2539H

Model : TOYOTA RUSH 1.5X A

Chassis/ Eng # : J200E0023549 / 35Z2176632

Supplementary for Estimate Items

Description of part	Qty	Unit Price	Amount
Rear Fender Inner Shield	1	85.00	70.00 85.00 ✓
Subtotal			85.00
Percentage discount 25%			21.25
Sub-total			63.75
Rear Fender Inner Shield Clips (Set)(SN)		30.00	12 30.00 X
Sub-total 2			30.00
Parts total			93.75



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19020253/Uvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-11-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8456E	Veh. Inspected	SJN 2539H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19007209MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	14/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA RUSH (A)	c.c	1495	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	J200E0023549	Colour	GREY	
Odometer	247582	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/65 R16	MICHELIN	5 mm	
L/H Front Tyre	215/65 R16	MICHELIN	5 mm	
R/H Rear Tyre	215/65 R16	MICHELIN	5 mm	
L/H Rear Tyre	215/65 R16	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/11/2019	Inspection Date	14/11/2019	
Survey held at	Z-ONE AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVE 6, BLK C,#01-52 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 2539H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DISTORTED	441.70	441.70
2	REAR BUMPER NO PLATE LAMP L/R @\$69.00	NOT NECESSARY	138.00	-
2	REAR BUMPER SIDE REFLECTOR L/R @\$59.10	N/S CRACKED	118.20	59.10
2	REAR BUMPER SIDE RETAINER L/R @\$65.10	N/S BENT	130.20	65.10
1	REAR BUMPER TOWING COVER	NOT NECESSARY	60.10	-
1	REAR END PANEL (INNER)	TO REPAIR SEE LABOUR	494.70	-
1	REAR END PANEL (OUTER)	BADLY DENTED	367.80	367.80
1	REAR END PANEL INNER TOP GARNISH	TWISTED	124.10	124.10
3	REAR END PANEL INNER TOP GARNISH CLIPS @\$8.90	NOT NECESSARY	26.70	-
1	REAR EXHAUST CENTER PIPE	TO REPAIR SEE LABOUR	1,556.70	-
1	REAR EXHAUST SILENCER BOX	BENT / TWISTED	786.80	786.80
2	REAR EXHAUST SILENCER BOX RUBBER MOUNTING @\$55.10	NOT NECESSARY	110.20	-
1	REAR TAILGATE	BADLY DENTED	971.80	971.80
1	REAR TAILGATE "RUSH" EMBLEM	NECESSARY	110.00	66.50
1	REAR TAILGATE "TOYOTA" EMBLEM	NECESSARY	56.00	56.00
1	REAR TAILGATE CHECKER	NOT NECESSARY	191.00	-
2	REAR TAILGATE HINGE @\$61.00	NOT NECESSARY	122.00	-
1	REAR TAILGATE INNER TRIMBOARD	DEFORMED / CRACKED	490.10	490.10
1	REAR TAILGATE LOCK STRIKER	NOT NECESSARY	55.00	-
1	REAR TAILGATE MECHANISM LOCK	SHORTED	309.10	309.10
1	REAR TAILGATE OUTER HANDLE	NOT NECESSARY	210.10	-
2	REAR TAILGATE RUBBER GUIDE STOPPER @\$23.10	NECESSARY	46.20	46.20
1	REAR TAILGATE SPARE TYRE BRACKET	BENT	410.00	410.00
1	REAR TAILGATE SPARE TYRE COVER	CRACKED	1,687.00	1,687.00
1	REAR TAILGATE SPARE TYRE RETAINER LOCK	NOT NECESSARY	48.80	-
1	REAR TAILGATE WEATHER STRIP	TWISTED	335.50	335.50
2	REAR TAILLAMP L/R @\$480.00	N/S CRACKED	960.00	365.10
2	REAR TAILLAMP STAY CLIPS L/R @\$5.90	NOT NECESSARY	11.80	-

Report Ref No. CS/FCI19020253/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER INNER SHIELD (ADDITIONAL)	TORN	85.00	85.00
	LESS 25% DISCOUNT		-2,613.65	-1,666.73
			7,840.95	5,000.17
	SPECIAL NETT ITEMS			
1	REAR FENDER INNER SHIELD CLIPS (ADDITIONAL)(SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER NO PLATE GARNISH (SN) }	CRACKED	50.00	40.00
1	REAR BUMPER NO PLATE (SN) }	CRACKED	25.00	-
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	350.00	200.00
1	SET REAR TAILGATE INNER TRIMBOARD CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR TAILGATE SPARE TYRE (SN)	SERVICEABLE	280.00	-
1	REAR TAILGATE SPARE TYRE COVER LOCK (SN)	NOT NECESSARY	60.00	-
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
			935.00	340.00
	LABOUR			
	DIAGNOSE,REPLACE AND/OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		120.00	30.00
	TO REMOVE,REFIX/RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING.		120.00	50.00
	TO REMOVE,REINSTALL REAR TAILGATE WINDSCREEN.		150.00	120.00
	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET.		100.00	60.00
	TO TRANSFER TAILGATE/BOOTLID MECHANISM AND WIRING ASSY (TO FR).		150.00	60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT.		1,400.00	1,100.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.		150.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF REAR END PANEL (INNER) AND REAR EXHAUST CENTER PIPE.		1,600.00	1,000.00
	TO APPLY ANTI-RUST CHEMICAL (TUFF-KOTE) ON REPAIRED AND REPLACED PANEL.		120.00	60.00
			3,910.00	2,540.00
GRAND TOTAL			12,685.95	7,880.17
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,200.00

Report Ref No. CS/FCI19020253/Uvd3n2

MARKET VALUE: \$42,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$23,762.00=NETT VALUE: \$18,238.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.