

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Ms.
HE
WEIQIAN
1 BUKIT BATOK STREET 23
#02-15
Singapore 658882

Document no.
Document date 14-11-2019
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 39999
Job order number 2019002682/ 1
Job order date 14-11-2019
Service Advisor TIOU CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SLS4176H	5G13HZ	24-08-2017	WWWZZZAUZHW119316	Golf 1.4 CLBM 92 TSI D7F	17,338

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00 ✓	#1	480.00 ✓	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00 ✓	#1	280.00 ✓	299.60
5G6827025Q	Rear Trunk Lid ✓ <i>Blue</i>	1	pcs.	1,853.05 ✓	#1	1,853.05 ✓	1,982.76
D 169300M2	1k Window Adhesive ✓	2	pcs.	49.88 ✓	#1	99.76 ✓	106.74
D 002000A2	Adhesive Remover ✓	1	pcs.	115.74 ✓	#1	115.74 ✓	123.84
D 00920002	Primer ✓	1	pcs.	25.92 ✓	#1	25.92 ✓	27.73
D 00950025	Applicator ✓	2	pcs.	9.48 ✓	#1	18.96 ✓	20.29
D 181802M1	Activator For Precoated W ✓	1	pcs.	24.00 ✓	#1	24.00 ✓	25.68
5G6971829B	Grommet ✓	1	pcs.	14.29 ✓	#1	28.58 ✓	30.58
5G0827469F FOD	Oper.Mechan.With Micro Sw ✓	1	pcs.	1,760.35 ✓	#1	1,760.35 ✓	1,883.57
5G0853687 2ZZ	Inscription Bright Chrome GOLF ✓ <i>MC</i>	1	pcs.	66.63 ✓	#1	66.63 ✓	71.29
5G6827705E	Gasket WEATHERSTRIP ✓ <i>mc</i>	1	pcs.	238.16 ✓	#1	238.16 ✓	254.83
5G6827505B 9B9	Hood Latch Satin Black LOCK ✓ <i>NN</i>	1	pcs.	359.59 ✓	#1	359.59 ✓	384.76
5G0827517D	Striker Plate LATCH ✓ <i>NN</i>	1	pcs.	49.44 ✓	#1	49.44 ✓	52.90
5G0945087B	Additional Brake Light Wi ✓ <i>mc</i>	1	pcs.	155.54 ✓	#1	155.54 ✓	166.43
5G6807417APGRU	Cover For Bumper Primed REAR BUMPER ✓ <i>mc</i>	1	pcs.	1,080.14 ✓	#1	1,080.14 ✓	1,155.75
5G6807568D 9B9	Rear Diffusor Satin Black ✓ <i>mc</i>	1	pcs.	277.23 ✓	#1	277.23 ✓	296.64
5G0919491	Sensor Bracket ✓	1	pcs.	13.21 ✓	#1	13.21 ✓	14.13
5G0919491A	Sensor Bracket ✓ <i>mc</i>	1	pcs.	13.21 ✓	#1	13.21 ✓	14.13
5G0919492A	Sensor Bracket ✓	1	pcs.	13.21 ✓	#1	13.21 ✓	14.13
5G0919491	Sensor Bracket ✓	1	pcs.	13.21 ✓	#1	13.21 ✓	14.13
5Q0919275B GRU	Sensor Primed ✓ <i>NN</i>	1	pcs.	164.62 ✓	#1	164.62 ✓	176.14
5Q0919133 9B9	Seal Ring Satin Black ✓	1	pcs.	1.18 ✓	#1	1.18 ✓	1.26
D 180KU2A1	2k-Plastic Adhesive ✓	1	pcs.	74.29 ✓	#1	74.29 ✓	79.49
D 822150A1	Bonding Agent For Plastic ✓ <i>mc</i>	1	pcs.	56.90 ✓	#1	56.90 ✓	60.88
WHT005263	Rivet ✓	4	pcs.	1.09 ✓	#1	4.36 ✓	4.67
5G0807305D	Bumper REINFORCEMENT ✓ <i>NN</i>	1	pcs.	572.31 ✓	#1	572.31 ✓	612.37
5G6807863C	Attachment Strip RR CTR BRACKET ✓ <i>mc</i>	1	pcs.	59.89 ✓	#1	59.89 ✓	64.08
5G6807393A	Guide Piece LHR TAILLIGHT BRACKET ✓	1	pcs.	34.51 ✓	#1	34.51 ✓	36.93
5G6807394A	Guide Piece RHR TAILLIGHT BRACKET ✓	1	pcs.	34.51 ✓	#1	34.51 ✓	36.93
5G6807393	Guide Piece LHR SIDE BRACKET ✓	1	pcs.	34.51 ✓	#1	34.51 ✓	36.93
5G6807394	Guide Piece RHR SIDE BRACKET ✓ <i>NN</i>	1	pcs.	34.51 ✓	#1	34.51 ✓	36.93
5G0945105	Reflector LHR ✓	1	pcs.	68.93 ✓	#1	68.93 ✓	73.76
5G0945106	Reflector RHR ✓	1	pcs.	68.93 ✓	#1	68.93 ✓	73.76

Quotation

Non binding - Preview

Page

2/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Ms.
HE
WEIQIAN
1 BUKIT BATOK STREET 23
#02-15
Singapore 658882

Document no.
Document date 14-11-2019
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 39999
Job order number 2019002682/ 1
Job order date 14-11-2019
Service Advisor TIOU CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SLS4176H	5G13HZ	24-08-2017	WVWZZZAUZH119316	Golf 1.4 CLBM 92 TSI D7F	17,338

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
1K8943021	License Plate Light	2	pcs.	37.19	#1	74.38	79.59
5G0945093AD	Taillight	1	pcs.	252.43	#1	252.43	270.10
	LHR INNER						
5G0945094AD	Taillight With Rear Fog L	1	pcs.	252.43	#1	252.43	270.10
	RHR INNER						
5G6813309	End Plate	1	pcs.	112.33	#1	112.33	120.19
D 007600A1	Inox-Spray	1	pcs.	62.88	#1	62.88	67.28
D 180003M2	2k-Body Adhesive	1	pcs.	398.47	#1	398.47	426.36
D 476KD1M2	Sealant Can Be Sprayed	1	pcs.	62.20	#1	62.20	66.55
	LABOUR	7	pcs.	840.00	#1	5,880.00	6,291.60
	TRANSFER BOOTLID MECHANISM	1	pcs.	840.00	#1	840.00	898.80
	R&R REAR WINDSCREEN	1	pcs.	840.00	#1	840.00	898.80
	R&R LUGGAGE COMPARTMENT	1	pcs.	840.00	#1	840.00	898.80
	CHECK WATER LEAK	1	pcs.	150.00	#1	150.00	160.50
	Spray Painting	3	6	800.00	#1	4,800.00	5,136.00
	NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60
	AIG DIRECT SETTLEMENT						
	DOA : 12/11/2019						
	TP VEH : SMC2473K						
	SURVEY BY :						

Quotation valid till 21-11-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	22,060.50	7%	1,597.44	22,820.50	24,417.94
Total	760.00	22,060.50		1,597.44	22,820.50	24,417.94

8 Days.
before paint photos.
Gua Ri ang - 82880282
20/11/19.

Customer

Service Advisor

---VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for information services, products and promotions).---

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: