

ASS. REC. BY:

REF: es/SM019020281/ktd3 | Special Instruction:

Survey: Kenneth

ASSIGNMENT (Office)

From (Person): Yong Kong Melvin of SMO Date/Time: 15/11/19 @ 9.37am

Estimated Cost: Bill to:

① WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBC 4051L Insured:

at Workshop m/s Ah Lim Motor Tel: 64831244.

of 10 Amk Ind. Park 2A #01-09

Policy No: Claim No: CMTD1905293/AGC

Sum Insured: Excess: \$500.00

Make of Veh: D.O.A. 9/11/19
(Client's Record)

CA (REV) REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 9.42am @ 15/11/19 Person Contacted: Zila Vehicle IN/OUT

Date/Time	Action/Instruction
	GBC 4051L - X
15/11 @ 3:16pm	Sent. preli advise revised
18/11 @ 10:34am	authorize repair by Agnes Chua excess \$500/-
18/11 @ 10:48am	email to ah lim motor Zila authorize repair not exceeding lump sum \$16,000/-

ASS. REQ. BY:

REF:

SMO CS/SM019020281/1ctd3

ASSIGNMENT

From: _____ Date: 15/11/19

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBC 4051L

at Workshop n/s Ah Lim Motor

of 10 AMK Ind. Park 2A # 01-09

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$500.00

(Client's Record)

Make of Veh: Vehicle In

Veh No: GBC 4051L Yr Regn: 04 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Hiace c.c. 2982

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 255422 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFH702P300084686

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15

R: _____

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$30k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 24 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front		Rear
R/Bal. <u>9</u> mm		R/Bal. <u>3</u> mm
L/Bal. <u>9</u> mm		L/Bal. <u>3</u> mm
D.O.A. <u>9/11/19</u>		D.O.I. <u>15/11/19</u>

*Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>19/13</u>	<u>11 Day @ 15,450k confirmed</u>
	<u>refinanced at \$14900 (lump sum (Red: 12120.70; 44%))</u>

RECEIVED 26 MAR 2020

Date/Time, File Pass to? : Prel. Report

11/26/3 Typist : Final Report

Date/Time, File Return to? _____

Report Format: OD

Lump Sum / N.B.: (\$) 14900/-

Days Of Repair: 24.

Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$) _____

: Interview (\$) _____

: Tech. Invs (\$) _____

: Wash end (\$) _____

Survey Fee:	
Transportation:	
S + RS, SI	
Photos	
Other:	
TOTAL	

Nivitha (LKK Auto)

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Sent: Friday, 15 November 2019 9:37 AM
To: Zila @ Ah Lim Motor Company; assignments; SUR
Cc: Chan, Shu Hui Agnes; Henry, Irene James
Subject: RE: GBC4051L - OD CLAIM Our ref : CMTD1905293/AGC

Dear Zila,

We have appointed LKK Auto to conduct the survey.

Please note that the handler for this claim is Ms Agnes Chan.

Excess : \$500

Dear LKK Auto,

Please make arrangement to conduct the survey for GBC4051L.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

or

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Zila @ Ah Lim Motor Company <zila@ahlimmotor.com.sg>
Sent: Thursday, 14 November, 2019 4:56 PM
To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>
Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Subject: GBC4051L - OD CLAIM

Hi Claims Dept,

Kindly arrange for the vehicle to be survey.
Note: Vehicle is in @ ALM AMK Autopoint workshop.

Thanks.

Regards,
Zila
Ah Lim Motor (AMK)
10 Ang Mo Kio Ind Pk 2A
#01-09 AMK AUTOPOINT
5568047
Tel: 64831244 Fax: 64836170

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 15 November 2019 3:16 PM
To: Admin-D (LKKAuto); 'Ye, Yong Kang Melvin'; assignments
Cc: 'Chan, Shu Hui Agnes'; 'Henry, Irene James'; SUR
Subject: RE: GBC4051L - OD CLAIM Our ref : CMTD1905293/AGC
Attachments: PRELI ADVISED OF GBC 4051L.pdf; ESTIMATE.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **GBC 4051L**
Number of days (estimated) : 24 days

Repairer willing to undertake repair cost at lump sum \$16,000/-(all-in)

Please let us have your approval.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 15 November 2019 9:56 AM
To: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: GBC4051L - OD CLAIM Our ref : CMTD1905293/AGC

Dear Melvin,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ye, Yong Kang Melvin [<mailto:melvin.ye@sompo.com.sg>]
Sent: Friday, 15 November 2019 9:37 AM

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 24 March 2020 3:00 PM
To: Mui Hong @ Ah Lim Motor
Cc: Kenneth Kong (LKKAuto)
Subject: RE: GBC 4051L / OD / SOMPO / DOA: 9/11/2019

Dear Mui Hing,

We confirm lump sum \$14900/-.

Yes, Please do the necessary amend to sompo the final invoice.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mui Hong @ Ah Lim Motor <muihong@ahlimmotor.com.sg>
Sent: Tuesday, 24 March 2020 2:50 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Cc: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>
Subject: RE: GBC 4051L / OD / SOMPO / DOA: 9/11/2019

Dear Denise,

My apologies... I had overlook to remove the 2 items. I had checked with my staff and noted that it was actually cancelled but I overlook to remove them.

Pls see attached the amended draft and the Amended Final Invoice.

If all is in order, do you need me to email the amended invoice to Sompo as I had earlier email to Sompo the Final Invoice.

Thanks

Best Regards,

Kee Mui Hong
Ah Lim Motor @ AMK
10, Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint S568047
Tel : 6483 1244 Fax : 6483 6170

From: Denise Tay (LKKAuto) [<mailto:denisetay@lkkauto.com>]
Sent: Tuesday, 24 March 2020 9:18 AM
To: Mui Hong @ Ah Lim Motor <muihong@ahlimmotor.com.sg>; Kee Mui Hong - Ah Lim Motor @ Sin Ming <muihong@almsm.com.sg>

Denise Tay (LKKAuto)

From: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>
Sent: Monday, 18 November 2019 10:34 AM
To: Denise Tay (LKKAuto); Admin-D (LKKAuto); assignments
Cc: SUR; Ye, Yong Kang Melvin
Subject: RE: GBC4051L - OD CLAIM Our ref : CMTD1905293/AGC

Dear Denise

We refer to our phone conversation just now.

Please authorise the repair of GBC4051L and the excess of 500/- is applicable.

Thank you.

Best Regards

Agnes Chan

Claims Divison

D: 6329 5327 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

or

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Sent: Friday, 15 November, 2019 3:16 PM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; assignments <assignments@lkkauto.com>

Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: GBC4051L - OD CLAIM Our ref : CMTD1905293/AGC

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 18 November 2019 10:48 AM
To: zila@ahlimmotor.com.sg
Cc: muihong@ahlimmotor.com.sg; SUR
Subject: GBC 4051L / SMOPO / DOA: 9/11/2019

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **GBC 4051L (Excess \$500/-). NOT EXCEEDING LUMP SUM \$16,000/-**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref : CMTD1905293/AGC

Date: 15/11/2018

Our Ref: GS/SMO19020281/Ktd3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE PL

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. GBC 4051L .


We thank you for the instruction on 15/11/2019 .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/11/2019 at the premises of M/s Ah Lim Motor and have the following to report: -

Workshop Estimate Amount	: <u>S\$ 25,581.20</u>
Revised Estimate Amount	: <u>S\$ 15,771.30</u>
"Check" Items Amount	: <u>S\$ 5,351.20</u>
Total	: <u>S\$ 21,122.50</u>
Market Value	: <u>S\$ 30,000.00</u>
LTA Reimbursement Value	: <u>S\$ 10,553.00</u>
Nett Value	: <u>S\$ 19,447.00</u>

Description of Damage:

The vehicle sustained at the o/s body
And undercarriage portion.



Comments/ Present Status:

Damage consistent
Repair cost economical

We have not authorized repairs.

Yours Faithfully,
Kenneth
Automotive Assessor



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref : CMTD1905293/AGC

Date: 15/11/2018

Our Ref: CS/SMO19020281/Ktd3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE PL

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. GBC 4051L .


We thank you for the instruction on 15/11/219 .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/11/2019 at the premises of M/s Ah Lim Motor and have the following to report: -

Workshop Estimate Amount	: S\$ <u>25,581.20</u>
Revised Estimate Amount	: S\$ <u>15,771.30</u>
"Check" Items Amount	: S\$ <u>5,351.20</u>
Total	: S\$ <u>21,122.50</u>
Market Value	: S\$ <u>30,000.00</u>
LTA Reimbursement Value	: S\$ <u>10,553.00</u>
Nett Value	: S\$ <u>19,447.00</u>

Description of Damage:

The vehicle sustained at the o/s body
And undercarriage portion.



Comments/ Present Status:

Damage consistent

Pending repair cost from repairer

We have not authorized repairs.

Yours Faithfully,
Kenneth
Automotive Assessor

Celine 15/11/19.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	689D
Vehicle Details	
Vehicle No.:	GBC4051L
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	1KD2140097
Chassis No.:	JTFHT02P300084696
Maximum Power Output:	-
Open Market Value:	\$25,820.00
Original Registration Date:	09 Apr 2012
First Registration Date:	09 Apr 2012
Transfer Count:	1
Actual ARF Paid:	\$1,291.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	08 Apr 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$44,001.00
COE Rebate Amount:	\$10,553.00
Total Rebate Amount:	\$10,553.00

The information contained herein is correct as at 15 Nov 2019

OK

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 689D

Vehicle Details

Vehicle No.: GBC4051L
Vehicle to be Exported: No
Intended Deregistration Date: 11 Nov 2019
Vehicle Make: TOYOTA
Vehicle Model: HIACE MANUAL
Primary Colour: Silver
Manufacturing Year: 2011
Engine No.: 1KD2140097
Chassis No.: JTFHT02P300084696
Maximum Power Output: -
Open Market Value: \$25,820.00
Original Registration Date: 09 Apr 2012
First Registration Date: 09 Apr 2012
Transfer Count: 1
Actual ARF Paid: \$1,291.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 08 Apr 2022
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
QP Paid: \$44,001.00
COE Rebate Amount: \$10,601.00
Total Rebate Amount: \$10,601.00

The information contained herein is correct as at 11 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/11/2019 16:58
Date Of Accident	09/11/2019 23:00
Exact Location Of Accident	ALONG KAKI BUKIT AVE 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC4051L
Insured/Policyholder	
Name Of Registered Owner	ENTRE' AUTOMATICS PTE LTD
Co Reg No	200500689D
Email Address	ACCOUNT@ENTREAUTOMATIC.COM
Mobile Phone No	(LOCAL) +65-84216537
Alternative Phone No	OFFICE-62501508

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D19MTPCVE000846
Cover Note Number	09/04/2019 - 08/04/2020

Driver

Name of Driver	MD RABIUL ALAM MD ABUL BASHAR
Passport No/FIN	G8470680P
Date Of Birth	01/12/1986
Occupation	OUTDOOR
Date Of Driving Pass	28/02/2017
Driving Experience	2 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81369017
Fax Number	
Contact Number	OFFICE-62501508
EMail Address	NOEMAIL

Sketch Plan Pg. 1

11-11-19; 16:44

07 69 01 1 v

1/ 2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

X  

Policyholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre/Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 3



**SINGAPORE
POLICE FORCE**



T/20191111/2084

1 of 3

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

Report No. T/20191111/2084

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/11/2019 15:29	Vide Report No.:	Station Diary No.: 51
--	------------------	--------------------------

Informant's Particulars

Name of Informant: ALAM MD RABIUL		Address:	
ID Type / ID No.: FIN NO / G8470680P		Contact No.: Home/Office: Mobile: 81369017 / 84216537	
Nationality: BANGLADESHI		Email:	
Sex: Male	Age: 32	Date of Birth: 01/12/1986	Type of Informant: Driver
Race: Indian		Language: English	Institution / School Name:
Occupation: CONTRACTOR		Driving Licence Information: Class: 3 Date of Expiry: 27/02/2022	

General Information of the Accident

Type of Accident:	Non-Injury Government Property	Drink Drive: No	Date/Time of Accident: 09/11/2019 23:00	Type of Location: Bend
Location: Along Road 1 KAKI BUKIT AVENUE 4 after turning in from Bartley Road East				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Road Divider/Kerb/Railings				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC4051L	Van	TOYOTA	HIACE MANUAL	Blue	Slightly Damaged	3

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20191111/2084

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999


3 of 3
Report No. T/20191111/2084

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: D / Sgt 3 LEE HONG HAI 	Signature Of Informant: 	
Signature Of Interpreter: Not applicable	Date/Time: 11/11/2019 15:29	
Officer In Charge Of Case: TP / AEIT / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:	
<table border="1"> <tr> <td data-bbox="272 1890 810 2060"> Authentication Stamp: NP168  POLICE FORCE  SN 49 SIGNATURE </td> </tr> </table>		Authentication Stamp: NP168  POLICE FORCE  SN 49 SIGNATURE
Authentication Stamp: NP168  POLICE FORCE  SN 49 SIGNATURE		

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #05-01/06 SINGAPORE LAND TOWER
 SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department

Estimate No: MC1900823
Date: 13 Nov 2019
Policy No: D19MTPCVE000846
Veh Reg No: GBC4051L
Make/Model: TOYOTA HIACE
 MANUAL

Your Ref No: GBC4051L
Claim Type: Own Damage
Accident Date: 09/11/2019

old body & ulc
LKK
Not work
24 days
Ex \$500k
Measuring After Paint
Fig: 62564315

Estimate Repair Cost to Vehicle No : GBC4051L

Description	U/Price	Quantity	Cost	Amount
			SS	SS
SPARE PARTS				
1 FRONT BONNET EMBLEM		1 PC	25.00	✓
2 FRONT BONNET INNER LOCK		1 PC	35.00	✓
3 FRONT GRILLE		1 PC	165.00	X
4 FRONT GRILLE CLIPS		6 PC	9.00	X
5 HEADLAMP LH & RH		2 PC	400.00	✓
6 CORNER PANEL RH		1 PC	60.00	✓
7 FRONT BUMPER		1 PC	165.00	✓
8 FRONT BUMPER SIDE RETAINER LH & RH		2 PC	96.00	✓
9 FRONT BUMPER CLIPS		10 PC	15.00	✓
10 FRONT BUMPER LOWER AIR GRILLE		1 PC	70.00	✓
11 FRONT BUMPER TOW COVER		1 PC	13.00	✓
12 FRONT BUMPER REINFORCEMENT TOP		1 PC	65.00	✓
13 FRONT BUMPER REINFORCEMENT LOWER		1 PC	100.00	✓
14 FOGLAMP COVER RH		1 PC	35.00	✓
15 RADIATOR SUPPORT PANEL TOP		1 PC	135.00	✓
16 BRACE PANEL		1 PC	28.00	✓
17 FIREWALL CROSSMEMBER		1 PC	160.00	X
18 FIREWALL PANEL		1 PC	700.00	X
19 AIR CON CONDENSER		1 PC	480.00	✓
20 AIR CON CONDENSER PIPE (COND-COMP) - CHECK PRICE		1 PC	0.0000	720 ✓
21 AIR CON CONDENSER PIPE (COND-VALVE) - CHECK PRICE		1 PC	0.0000	710 ✓
22 RADIATOR ASSY		1 PC	580.00	✓
23 RADIATOR FAN MOTOR ASSY		1 PC	365.00	✓
24 RADIATOR BOTTOM BRACKET		1 PC	38.00	✓
25 RADIATOR TOP HOSE		1 PC	40.00	X
26 RADIATOR BOTTOM HOSE		1 PC	22.00	X
27 AIR FILTER BOX ASSY		1 PC	265.00	✓
28 FRONT WINDSCREEN MOULDING		1 PC	45.00	✓
29 FRONT DOOR PILLAR RH		1 PC	205.00	✓
30 STEP PANEL RH		1 PC	45.00	✓
31 STEP PANEL GARNISH RH		1 PC	55.00	✓
32 SIDE MIRROR W GLASS RH		1 PC	75.00	✓
33 FRONT DOOR RH		1 PC	580.00	✓
34 FRONT DOOR HINGE TOP		1 PC	30.00	✓
35 FRONT DOOR HINGE LOWER		1 PC	30.00	✓
36 FRONT DOOR CHECKER		1 PC	60.00	✓
37 FRONT DOOR INNER MIRROR TRIM RH		1 PC	35.00	X
38 FRONT DOOR RUBBER (AT DOOR)		1 PC	75.00	✓
39 FRONT DOOR RUBBER LOWER		1 PC	25.00	✓



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #05-01/06 SINGAPORE LAND TOWER
 SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department

Estimate No: MC1900823
Date: 13 Nov 2019
Policy No: D19MTPCVE000846
Veh Reg No: GBC4051L
Make/Model: TOYOTA HIACE
 MANUAL

Your Ref No: GBC4051L
Claim Type: Own Damage
Accident Date: 09/11/2019

Estimate Repair Cost to Vehicle No : GBC4051L

Description	U/Price	Quantity	Cost	Amount
40 FRONT DOOR RUBBER (AT BODY)		1 PC	90.00	SS
41 FRONT DOOR INNER TRIMBOARD		1 PC	545.00	SS
42 FRONT DOOR POWER WINDOW MOTOR		1 PC	220.00	
43 FRONT DOOR POWER WINDOW REGULATOR		1 PC	70.00	
44 FRONT DOOR INNER LOCK		1 PC	175.00	
45 FRONT DOOR STRIKER		1 PC	15.00	
46 FRONT FLOOR PANEL		1 PC	630.00	X
47 FRONT FLOOR CARPET		1 PC	450.00	X
48 FRONT DOOR PILLAR REAR PORTION RH (B PILLAR)		1 PC	185.00	
49 FRONT WHEELHOUSE TOP TRIM RH		1 PC	145.00	
50 SLIDING DOOR RH		1 PC	600.00	X
51 SLIDING DOOR LOWER ROLLER ARM RH		1 PC	100.00	X
52 SLIDING DOOR UPPER ROLLER ARM RH		1 PC	45.00	X
53 REAR FENDER RH		1 PC	530.00	
54 REAR FENDER AIR VENT RH		1 PC	25.00	
55 TAILAMP RH		1 PC	95.00	
56 TAILAMP LOWER GARNISH RH		1 PC	40.00	
57 REAR BUMPER	Buc/cm	1 PC	130.00	
58 REAR BUMPER SIDE RETAINER RH		1 PC	15.00	
59 REAR BUMPER CLIPS		10 PC	15.00	
60 ROCKER PANEL RH		1 PC	350.00	
61 SPARE TYRE HOLDER		1 PC	155.00	X
62 C PILLAR RH		1 PC	220.00	X
63 REAR FLOOR PANEL STEP PANEL RH		1 PC	420.00	X
64 DASHBOARD		1 PC	420.00	X
65 DASHBOARD LOWER COVER RH		1 PC	130.00	X
66 ACCELERATION PEDAL RH		1 PC	50.00	
67 BRAKE PEDAL RH		1 PC	60.00	
68 FRONT WHEEL BEARING W HUB RH		1 PC	85.00	
69 FRONT BRAKE DISC RH		1 PC	125.00	X
70 FRONT BRAKE CALLIPER RH		1 PC	600.00	X
71 FRONT KNUCKLE ARM RH		1 PC	165.00	
72 FRONT LOWER ARM RH		1 PC	115.00	
73 FRONT LOWER ARM BALL JOINT RH		1 PC	75.00	
74 FRONT UPPER ARM RH		1 PC	245.00	
75 FRONT SHOCK ABSORBER		1 PC	55.00	
76 FRONT STABILISER BAR		1 PC	150.00	
77 FRONT STABILISER LINKAGE LH & RH	c/s o/s	2 PC	110.00	X
78 FRONT STEERING RACK		1 PC	1,100.00	
79 FRONT CROSSMEMBER		1 PC	1,050.00	



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlime@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #05-01/06 SINGAPORE LAND TOWER
 SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department

Estimate No: MC1900823
Date: 13 Nov 2019
Policy No: D19MTPCVE000846
Veh Reg No: GBC4051L
Make/Model: TOYOTA HIACE
 MANUAL

Your Ref No: GBC4051L
Claim Type: Own Damage
Accident Date: 09/11/2019

Estimate Repair Cost to Vehicle No : GBC4051L

Description	U/Price	Quantity	Cost	Amount
			SS	SS
80 REAR WHEEL BEARING		1 PC	50.00	✓
81 REAR WHEEL HUB RH		1 PC	66.00	✓
82 REAR SHOCK ABSORBER		1 PC	50.00	✓
83 REAR DRIVE SHAFT RH		1 PC	650.00	✗
			15,942.00	
		Add 10%	1,594.20	17,536.20

Special Nett

84 FRONT DOOR COMPANY STICKER		1 PC	30.00	✓
85 NUMBER PLATE		1 PC	35.00	250
86 SPORT RIM RHF RHR		2 PC	500.00	1200 240
87 TYRE RHF RHR	900	2 PC	400.00	132
88 FRONT WINDSCREEN SEALANT		1 PC	40.00	✓
89 60 KM/H		1 PC	10.00	✓
90 9 PAX		1 PC	10.00	✓
			1,025.00	



LABOUR

91 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00	✓
92 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	100.00	✓
93 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		1 PC	80.00	✓
94 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.		1 PC	120.00	✓
95 TO REMOVE AND REINSTALL/REPLACE DASHBOARD.		1 PC	350.00	250
96 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.		1 PC	120.00	60
97 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		1 PC	350.00	150
98 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE - FRONT		1 PC	300.00	240
99 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE - REAR		1 PC	300.00	150
100 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.		1 PC	60.00	50.

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department

Estimate No: MC1900823
Date: 13 Nov 2019
Policy No: D19MTPCVE000846
Veh Reg No: GBC4051L
Make/Model: TOYOTA HIACE
MANUAL

Your Ref No: GBC4051L
Claim Type: Own Damage
Accident Date: 09/11/2019

Estimate Repair Cost to Vehicle No : GBC4051L

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
101 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD RADIATOR SUPPORT PANEL,FRT DOOR PILLAR RH,B PILLAR RH,C PILLAR RH,RR FENDER RH, ROCKER PANEL RH,STEP PANEL RH.TO KNOCK & REPAIR ROOF PANEL,TAILGATE & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	3,000.00	2200
102 TO SPRAY FRONT BONNET,FRONT GRILLE,CORNER PANEL,FRONT DOOR RH,FRONT DOOR PILLAR RH, SLIDING DOOR RH,ROCKER PANEL RH,RR FENDER RH,TAILGATE,REAR BUMPER.		1 PC	2,200.00	1980
				7,020.00
			Lump Sum Repair	SS 25,581.20
			Add GST @ 7%	1,790.68
			Total Amount payable	SS 27,371.88

TOTAL: SINGAPORE DOLLAR TWENTY SEVEN THOUSAND THREE HUNDRED SEVENTY ONE AND CENTS EIGHTY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

27020.70

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #05-01/06 SINGAPORE LAND TOWER
 SINGAPORE 048623
 TEL: 64616555
 ATTN: Motor Claim Department

Estimate No: MC1900823
 Date: 08 Feb 2020
 Policy No: D19MTPCVE000846
 Veh Reg No: GBC4051L
 Make/Model: TOYOTA HIACE
 MANUAL

Your Ref No: GBC4051L
 Claim Type: Own Damage
 Accident Date: 09/11/2019

Estimate Repair Cost to Vehicle No : GBC4051L

Description	U/Price	Quantity	Cost SS	Amount SS
Supplementary Parts to Repair				
SPARE PARTS				
1 ENGINE MOUNTING RH		1 PC	CM 60.00	✓
2 ENGINE MOUNTING LH		1 PC	CM 60.00	✓
3 AIR CLEANER TOP AIR DUCT		1 PC	nd 50.00	✓
4 RADIATOR FAN SHROUD		1 PC	CM 90.00	✓
5 RADIATOR FAN BLADE RH		1 PC	Di 50.00	✓
6 RADIATOR FAN BLADE LH		1 PC	Di 55.00	✓
7 RADIATOR FAN MOTOR RH LH		2 PC	Tn 680.00	✓
8 FUSE WIRE HOLDER CONNECTOR RH		1 PC	CM 50.00	✓
			1,095.00	
	Add 10%		109.50	1,204.50
Special Nett				
9 RADIATOR COOLANT	<i>Requested</i>	1 PC	<i>Net</i> 35.00	✓
				35.00
LABOUR				
10 TO CHANGE ENGINE MOUNTING, RADIATOR, FAN MOTOR AND FUSE WIRE CONNECTOR		1 PC	200.00	✓
				200.00
			Lump Sum Repair	SS 1,439.50
			GST Amount	SS 100.77
			Total Amount payable	SS 1,540.27

The above vehicle was surveyed by KENNETH KONG -LKK on 15/11/2019

For AH LIM MOTOR COMPANY


 AH LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 FAX: 6483 6170
 AUTHORIZED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK, Aetopoint Singapore 56847
 TEL: 6463 1344 (4 lines) FAX: 6483 6170 Email: ahlimmco@singapore.com.sg
 GST:M9-2009639-E RCB NO:064'031GB

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #05-01/06 SINGAPORE LAND TOWER
 SINGAPORE 048623

Estimate No: MC1900823
 Date: 13 Nov 2019
 Policy No: D19MTPCVE000846
 Veh Reg No: GBC4051L
 Make/Model: TOYOTA HIACE
 MANUAL

TEL: 64616555
 ATTN: Motor Claim Department

Your Ref No: GBC4051L
 Claim Type: Own Damage
 Accident Date: 09/11/2019

Handwritten notes:
 Old body & etc
 LK
 Not Authorized
 C/Pay @ 7
 Measuring After Paint 24 days
 Ex @ 300k

Estimate Repair Cost to Vehicle No : GBC4051L Fax: 62564315

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 FRONT BONNET EMBLEM		1PC	25.00	✓
2 FRONT BONNET INNER LCK		1PC	35.00	✓
3 FRONT GRILLE		1PC	165.00	X
4 FRONT GRILLE CLIPS		5PC	9.00	X
5 HEADLAMP LH & RH	NIS?	2PC	400.00	✓ 2007
6 CORNER PANEL RH		1PC	60.00	✓
7 FRONT BUMPER		1PC	165.00	✓
8 FRONT BUMPER SIDE RETAINER LH & RH	old	2PC	96.00	✓ 48
9 FRONT BUMPER CLIPS		10PC	15.00	✓
10 FRONT BUMPER LOWER AIR GRILLE		1PC	70.00	✓
11 FRONT BUMPER TOW COVER		1PC	13.00	✓
12 FRONT BUMPER REINFORCEMENT TOP		1PC	65.00	✓
13 FRONT BUMPER REINFORCEMENT LOWER		1PC	100.00	✓
14 FOGLAMP COVER RH		1PC	35.00	✓
15 RADIATOR SUPPORT PANEL TOP		1PC	135.00	✓
16 BRACE PANEL		1PC	28.00	✓
17 FIREWALL CROSSMEMBER		1PC	160.00	X
18 FIREWALL PANEL		1PC	700.00	X
19 AIR CON CONDENSER		1PC	480.00	✓
20 AIR CON CONDENSER PIPE (COND-COMP) - CHECK PRICE		1PC	0.0000	?
21 AIR CON CONDENSER PIPE (COND-VALVE) - CHECK PRICE		1PC	0.0000	?
22 RADIATOR ASSY		1PC	580.00	✓
23 RADIATOR FAN MOTOR ASSY		1PC	365.00	✓
24 RADIATOR BOTTOM BRACKET		1PC	38.00	✓
25 RADIATOR TOP HOSE		1PC	40.00	?
26 RADIATOR BOTTOM HOSE		1PC	22.00	?
27 AIR FILTER BOX ASSY		1PC	265.00	✓
28 FRONT WINDSCREEN MOULDING		1PC	45.00	✓
29 FRONT DOOR PILLAR RH		1PC	205.00	✓
30 STEP PANEL RH		1PC	45.00	✓
31 STEP PANEL GARNISH RH		1PC	55.00	✓
32 SIDE MIRROR W GLASS RH		1PC	75.00	✓
33 FRONT DOOR RH		1PC	580.00	✓
34 FRONT DOOR HINGE TOP		1PC	30.00	✓
35 FRONT DOOR HINGE LOWER		1PC	30.00	✓
36 FRONT DOOR CHECKER		1PC	60.00	✓
37 FRONT DOOR INNER MIRROR TRIM RH		1PC	35.00	?
38 FRONT DOOR RUBBER (AT DOOR)		1PC	75.00	✓
39 FRONT DOOR RUBBER LOWER		1PC	25.00	✓



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autojoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimco@singnet.com.sg
 GST: M9-1009639-E RCB NO: 064103003

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #05-01/06 SINGAPORE LAND TOWER
 SINGAPORE 048623
 TEL: 64616555
 ATTN: Motor Claim Department

Estimate No: MC1900823
 Date: 13 Nov 2019
 Policy No: D19MTPCVE000846
 Veh Reg No: GBC4051L
 Make/Model: TOYOTA HIACE
 MANUAL

Your Ref No: GBC4051L
 Claim Type: Own Damage
 Accident Date: 09/11/2019

Estimate Repair Cost to Vehicle No : GBC4051L

Description	U/Price	Quantity	Cost		Amount
			SS	SS	
40 FRONT DOOR RUBBER (AT BODY)		1PC	90.00	7	
41 FRONT DOOR INNER TRIMBOARD		1PC	545.00	7	
42 FRONT DOOR POWER WINDOW MOTOR		1PC	220.00	7	
43 FRONT DOOR POWER WINDOW REGULATOR		1PC	70.00	7	
44 FRONT DOOR INNER LOCK		1PC	175.00	7	
45 FRONT DOOR STRIKER		1PC	15.00	7	
46 FRONT FLOOR PANEL		1PC	630.00	7	
47 FRONT FLOOR CARPET		1PC	450.00	7	
48 FRONT DOOR PILLAR REAR PORTION RH (B PILLAR)		1PC	185.00	7	
49 FRONT WHEELHOUSE TOP TRIM RH		1PC	145.00	7	
50 SLIDING DOOR RH		1PC	600.00	X	
51 SLIDING DOOR LOWER ROLLER ARM RH		1PC	100.00	7	
52 SLIDING DOOR UPPER ROLLER ARM RH		1PC	45.00	7	
53 REAR FENDER RH		1PC	530.00	7	
54 REAR FENDER AIR VENT RH		1PC	25.00	7	
55 TAILAMP RH		1PC	95.00	7	
56 TAILAMP LOWER GARNISH RH		1PC	40.00	7	
57 REAR BUMPER		1PC	130.00	7	
58 REAR BUMPER SIDE RETAINER RH		1PC	15.00	7	
59 REAR BUMPER CLIPS		10PC	15.00	7	
60 ROCKER PANEL RH		1PC	350.00	7	
61 SPARE TYRE HOLDER		1PC	155.00	7	
62 C PILLAR RH		1PC	220.00	X	
63 REAR FLOOR PANEL STEP PANEL RH		1PC	420.00	X	
64 DASHBOARD		1PC	420.00	7	
65 DASHBOARD LOWER COVER RH		1PC	130.00	7	
66 ACCELERATION PEDAL RH		1PC	50.00	7	
67 BRAKE PEDAL RH		1PC	60.00	7	
68 FRONT WHEEL BEARING W HUB RH		1PC	85.00	7	
69 FRONT BRAKE DISC RH		1PC	125.00	7	
70 FRONT BRAKE CALLIPER RH		1PC	600.00	7	
71 FRONT KNUCKLE ARM RH		1PC	165.00	7	
72 FRONT LOWER ARM RH		1PC	115.00	7	
73 FRONT LOWER ARM BALL JOINT RH		1PC	75.00	7	
74 FRONT UPPER ARM RH		1PC	245.00	7	
75 FRONT SHOCK ABSORBER		1PC	55.00	7	
76 FRONT STABILISER BAR		1PC	150.00	7	
77 FRONT STABILISER LINKAGE LH & RH		2PC	110.00	7	55
78 FRONT STEERING RACK		1PC	1,100.00	7	
79 FRONT CROSSMEMBER		1PC	1,050.00	7	



also

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK, Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg
 GST:M9-0009639-E RCB NO:064703008

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #05-01/06 SINGAPORE LAND TOWER
 SINGAPORE 048623
 TEL: 64616555
 ATTN: Motor Claim Department

Estimate No: MC1900823
 Date: 13 Nov 2019
 Policy No: D19MTPCVE000846
 Veh Reg No: GBC4051L
 Make/Model: TOYOTA HIACE
 MANUAL

Your Ref No: GBC4051L
 Claim Type: Own Damage
 Accident Date: 09/11/2019

Estimate Repair Cost to Vehicle No : GBC4051L

Description	U/Price	Quantity	Cost	Amount
			SS	SS
80 REAR WHEEL BEARING		1PC	50.00	✓
81 REAR WHEEL HUB RH		1PC	66.00	✓
82 REAR SHOCK ABSORBER		1PC	50.00	?
83 REAR DRIVE SHAFT RH		1PC	650.00	?
			15,942.00	
	Add 10%		1,594.20	17,536.20

Special Nett				
84 FRONT DOOR COMPANY STICKER		1PC	30.00	✓
85 NUMBER PLATE		1PC	35.00	2500
86 SPORT RIM RHF RHR		2PC	500.00	12000
87 TYRE RHF RHR	Fr 90% 180	2PC	400.00	
88 FRONT WINDSCREEN SEALANT		1PC	40.00	✓
89 60 KM/H		1PC	10.00	✓
90 9 PAX		1PC	10.00	✓
				1,025.00

LABOUR				
91 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1PC	40.00	✓
92 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1PC	100.00	✓
93 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		1PC	80.00	✓
94 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.		1PC	120.00	✓
95 TO REMOVE AND REINSTALL/REPLACE DASHBOARD.		1PC	350.00	2500
96 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.		1PC	120.00	600
97 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		1PC	350.00	1500
98 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE - FRONT		1PC	300.00	2400
99 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE - REAR		1PC	300.00	?
100 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.		1PC	60.00	500



1912 2417

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK, Autopoint Singapore 568047
 TEL: 6483 1344 (4 lines) FAX: 6483 6170 Email: ahl@ahlim.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #05-01/06 SINGAPORE LAND TOWER
 SINGAPORE 048623
 TEL: 6461 6555
 ATTN: Motor Claim Department

Estimate No: MC1900823
 Date: 13 Nov 2019
 Policy No: DISMTPCVIE000846
 Veh Reg No: GBC4051L
 Make/Model: TOYOTA HIACE
 MANUAL

Your Ref No: GBC4051L
 Claim Type: Own Damage
 Accident Date: 09/11/2019

Estimate Repair Cost to Vehicle No : GBC4051L

Description	U/Price	Quantity	Cost	Amount
			SS	SS
101 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD RADIATOR SUPPORT PANEL,FRT DOOR PILLAR RH,B PILLAR RH,C PILLAR RH,RR FENDER RH, ROCKER PANEL RH,STEP PANEL RH.TO KNOCK & REPAIR ROOF PANEL,TAILGATE & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	3,000.00	2200
102 TO SPRAY FRONT BONNET,FRONT GRILLE,CORNER PANEL,FRONT DOOR RH,FRONT DOOR PILLAR RH, SLIDING DOOR RH,ROCKER PANEL RH,RR FENDER RH,TAILGATE,REAR BUMPER.		1 PC	2,200.00	1980
				7,020.00

Lump Sum Repair S\$ 25,581.20
 Add GST @ 7% 1,790.68
 Total Amount payable S\$ 27,371.88

TOTAL: SINGAPORE DOLLAR TWENTY SEVEN THOUSAND THREE HUNDRED SEVENTY ONE AND CENTS EIGHTY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.
 Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #05-01/06 SINGAPORE LAND TOWER
 SINGAPORE 048623
 TEL: 64616555
 ATTN: Motor Claim Department

Claim No: MC1900823
 Ref No: MF1900927
 Date: 16 Mar 2020
 Policy No: D19MTPCVE000846
 Veh Reg No: GBC4051L
 Make/Model: TOYOTA HIACE
 MANUAL
 Chassis No: JTFHT02P300084696

Your Ref No: GBC4051L
 Claim Type: Own Damage
 Accident Date: 09/11/2019

Repair Cost to Vehicle No (For Finalization): GBC4051L

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 FRONT BONNET EMBLEM		1 PC	25.00	
2 FRONT BONNET INNER LOCK		1 PC	35.00	
3 HEADLAMP RH		1 PC	200.00	
4 CORNER PANEL RH		1 PC	60.00	
5 FRONT BUMPER		1 PC	165.00	
6 FRONT BUMPER SIDE RETAINER RH		1 PC	48.00	
7 FRONT BUMPER CLIPS		10 PC	15.00	
8 FRONT BUMPER LOWER AIR GRILLE		1 PC	70.00	
9 FRONT BUMPER TOW COVER		1 PC	13.00	
10 FRONT BUMPER REINFORCEMENT TOP		1 PC	65.00	
11 FRONT BUMPER REINFORCEMENT LOWER		1 PC	100.00	
12 FOGLAMP COVER RH		1 PC	35.00	
13 RADIATOR SUPPORT PANEL TOP		1 PC	135.00	
14 BRACE PANEL		1 PC	28.00	
15 FIREWALL CROSSMEMBER		1 PC	160.00	
16 AIR CON CONDENSER		1 PC	480.00	
17 AIR CON CONDENSER PIPE (COND-COMP)		1 PC	120.00	
18 AIR CON CONDENSER PIPE (COND-VALVE)		1 PC	110.00	
19 RADIATOR ASSY		1 PC	580.00	
20 RADIATOR FAN MOTOR ASSY		1 PC	365.00	
21 RADIATOR BOTTOM BRACKET		1 PC	38.00	
22 AIR FILTER BOX ASSY		1 PC	265.00	
23 FRONT WINDSCREEN MOULDING		1 PC	45.00	
24 FRONT DOOR PILLAR RH		1 PC	205.00	
25 STEP PANEL RH		1 PC	45.00	
26 STEP PANEL GARNISH RH		1 PC	55.00	
27 SIDE MIRROR W GLASS RH		1 PC	75.00	
28 FRONT DOOR RH		1 PC	580.00	
29 FRONT DOOR HINGE TOP		1 PC	30.00	
30 FRONT DOOR HINGE LOWER		1 PC	30.00	
31 FRONT DOOR CHECKER		1 PC	60.00	
32 FRONT DOOR RUBBER (AT DOOR)		1 PC	75.00	
33 FRONT DOOR RUBBER LOWER		1 PC	25.00	
34 FRONT DOOR POWER WINDOW MOTOR		1 PC	220.00	
35 FRONT DOOR POWER WINDOW REGULATOR		1 PC	70.00	
36 FRONT DOOR INNER LOCK		1 PC	175.00	
37 FRONT DOOR STRIKER		1 PC	15.00	
38 FRONT DOOR PILLAR REAR PORTION RH (B PILLAR)		1 PC	185.00	
39 FRONT WHEELHOUSE TOP TRIM RH		1 PC	145.00	

AH LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Industrial Park
 #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 FAX: 6483 6170 Email: ahlimc@singnet.com.sg

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimnc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #05-01/06 SINGAPORE LAND TOWER
 SINGAPORE 048623
 TEL: 64616555
 ATTN: Motor Claim Department

Claim No: MC1900823
 Ref No: MF1900927
 Date: 16 Mar 2020
 Policy No: D19MTPCVE000846
 Veh Reg No: GBC4051L
 Make/Model: TOYOTA HIACE
 MANUAL
 Chassis No: JTFHT02P300084696

Your Ref No: GBC4051L
 Claim Type: Own Damage
 Accident Date: 09/11/2019

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization): GBC4051L

Description	U/Price	Quantity	Cost	Amount
			SS	SS
75 FRONT WINDSCREEN SEALANT		1 PC	40.00	
76 60 KM/H		1 PC	10.00	
77 9 PAX		1 PC	10.00	
78 RADIATOR COOLANT		1 PC	35.00	
				522.00
LABOUR				
79 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00	
80 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	100.00	
81 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		1 PC	80.00	
82 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.		1 PC	120.00	
83 TO REMOVE AND REINSTALL/REPLACE DASHBOARD.		1 PC	250.00	
84 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.		1 PC	60.00	
85 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		1 PC	150.00	
86 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE - FRONT		1 PC	240.00	
87 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE - REAR		1 PC	150.00	
88 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.		1 PC	50.00	
89 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD RADIATOR SUPPORT PANEL,FRT DOOR PILLAR RH,B PILLAR RH,C PILLAR RH,RR FENDER RH, ROCKER PANEL RH,STEP PANEL RH.TO KNOCK & REPAIR ROOF PANEL,TAILGATE & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	2,200.00	
90 TO SPRAY FRONT BONNET,FRONT GRILLE,CORNER PANEL,FRONT DOOR RH,FRONT DOOR PILLAR RH, SLIDING DOOR RH,ROCKER PANEL RH,RR FENDER RH,TAILGATE,REAR BUMPER.		1 PC	1,980.00	
91 TO CHANGE ENGINE MOUNTING, RADIATOR, FAN MOTOR AND FUSE WIRE CONNECTOR		1 PC	200.00	
				5,620.00

AH LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Industrial Park 2A
 #01-09 AMK Autopoint Singapore 568047
 Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623

TEL: 64616555

ATTN: Motor Claim Department

Your Ref No: GBC4051L
Claim Type: Own Damage
Accident Date: 09/11/2019

Claim No: MC1900823
Ref No: MF1900927
Date: 16 Mar 2020
Policy No: D19MTPCVE000846
Veh Reg No: GBC4051L
Make/Model: TOYOTA HIACE
MANUAL
Chassis No: JTFHT02P300084696

Repair Cost to Vehicle No (For Finalization): GBC4051L

Total	S\$ 18,641.30
Lump Sum Less 20%	-3,728.26
Amount Before Excess	S\$ 14,913.04
Less Rounding	-13.04
Amount Before Excess	S\$ 14,900.00
Less Excess	S\$ 500.00
Amount Before GST	S\$ 14,400.00
Add GST @ 7%	1,008.00
Total Amount payable	S\$ 15,408.00

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND FOUR HUNDRED AND EIGHT ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 15/11/2019

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B
AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimco@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555
ATTN: Motor Claim Department

Final No: AL1902839
Claim No: MC1900823
Date: 21 Mar 2020
Policy No: D19MTPCVE000846
Veh Reg No: GBC4051L
Make/Model: TOYOTA HIACE
MANUAL
Chassis No: JTFHT02P300084696

Your Ref No: GBC4051L
Claim Type: Own Damage
Accident Date: 09/11/2019

Tax Invoice-Final Repair Cost to Vehicle No :GBC4051L

Description	Quantity	List Price	Amount
		SS	SS
As agreed to proceed repair at Lump Sum Repair			SS 14,900.00
Less Excess			SS 500.00
Amount Before GST			SS 14,400.00
Add GST @ 7%			1,008.00
Total Amount payable			<u>SS 15,408.00</u>

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND FOUR HUNDRED AND EIGHT ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 15/11/2019

For AH LIM MOTOR COMPANY

E. & O. E.

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE