



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile


SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO19020281/Ktd3e2

50 RAFFLES PLACE  
#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 07-04-2020



Code : SMO

### 1. Policy Particulars :- OWN DAMAGE

<b>Insured Veh.</b>		<b>Veh. Inspected</b>	GBC 4051L
<b>Policy No.</b>	D19MTPCVE000846	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CMTD1905293/AGC	<b>Excess (\$)</b>	500.00
<b>Assign From</b>	YONG KANG MELVIN	<b>Assign Date</b>	15/11/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA HIACE	<b>c.c</b>	2982
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2012
<b>Chassis No.</b>	JTFHT02P300084696	<b>Colour</b>	BLUE
<b>Odometer</b>	255422	<b>Steering</b>	JAMMED
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195 R15	BRIDGESTONE	9 mm
<b>L/H Front Tyre</b>	195 R15	BRIDGESTONE	9 mm
<b>R/H Rear Tyre</b>	195 R15	BRIDGESTONE	3 mm
<b>L/H Rear Tyre</b>	195 R15	BRIDGESTONE	3 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	09/11/2019	<b>Inspection Date</b>	15/11/2019
<b>Survey held at</b>	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		

### 5a. Remarks

A)THE MARKET VALUE IS S\$30,000.00(EST. AVERAGE)  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>24 Working Days</b>
--	------------------------