

ASS. REC. BY:

REF: es/AG/19020283/Ksd301

Special Instructions:

Surrender: Kenneth

ASSIGNMENT (Office)

From (Person):

Fun Winnie

of

AIG

Date/Time:

15/11/19 @ 11:42am

Estimated Cost:

Bill to:

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

GBJ 2093S

Insured:

at Workshop in/

Tong Luek

Tel:

6250 0088.

is

160 Sin Ming Drive #07-01/06

Policy No.:

Claim No.:

Sum Insured:

Excess:

~~100~~ \$1400

Make of Veh:

D.O.A.

06/10/2019

(Client's Record)

CA (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:01pm @ 15/11/19

Person Contacted:

candy

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	Tolman /
	GBJ 2093S-X
15/11/19	Revert Via Merimen
18/11/19	@ 17:25 pm mandate approved by Lois Chay via merimen.
18/11/19	@ 18:20 pm informed CA to Yu Chay via email.

ASS. REC. BY:

REF:

116/CS/ALG 19020283/Ksd3

Kennerth

ASSIGNMENT

From:

Date:

Estimated Cost:

00/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

17/12 84483.20 Car Insured

C\$ 2,649.60 Red - 37%

RECEIVED 16 DEC 2019

Date/Time, File Pass to?

1) Typist

Date/Time, File Return to?

2)



Prell. Report



Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

Lump Sum / I.B. (\$ 4,493.20 P/P)

200
11
211

- Estimated repair cost for repairing vehicle no.: GBJ2093S -- OD Claim

From: AIG SGP, Claims-Survey
To:
Cc: Fong, Andy-SY
Sent: 11/15/2019 11:42:02 AM
Attachments:  GBJ2093S - Estimate.pdf

Hi LKK,

Kindly assist to survey.

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Operation / Yu Ching [mailto:operation@tlauto.com.sg]
Sent: Friday, November 15, 2019 11:30 AM
To: AIG SGP, Claims-Survey
Cc: Fan, Winnie-LW
Subject: [EXTERNAL] Estimated repair cost for repairing vehicle no.: GBJ2093S -- OD Claim

This message is from an external sender; be cautious with links and attachments.

Dear All,

Please find attached documents for your information and necessary action

The vehicle is now garage at our workshop

Kindly arrange your surveyor to inspect the vehicle at an earlier date

Thanks & regards,
Yu Ching



Tong Luck Auto Pte Ltd

160 Sin Ming Drive

#07-01/06 Sin Ming Autocity

Singapore 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	778Z
Vehicle Details	
Vehicle No.:	GBJ20935
Vehicle to be Exported:	Yes
Intended Deregistration Date:	15 Nov 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	VITO 109 CDI MT LONG
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	R9MA503C053923
Chassis No.:	WDF44760323481698
Maximum Power Output:	-
Open Market Value:	\$28,138.00
Original Registration Date:	30 Jan 2019
First Registration Date:	30 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$1,407.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jan 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$26,230.00
COE Rebate Amount:	\$20,984.00
Total Rebate Amount:	\$20,984.00

The information contained herein is correct as at 15 Nov 2019

OK



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

1982 MB G Wagen Legit LWB 5 Doors 4x4 Proper. Rarr.



Strong Car With Presence,
Original Classic Style. Very
Sturdy, 1st Series Of G's.
Direct Owner. Sturdy

PRIME MOTOR & LEASING

TOHONG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

1 vehicles

Mercedes Benz VITO

Sort by Date Posted

20 results/page

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mercedes Benz VITO		Any	Any	2019	Any	Any	Any	Available
	Mercedes-Benz Vito	114 CDI	\$81,800	\$6,770 /yr	14-Mar-2019	2,143 cc	6,864 km	Van	Available
	Fuel Type: Diesel Luxury Van In Town! Still Under Warranty, Auto Transmission, Smooth Driving Experience And Good Performance. Fast Loan Approval Up To 100% Loan, High Trade In Available. Price Negotiable And Free Gift, Warranty Plus Free Servicing! Call Now For Better Offer!								
	ABWIN Bus Pte Ltd Posted: 15-Nov-2019 Tags: 2019 Mercedes-Benz Vito, 2019 mercedes-benz vito, Mercedes-Benz Vito, mercedes-benz vito, Mercedes-Benz, Vito, vito, Used Mercedes-Benz								

Save this search criteria, to get email alerts whenever a match is found.

For old advertisements, view **Expired ads**

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Mercedes Benz VITO, Mercedes Benz VITO Singapore, used Mercedes Benz VITO Singapore, used Mercedes Benz VITO, used vehicles Singapore or even buy used Mercedes Benz VITO Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

Marked V \$79

Compare

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 18 November 2019 6:20 pm
To: operation@tlauto.com.sg
Cc: SUR
Subject: GBJ 2093S OD (AIG) DOA - 06/10/2019

Dear Candy/Yu Ching,

As instructed by our client, please proceed to repair the insured vehicle **GBJ 2093S (Excess \$ 1,400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***GBJ20935 (2670782103SG)**

OD

Oct 6 2019 10:00AM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]

Tong Luck Auto Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 18/11/2019 17:25 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$4288.00) - GBJ20935 - Claim Handler: Azlan, Syazairdina

Approved:4288.00:RE-INSPECTION REQUIRE ON CHECK ITEM

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 15 Nov 2019

Preliminary Advice

Vehicle No	: GBJ2093S	Accident Date	: 06/10/2019
Make	: MERCEDES-BENZ VITO 109	Policy No.	: 0999994164
Assignment Date	: 15/11/2019	Excess	: S\$1,400.00
Date of Inspection	: 15/11/2019	Est. Duration of Repair	: 4.00
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,621.40
Revised Amount	:S\$	4,287.95
Check Items (Estimated)	:S\$	463.25
Total	:S\$	4,751.20

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	79,000.00
COE / PARF Rebate	:S\$	20,984.00
Salvage Value	:S\$	
Margin for Repair	:S\$	58,016.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/10/2019 00:06
Date Of Accident	06/10/2019 10:35
Exact Location Of Accident	ALONG BLOCK 608 ANG MO KIO AVENUE 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBJ2093S
Insured/Policyholder	
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Co Reg No	199803778Z
Email Address	KATHRYN.ADRIANO@DAIMLER.COM
Mobile Phone No	
Alternative Phone No	OFFICE-68498118

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	VITO 109 CDI MT LONG
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995580
Cover Note Number	

Driver

Name of Driver	WANG XIAOYU
NRIC No	G6651121P
Date Of Birth	29/08/1991
Occupation	OUTDOOR
Date Of Driving Pass	23/11/2012
Driving Experience	6 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90733855
Fax Number	
Contact Number	
Email Address	1623099608@QQ.COM

Address NIL

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? YES

Foreign Vehicle Registration Number JTH795 (MOTORCYCLE)

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 3

Passenger 1 NAME: : SUN XIAOYANG
GENDER: : MALE

Passenger 2 NAME: : P2
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER] ANG MO KIO NORTH N.P.C

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO POLICE REPORT NO.T/20191006/2068 LODGE AT ANG MO KIO NORTH N.P.C ON 06/10/2019 AT ABOUT 1035HRS, I WAS AT THE CAR PARK OF BLK 608 ANG MO KIO AVENUE 4. AFTER MAKING THE DELIVERY, I WANTED TO LEAVE THE CAR PARK, AND WAS MAKING THE TURN WHEN I REALIZED I WAS AT A DEAD END. I WAS UNABLE TO MAKE A THREE POINT TURN AS THE LOTS ALONG THE CAR PARK WERE ALL OCCUPIED. I THEN MADE THE REVERSE WHILE CHECKING MY SIDE MIRRORS. SUDDENLY, I HEARD A LOUD BANG AND IMMEDIATELY STOPPED MY CAR. MY REAR VIEW MIRROR WAS BLOCKED AND HENCE I WAS UNABLE TO SEE THE MOTORBIKE (JTH795) AT THE BACK. THE MOTORIST (CHINESE MALE IN HIS 30S) WAS ALREADY AT THE DRIVER SIDE WAITING FOR ME TO ALIGHT. I THEN ALIGHTED AND APOLOGIZED TO HIM. I ASKED IF HE NEEDED ANY MEDICAL ASSISTANCE AND THE MOTORIST INFORMED THAT HE HAD SPRAINED HIS RIGHT LEG AND DO NOT NEED IMMEDIATE MEDICAL ASSISTANCE. THERE IS A PRIVATE AMBULANCE AT THE CAR PARK, AND THE PARAMEDIC SAW WHAT HAD HAPPENED AND CAME TO CHECK ON US. AS THIS IS THE FIRST TIME SUCH INCIDENT HAPPENED, I WAS UNSURE OF WHAT TO DO AND HENCE CALLED MY MANAGER FOR ASSISTANCE. A WHILE LATER, THE MOTORIST COLLEAGUES CAME AND AFTER DISCUSSING THEY DECIDED TO CALL FOR THE TRAFFIC POLICE. WE ALL WAITED FOR THE TRAFFIC POLICE ARRIVAL, AND OUR PARTICULARS WERE TAKEN DOWN. THERE IS IN CAR CAMERA IN BOTH FRONT AND BACK OF MY VAN, WHICH THE TRAFFIC POLICE HAD TAKEN. THE MOTORIST WAS LATER CONVEYED TO THE HOSPITAL. THE REAR BUMPER OF MY VAN WAS DENTED. MY PASSENGER AND I WERE NOT INJURED FROM THE ACCIDENT.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	NA
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	JTH795
Vehicle Make/Model/Colour	NA
Details Of Properties	NA
Vehicle Category	MOTORCYCLE
Name of Driver	NA
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	
Approximate Age	
Injuries Sustain	HAD SPRAINED ON RIGHT LEG
Injured person in which vehicle?	JTH795
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
VOO CHEON YEE

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

8-10-2019

Sketch Plan #2

SKETCH PLAN

A: GBI20735
B: JTH 795



Along Ang Mo Kio Ave 5 Block
608 open Place Carpark.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

DECLARATION

(I/We declare the foregoing particulars are true in every respect.)

Motorist's Signature
Date & Time:

[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
VOO CHEON YEE

Reporting Centre Personnel's Signature
Name:
SR/CYIN No.:

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20191006/2068

1 of 3

Police Station Of Origin:
Ang Mo Kio North N.P.C.
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

Report No. T/20191006/2068

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/10/2019 13:31	Vide Report No.: F/20191006/0105	Station Diary No.: 19
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: WANG XIAOYU			Address: APT BLK 126 Bukit Merah Lane 1 #01-216 SINGAPORE 150126		
ID Type / ID No.: FIN NO / G6651121P			Contact No. Home/Office: Mobile: 90733855		
Nationality: CHINESE			Email:		
Sex: Male	Age: 28	Date of Birth: 29/08/1991	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: DELIVERY DRIVER			Driving Licence Information: Class: 3 Date of Expiry: 22/11/2022		

General Information of the Accident

Type of Accident:	Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 06/10/2019 10:35	Type of Location: Car Park
Location: Along Road 1 ANG MO KIO AVENUE 4 Blk 606 Ang Mo Kio Avenue 4 Carpark				
Weather:		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBU2093S	Van				Slightly Damaged	2
JTH795	Motorcycle					0

POLICE REPORT



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999



T/20191006/2068

2 of 3

Report No. T/20191006/2068

CONTINUATION OF REPORT

Brief Details.

On 06/10/2019 at about 1035hrs, I was at the carpark of Blk 608 Ang Mo Kio Avenue 4. After making the delivery, I wanted to leave the carpark, and was making the turn when I realized I was at a dead end. I was unable to make a three-point turn as the lots along the carpark were all occupied.

I then made the reverse while checking my side mirrors. Suddenly, I heard a loud bang and immediately stopped my car. My rearview mirror was blocked and hence I was unable to see the motorbike (JTH795) at the back. The motorist (Chinese Male in his 30s) was already at the driver side waiting for me to alight. I then alighted and apologized to him. I asked if he needed any medical assistance and the motorist informed that he had sprained his right leg and do not need immediate medical assistance. There is a private ambulance at the carpark, and the paramedic saw what had happened and came to check on us.

As this is the first time such incident happened, I was unsure of what to do and hence called my manager for assistance.

A while later, the motorist colleagues came and after discussing they decided to call for the traffic police. We all waited for the traffic police arrival, and our particulars were taken down. There is in-car camera in both front and back of my van, which the traffic police had taken. The motorist was later conveyed to the hospital. The rear bumper of my van was dented. My passengers and I were not injured from the accident.

POLICE REPORT



SINGAPORE
POLICE FORCE



T:201910062068

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4549999

3 of 3

Report No: T:201910062068

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 VIVIAN TEO MAN LING

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:
06/10/2019 13:31

Officer In Charge Of Case:

TP / AEIT /

Staff Sgt WONG SIEU LUI

Contact No: 65478151

Classification Of Case:

Authentication Stamp

NP166



MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1969 (MALAYSIA)

68.2.2015

SECOND



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 675722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 06/10/2019

ESTIMATE

NO : QUOT201911-000040(00)

DATE : 14/11/2019

POLICY NO : 999994764

VEH REG NO : GBJ2093S

MAKE/MODEL : MERCEDES BENZ VITO 109
CDI MT LONG

CHASSIS NO : WDF4760323481598

ENGINE NO : R3MA503C053923

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : GBJ2093S

Per: 62564315

Description	Quantity	Unit Price	Amount
		\$	\$
PARTS			
1 Tailgate	1	1,450.00	1,450.00 ✓
2 Tailgate weathstrip	1	128.00	128.00 ✓
3 Tailgate lock	1	160.00	160.00 ?
4 Tailgate centre logo	1	40.00	40.00 ✓
5 Tailgate 'VITO' emblem	1	45.00	45.00 ✓
6 Tailgate 'C&C' emblem	1	38.00	38.00 ✓
7 Tailgate '109 CDI' emblem	1	55.00	55.00 ✓
8 Tailgate centre trim	1	85.00	85.00 ✓
9 Tailgate inner trimboard clips	15	6.50	97.50 ?
10 Rear end panel	1	198.00	198.00 X
11 Rear end panel top garnish	1	78.00	78.00 ✓
12 Rear bumper	1	795.00	795.00 ✓
13 Rear bumper clips	15	5.50	82.50 ✓
			3,248.00
		Add 10%	324.80
			3,572.80
SPECIAL NET			
14 Rear windscreen sealant	1	60.00	60.00 ✓
15 Tailgate '8 PAX' sticker	1	25.00	25.00 12/11
16 Tailgate '70 km/h' sticker	1	25.00	25.00 12/11
17 Rear bumper sensor (set)	1	380.00	380.00 X
			490.00
LABOUR			
18 To remove and refit rear bumper sensor	1	100.00	100.00 30/
19 To remove and refit rear windscreen glass	1	150.00	150.00 12/11
20 To transfer damaged tailgate interior mechanism to new tailgate	1	150.00	150.00 60/
21 To check and rectify wiring system and focus of lightings	1	80.00	80.00 20/
22 To panel beat and straighten rear chassis frame, rear floorboard panel, rear bumper bracket, to cut and weld rear end panel including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00	1,200.00 50/
23 To putty and spray same or affected areas	1	1,200.00	1,200.00 40/
24 To supply and paste letterings on tailgate	1	180.00	180.00 ?
			3,060.00

(Invoice)?



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/05 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5543

Email: operation@t1auto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-10
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000 FAX : 6416 3723

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 08/10/2019

ESTIMATE

NO : QUOT201911-000040(00)
DATE : 14/11/2019
POLICY NO : 999994164
VEH REG NO : GBJ2093S
MAKE/MODEL : MERCEDES BENZ VITO 109
CDI MT LONG
CHASSIS NO : VJDF44760323461698
ENGINE NO : R9MA533C053923
REG. DATE : 2016

Estimate Repair Cost to Vehicle No : GBJ2093S

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 7,122.80
		ADD GST @ 7%	498.60
		GRAND TOTAL	S\$ 7,621.40

SINGAPORE DOLLAR SEVEN THOUSAND SIX HUNDRED TWENTY-ONE AND CENTS FORTY ONLY

Vehicle Consignments notice notify

the following information:


- Vehicle make, model, year, country
- Vehicle colour, engine, transmission
- Vehicle body colour, is it a "factory" finish
- No major modifications or repairs
- Accessories (e.g. roof rack, sunroof, etc.)
- Assigned to the assigned Motor Insurance Company

Accepted by Receiver

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD


AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 06/10/2019

ESTIMATE

NO : QUOT201911-000040(00)

DATE : 14/11/2019

POLICY NO : 999994164

VEH REG NO : GBJ2093S

MAKE/MODEL : MERCEDES BENZ VITO 109
CDI MT LONG

CHASSIS NO : WDF44760323481698

ENGINE NO : R9MA503C053923

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : GBJ2093S

4 days
Total 62564315

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Tailgate	1	1,450.00	1,450.00 ✓
2 Tailgate weathertrip	1	126.00	126.00 ✓
3 Tailgate lock	1	160.00	160.00 ✓
4 Tailgate centre logo	1	40.00	40.00 ✓
5 Tailgate 'VITO' emblem	1	45.00	45.00 ✓
6 Tailgate 'C&C' emblem	1	38.00	38.00 ✓
7 Tailgate '109 CDI' emblem	1	55.00	55.00 ✓
8 Tailgate centre trim	1	85.00	85.00 ✓
9 Tailgate inner trimboard clips	15	6.50	97.50 ✓
10 Rear end panel	1	196.00	196.00 X
11 Rear end panel top garnish	1	78.00	78.00 ✓
12 Rear bumper	1	795.00	795.00 ✓
13 Rear bumper clips	15	5.50	82.50 ✓
			3,248.00
		Add 10%	324.80
			3,572.80
SPECIAL NET			
14 Rear windscreen sealant	1	60.00	60.00 ✓
15 Tailgate '6 PAX' sticker	1	25.00	25.00 ✓
16 Tailgate '70 km/h' sticker	1	25.00	25.00 ✓
17 Rear bumper sensor (set)	1	380.00	380.00 X
Tailgate Centre trim rivets	1	20.00	20.00 ✓
			490.00
LABOUR			
18 To remove and refit rear bumper sensor	1	100.00	100.00 ✓
19 To remove and refit rear windscreen glass	1	150.00	150.00 ✓
20 To transfer damaged tailgate interior mechanism to new tailgate	1	150.00	150.00 ✓
21 To check and rectify wiring system and focus of lightings	1	80.00	80.00 ✓
22 To panel beat and straighten rear chassis frame, rear floorboard panel, rear bumper bracket, to cut and weld rear end panel including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00	1,200.00 ✓
23 To putty and spray same on affected areas	1	1,200.00	1,200.00 ✓
24 To supply and paste letterings on tailgate	1	180.00	180.00 ✓
			3,060.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This party survey is on a "Without Physical" basis
- No legal responsibility is placed
- Subsequently liability must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer

Signature

Date

(Invoice)?



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 06/10/2019

ESTIMATE

NO : QUOT201911-000040(00)
DATE : 14/11/2019
POLICY NO : 999994164
VEH REG NO : GBJ2093S
MAKE/MODEL : MERCEDES BENZ VITO 109
CDI MT LONG
CHASSIS NO : WDF44760323481698
ENGINE NO : R9MA503C053923
REG. DATE : 2018

Estimate Repair Cost to Vehicle No : GBJ2093S

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 7,122.80
		ADD GST @ 7%	498.60
		GRAND TOTAL	S\$ 7,621.40

SINGAPORE DOLLAR SEVEN THOUSAND SIX HUNDRED TWENTY-ONE AND CENTS FORTY ONLY

7142.80

FOR TONG LUCK AUTO PTE LTD


AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-15

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 08/10/2019

ESTIMATE

NO : QUOT201911-000040(00)

DATE : 14/11/2019

POLICY NO : 999994164

VEH REG NO : GBJ2093S

MAKE/MODEL : MERCEDES BENZ VITO 109
CDI MT LONG

CHASSIS NO : WDF44760323481698

ENGINE NO : R9MA503C053923

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : GBJ2093S

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY SPECIAL NET			
1 Tailgate centre trim rivets (set)	1	20.00	20.00
			20.00
		TOTAL	S\$ 20.00
		ADD GST @ 7%	1.40
		GRAND TOTAL	S\$ 21.40

SINGAPORE DOLLAR TWENTY-ONE AND CENTS FORTY ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tiauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 06/10/2019

ESTIMATE

NO : QUOT201911-000040(00)

DATE : 14/11/2019

POLICY NO : 999994164

VEH REG NO : GBJ2093S

MAKE/MODEL : MERCEDES BENZ VITO 109

CDI MT LONG

CHASSIS NO : WDF44760323481698

ENGINE NO : R9MA503C053923

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : GBJ2093S

4 days
Total: 62564315

Description	Quantity	Unit Price	Amount
		S\$	S\$

PARTS

1 Tailgate	1	1,450.00	1,450.00	✓
2 Tailgate weathstrip	1	126.00	126.00	✓
3 Tailgate lock	1	160.00	160.00	✓
4 Tailgate centre logo	1	40.00	40.00	✓
5 Tailgate 'VITO' emblem	1	45.00	45.00	✓
6 Tailgate 'C&C' emblem	1	38.00	38.00	✓
7 Tailgate '109 CDI' emblem	1	55.00	55.00	✓
8 Tailgate centre trim	1	85.00	85.00	✓
9 Tailgate inner trimboard clips	15	6.50	97.50	750SA
10 Rear end panel	1	196.00	196.00	X
11 Rear end panel top garnish	1	78.00	78.00	✓
12 Rear bumper	1	795.00	795.00	✓
13 Rear bumper clips	15	5.50	82.50	✓
Tailgate centre trim rivets \$20/- SN. 100-3N. 100-3N				✓
Add 10%				✓
				3,572.80

SPECIAL NET

14 Rear windscreen sealant	1	60.00	60.00	✓
15 Tailgate '6 PAX' sticker	1	25.00	25.00	121N
16 Tailgate '70 km/h' sticker	1	25.00	25.00	121N
17 Rear bumper sensor (set)	1	380.00	380.00	X
				490.00

LABOUR

18 To remove and refit rear bumper sensor	1	100.00	100.00	501
19 To remove and refit rear windscreen glass	1	150.00	150.00	1201
20 To transfer damaged tailgate interior mechanism to new tailgate	1	150.00	150.00	601
21 To check and rectify wiring system and focus of lightings	1	80.00	80.00	201
22 To panel beat and straighten rear chassis frame, rear floorboard panel, rear bumper bracket, to cut and weld rear end panel including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00	1,200.00	5001
23 To putty and spray same on affected areas	1	1,200.00	1,200.00	4001
24 To supply and paste letterings on tailgate	1	180.00	180.00	701
				3,060.00

(Invoice) ?

210



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 06/10/2019

ESTIMATE

NO : QUOT201911-000040(00)

DATE : 14/11/2019

POLICY NO : 999994164

VEH REG NO : GBJ2093S

MAKE/MODEL : MERCEDES BENZ VITO 109
CDI MT LONG

CHASSIS NO : WDF44760323481698

ENGINE NO : R9MA503C053923

REG. DATE : 2018

Estimate Repair Cost to Vehicle No : GBJ2093S

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 7,122.80
		ADD GST @ 7%	498.60
		GRAND TOTAL	S\$ 7,621.40

SINGAPORE DOLLAR SEVEN THOUSAND SIX HUNDRED TWENTY-ONE AND CENTS FORTY ONLY

4493.20
~~S\$ 4,553.20~~
XS 1,400.00

S\$ 3,153.20
7% 220.73

S\$ 3,373.93

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



明義汽車私人有限公司

MIN GHEE AUTO PTE LTD

8, Jalan Lembah Kallang, #01-01 Min Ghee Building, Singapore 339564
Main Tel: 6291 3888 Fax: 6291 2172, 6294 1450 Accounts Tel: 6291 6118 Accounts Fax: 6297 0853
Email: info@minghee.com (Main), accounts@minghee.com (Accounts)
Website: http://www.minghee.com

TAX INVOICE

INVOICE NO. **8168994**

DATE	18/11/2019	PAGE	1
TERM	30 Days Net	SALESMAN	Ong Hai Choon
CUSTOMER REF.	GBJ2093S	OUR REF.	25979

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER: TONGLUK1 TIME: 11:45
TONG LUCK AUTO PTE LTD
160, SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722
Telephone No: 62500088

ROUTE
SM2

DELIVER TO:

TONG LUCK AUTO PTE LTD
160 SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722

PART NO	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MBA447 740 39 00	REAR DOOR	6A-1A	1 PC	1,450.00	1,450.00
2 MBA447 741 03 00	SEALING REAR DOOR	1D-1E	1 PC	126.00	126.00
3 MBA447 885 18 25 9851	TRIM BUMPER	48-1AA	1 PC	795.00	795.00
4 MBA447 816 02 16	MERCEDES STAR	1B-6H	1 PC	40.00	40.00
5 MBA447 817 44 00	MODEL PLATE	1B-6H	1 PC	38.00	38.00
6 MBA447 817 15 14	MODEL PLATE	1B-6H	1 PC	45.00	45.00

GOODS RECEIVED IN GOOD ORDER
AND CONDITION

*GOODS SOLD ARE NOT RETURNABLE.

*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S
PREVAILING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 7 DAYS
FROM DATE OF INVOICE.

Exclusive Distributor



Stockists

Payment via telegraphic transfer to
Name of Bank: United Overseas Bank
Account Name: Min Ghee Auto Pte Ltd

Branch Code: 046

Account No.: 503-305-511-3

*Please send a screen shot of your payment/
transfer confirmation to
accounts@minghee.com

TOTAL SIN 2,494.00

ADD GST 7% 174.58

AMOUNT DUE SIN 2,668.58



DATE

ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.



8, Jalan Lembah Kallang, #01-01 Min Ghee Building Singapore 339564
Main Tel: 6298 3888 Fax: 6291 1172, 6294 1450 Accounts Tel: 6291 6118 Accounts Fax: 6297 0863
Email: info@minghee.com (Main), account@minghee.com (Accounts)
Website: <http://www.minghee.com>

TAX INVOICE

INVOICE NO. **8169245**

DATE	20/11/2019	PAGE	1
TERM	30 Days Net	SALESMAN	Ong Hai Choon
CUSTOMER REF.	GBJ2093S	OUR REF.	27109

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER: TONG LUCK TIME 08:30
TONG LUCK AUTO PTE LTD
160, SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722
575722
Telephone No: 62500088

ROUTE
SH3

DELIVER TO:

TONG LUCK AUTO PTE LTD
160 SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722

PART NO	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MBA447 740 19 00	REAR DOOR LOCK	1A-06F	1 PC	160.00	160.00
2 MBA447 817 03 14	MODEL PLATE	1B-6H	1 PC	55.00	55.00
3 MBA447 885 11 06	END PANEL TRIM	1D-01C	1 PC	78.00	78.00
4 MBA447 885 27 62	TRIM	1D-02K	1 PC	85.00	85.00

GOODS RECEIVED IN GOOD ORDER
AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.

*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S
PREVAILING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 7 DAYS
FROM DATE OF INVOICE.

Exclusive Distributor

HDK

Stockists

Payment via telegraphic transfer to
Name of Bank: United Overseas Bank
Account Name: Min Ghee Auto Pte Ltd
Branch Code: 046

Account No.: 903-109-511-3

*Please send a screenshot of your payment/
transfer confirmation to
account@minghee.com

TOTAL	SIN	378.00
ADD GST	7%	26.46
AMOUNT DUE	SIN	404.46

SIGN & COMPANY'S STAMP

DATE

ALL CHECKS MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.



FOR MIN GHEE AUTO PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Oct 2019		15 Nov 2019 12:29 Edit Adj Rpt	S\$4,493.20 Edit Estimates	S\$4,493.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD., Co. Reg. No.: 199803778Z, Tel: +6590733855								
Vehicle Reg. No.:	GBJ2093S	Date of Loss:	06/10/2019 10:00 - :59 [8 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 2670782103SG	Policy/Cover Note No.:	0999994164 (Comprehensive)						
		Excess:	S\$1,400.00						
Repairer:	Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01 Sin Ming AutoCity, 575722 Sin Ming - Tel: 6250 0088								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Azlan, Syazairdina] syazairdina.azlan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 26/11/2019]								
Driver/Custodian:	WANG XIADYU (28 / Male), NRIC: G6651121P, Tel: +6590733855 Email: 1623099608@qq.com								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (19/12/2019): Alert - Adj Mandate Approved (S\$4493.20) - GBJ2093S - Claim Handler: Azlan, Syaz... - AIG_SG (18/11/2019): Alert - Adj Mandate Approved (S\$4288.00) - GBJ2093S - Claim Handler: Azlan, Syaz... - AIG_SG (15/11/2019): Alert - Adj Mandate Maintained - GBJ2093S - Claim Handler: Azlan, Syazairdina - AIG_SG (15/11/2019): GBJ2093S / OD / 06/10/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBJ20935 (26707821035G)

OD

Oct 6 2019 10:00AM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]

Tong Luck Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Video												1 per page					
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail		Print			
1	18/11/19 08:32	OI video footage											Load MP4				
Assessment Reports												1 per page					
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	15/11/19 15:00	Adjuster Immediate Advice											Load HTM				
Photos/Images												1 per page					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	15/11/19 17:39	General View											Load JPG				
2	15/11/19 17:39	General View											Load JPG				
3	15/11/19 17:39	General View											Load JPG				
4	15/11/19 17:39	General View											Load JPG				
5	15/11/19 17:39	General View											Load JPG				
6	15/11/19 17:39	General View											Load JPG				
7	15/11/19 17:39	General View											Load JPG				
8	15/11/19 17:39	General View											Load JPG				
9	15/11/19 17:39	General View											Load JPG				
10	15/11/19 17:39	General View											Load JPG				
11	15/11/19 17:39	General View											Load JPG				
12	15/11/19 17:39	General View											Load JPG				
13	15/11/19 17:39	General View											Load JPG				
14	15/11/19 17:39	General View											Load JPG				
15	15/11/19 17:39	General View											Load JPG				
16	15/11/19 17:39	General View											Load JPG				
17	15/11/19 17:39	General View											Load JPG				
18	15/11/19 17:39	General View											Load JPG				
19	15/11/19 17:39	General View											Load JPG				
20	17/12/19 10:25	Reinspection Photo											Load JPG				
21	17/12/19 10:25	Reinspection Photo											Load JPG				
22	17/12/19 10:25	Reinspection Photo											Load JPG				
23	17/12/19 10:25	Reinspection Photo											Load JPG				
24	17/12/19 10:25	Reinspection Photo											Load JPG				
Documentation												1 per page					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	15/11/19 14:42	Singapore Accident Statement											Load PDF				
2	15/11/19 14:42	Police Report											Load PDF				
3	15/11/19 14:42	Certificate of Insurance											Load PDF				
4	15/11/19 14:42	Driver's Driving License											Load PDF				
5	15/11/19 14:42	ESTIMATE											Load PDF				
6	18/12/19 16:19	ESTIMATE & SUPP MARKED.pdf											Load PDF				
7	19/12/19 14:06	Parts Invoice											Load PDF				

Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	13/11/19 10:26	Addendum Sheet	 Load TIF	
2	06/12/19 18:48	Accident Statement	 Load HTM	
3	06/12/19 18:49	Accident Statement	 Load HTM	
4	06/12/19 18:50	Accident Statement	 Load HTM	
5	06/12/19 18:51	Accident Statement	 Load HTM	
6	06/12/19 18:51	Accident Statement	 Load HTM	
7	06/12/19 18:52	Accident Statement	 Load HTM	
8	06/12/19 18:52	Accident Statement	 Load HTM	
9	06/12/19 18:55	Accident Statement	 Load HTM	
10	06/12/19 19:20	Accident Statement	 Load HTM	
11	06/12/19 19:23	Accident Statement	 Load HTM	
12	06/12/19 19:24	Accident Statement	 Load HTM	
13	06/12/19 19:25	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	09/10/19 22:25	Accident Photo	 Load JPG	☒
2	09/10/19 22:25	Accident Photo	 Load JPG	☒
3	09/10/19 22:25	Accident Photo	 Load JPG	☒
4	09/10/19 22:25	Accident Photo	 Load JPG	☒
5	09/10/19 22:25	Accident Photo	 Load JPG	☒
6	09/10/19 22:25	Accident Photo	 Load JPG	☒
7	09/10/19 22:25	Accident Photo	 Load JPG	☒
8	09/10/19 22:25	Accident Photo	 Load JPG	☒
9	09/10/19 22:25	Accident Photo	 Load JPG	☒
10	09/10/19 22:26	Accident Photo	 Load JPG	☒
11	09/10/19 22:26	Accident Photo	 Load JPG	☒
12	09/10/19 22:26	Accident Photo	 Load JPG	☒
13	09/10/19 22:26	Accident Photo	 Load JPG	☒
14	09/10/19 22:26	Accident Photo	 Load JPG	☒
15	09/10/19 22:26	Accident Photo	 Load JPG	☒
16	09/10/19 22:26	Accident Photo	 Load JPG	☒
17	09/10/19 22:26	Accident Photo	 Load JPG	☒
18	09/10/19 22:26	Driving License	 Load JPG	☒
19	09/10/19 22:26	Driving License	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	09/10/19 01:00	Sketch Plan	 Load TIFF	
2	09/10/19 01:00	Sketch Plan #2	 Load JPG	☒
3	09/10/19 01:00	POLICE REPORT	 Load JPG	☒
4	09/10/19 01:00	POLICE REPORT	 Load JPG	☒
5	09/10/19 01:00	POLICE REPORT	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer. Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG19020283/KSD3E2

Date: 19/12/2019

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.

Policy No: 0999994164

Date of Loss: 06/10/2019

Nature of Claim: OD Claim No: 2670782103SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBJ2093S

Make & Model: MERCEDES-BENZ VITO 109, 1.6 CDI LONG (M)

Engine No: R9MA503C053923

Reg. Date: 30/01/2019 (Man. Year: 2018)

Chassis No: WDF44760323481698

Colour: White

Odometer: 14741 km

Engine Capacity: 1598 cc

Market Value/New Car Price: S\$79,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R16

Rear Tyre Size: 205/65 R16

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 7 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,082.80	3,343.20	739.60	18.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,060.00	1,150.00	1,910.00	62.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,142.80	4,493.20	2,649.60	37.09
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	5,742.80	3,093.20	2,649.60	46.14
+ GST 7.00/7.00% (S\$)	402.00	216.52	185.48	46.14
Nett Amount (S\$)	6,144.80	3,309.72	2,835.08	46.14

INSPECTION

Date of Assignment: 15/11/2019

Date Inspected: 15/11/2019 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,450.00 F	*1,450.00 F
2	1		*TAILGATE WEATHERSTRIP	Cut	126.00 F	*126.00 F
3	1		*TAILGATE LOCK	Dented	160.00 F	*160.00 F
4	1		*TAILGATE CENTRE LOGO	Necessary	40.00 F	*40.00 F
5	1		*TAILGATE VITO EMBLEM	Necessary	45.00 F	*45.00 F
6	1		*TAILGATE C&C EMBLEM	Necessary	38.00 F	*38.00 F
7	1		*TAILGATE 109 CDI EMBLEM	Necessary	55.00 F	*55.00 F
8	1		*TAILGATE CENTRE TRIM	Cracked	85.00 F	*85.00 F
9	1		*TAILGATE INNER TRIMBOARD CLIPS (15PCS)	Necessary	107.25 FS	*50.00 FS
10	1		*REAR END PANEL	Repair	196.00 F	*- F
11	1		*REAR END PANEL TOP GARNISH	Dented	78.00 F	*78.00 F
12	1		*REAR BUMPER	Buckled	795.00 F	*795.00 F
13	1		*REAR BUMPER CLIPS (15PCS)	Necessary	90.75 FS	*50.00 FS
14	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
15	1		*TAILGATE 6 PAX STICKER	Necessary	25.00 FS	*12.00 FS
16	1		*TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*12.00 FS
17	1		*SET REAR BUMPER SENSOR	Serviceable	380.00 FS	*- FS
18	1		*SET TAILGATE CENTRE TRIM RIVETS	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	3,776.00	3,056.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	306.80	287.20

Total Parts (\$\$)	4,082.80	3,343.20
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	100.00	50.00
2	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
3	TO TRANSFER DAMAGED TAILGATE INTERIOR MECHANISM TO NEW TAILGATE	New	150.00	60.00
4	TO CHECK AND RECTIFY WIRING SYSTEM AND FOCUS OF LIGHTINGS	New	80.00	20.00
5	TO PANEL BEAT AND STRAIGHTEN REAR CHASSIS FRAME, REAR FLOORBOARD PANEL, REAR BUMPER BRACKET, TO CUT AND WELD REAR END PANEL INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,200.00	500.00
6	TO PUTTY AND SPRAY SAME ON AFFECTED AREAS	New	1,200.00	400.00
7	TO SUPPLY AND PASTE LETTERINGS ON TAILGATE	New	180.00	0.00
Gross Labour Cost (S\$)			3,060.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >