

CO. REG. NO: 199402370D
GST NO: M2-0123250-3

K. Kim Hin AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 30866

Date : 14-Nov-2019

PAGE : 1

Vehicle Insured : SHB 4694 R
Accident Date : 13-Nov-2019

Our Ref : 190679 (FIRST CAP) / SANDRA

ANTONIE LEE CHEE THIONG (MR)
Singapore

85042.72

Not Withheld

Running B4 PGM

9day

ESTIMATED COST OF REPAIR FOR HONDA SHUTTLE 1.5G CVT (2017) SLP7823U
=====

1 pc front bumper		Bul/cm 1,050.00	
2 pcs front bumper side retainer (LH/RH)	@ S\$ 15.40	old 30.80	15.40
1 pc o/s front bumper fog cover		Sn 45.00	X
1 pc front bumper centre lower grille		Sn 140.00	X
10 pcs front bumper clips	@ S\$ 3.50	M 35.00	
1 pc o/s front fender		R 435.00	X R
1 pc o/s front fender inner shield		CM 110.50	
8 pcs o/s front fender inner shield clips	@ S\$ 3.50	M 28.00	
1 pc wiper washer tank		Sn 75.00	X
1 pc wiper washer tank motor		Sn 59.60	X
1 pc o/s headlamp		CM 2,250.00	X
2 pcs headlamp lower bracket (LH/RH)	@ S\$ 38.00	Sn 76.00	X
1 pc front tyre lower arm LH		Bj 285.30	7V
1 pc front tyre knuckle arm LH		Bj 330.60	7V
1 pc front tyre knuckle arm bearing LH		M 168.00	7V
1 pc front tyre shock absorber LH		Bj 480.60	7V
1 pc front tyre shock absorber LH mounting		Sn 36.80	X
1 pc front tyre shock absorber LH bearing		Sn 36.70	X
1 pc front tyre shock absorber LH stopper		Sn 21.30	X
		5,694.20	
Less 20% :		-1,138.84	
		4,555.36	

Con't Page 2 ...

K. Kim Hin AUTO PTE LTD

金興(龔)汽車私人有限公司
160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

CO. REG. NO: 199402370D
GST NO: M2-0123250-3

Vehicle Insured : SHB 4694 R
Our Ref : 190679

Page : 2
No. : 30866

1 pc n/s front tyre 15"
1 pc front tyre sport rim

120sn 601sn
200.00 sn ?
300.00 sn
250sn

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

450.00 30d

To dismantle and check front under-
carriages. To replace affected
portions.

150.00 2

To putty and respray on affected
portions.

680.00 40d

To apply undersealing

40.00 2d

Total : S\$ 6,375.36
=====

Singapore Dollars Six Thousand Three Hundred
and Seventy Five and Cents Thirty Six Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

- LKK Auto Consultants hence notify
the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

4days

4753.40
- 20%
3802.48 72s/Parts
370 420 480.00 SN
+ 870.00 Labour
5152.48
5092.72