



# Feida Bus Consortium Pte Ltd

06 Sungei Kadut Way Singapore 728786

Tel: +656655 6665

Fax: +656655 665

15 November 2019

To: AIG ASIA PACIFIC INSURANCE PTE LTD

c/o : Attending Surveyor

Dear Sirs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

BY HAND ONLY

(+65 6419 3000)

Acknowledged by Repairer

Signature:

Date:

## THIRD PART CLAIM :- REPAIR ESTIMATE FOR CB 3111 Y

Traffic accident on 05/11/2019 at about 1805 hours along/at road 1 Paya Lebar road involving CB 3111 Y and SDW3039B

We append below the repair estimate for CB 3111 Y, MODEL : SUNLONG SLK6110

### Part required :-

1 pc	Rear right corner bumper	\$ 900.00	OK ✓
1 pc	Rear right lid cover assy	\$ 150.00	X NY
1 pc	Front right corner bumper	\$ 1500.00	OK ✓
1 pc	Front right battery door	\$ 1200.00	X NY
1 pc	Front right battery door lock	\$ 100.00	X NY
2 pcs	Front right foglamp	\$ 250.00	X NY
		\$ 4100.00	2400
	Less 10% trade discount	\$ 410.00	240
	Total part cost	\$ 3690.00	2160.

### Labour charges:-

To putty and spray painting on rear right corner bumper , front right corner bumper, front right battery compartment all affected accident part.(two tones)

\$ 2900 600

To knock/straighten all necessary part including repairing and changing of all damaged parts and align same

\$ 1500 600

Total repair cost

\$ 8,090.00

3360.

4/5 \$2600

Note:- This estimate is based on visible damage only. Should any hidden parts and/or labour charges required during works in progress, insurer and/or their surveyor will be notified accordingly.

Price quoted is subjected to 7% GST

Tanfik 97495749

WP

15/11/19

03 days

Impress

Resurvey after repair.

tanfik@lkkauto.com

Encl.

