## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: EQ Insurance Company Ltd F

5 Maxwell Road,#17-00 Tower Block

MND Complex Singapore 069110 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Joel Goh Date: 18 Nov 2019

# **Preliminary Advice**

Insured Vehicle No : FBP9835R

TP Vehicle No : SHC3881T Accident Date : 13/11/2019

Make : HYUNDAI I40 Assignment Date : 15/11/2019

Date of Inspection : 15/10/2019 Est. Duration of Repair : 2/Days

Inspection At : COMFORTDELGRO ENGINEERING PTE LTD

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...Rear.... portion and parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 1,498.10 |
|-----------------------------|------|----------|
| Revised Amount              | :S\$ | 738.00   |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 738.00   |

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

### Remarks

| ( | ) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. |
|---|---|--|
|   |   | Kindly let us have your authorisation.   |

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(x) Other comments: We have not authorized repairs.