

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

EQ Insurance Company Ltd (HQ)

Singapore

C45

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY
Policy No:
Vehicle Reg. No.: SHC3881T
Party At Fault: UNKNOWN

Ref. No:
Date of Loss: 13/11/2019
Driveable?

Make/Model: HYUNDAI I40, 1.7 D CRDI (A)
Vehicle Colour: BLUE
Engine No: D4FDEU473971
Odometer: 0 KM

Vehicle Reg. Date: 11/02/2015
Chassis No: KMHLB41UMFU06460

Paint Type:
List Item Discount: 20.00 %
Total Loss? NO
Est. Duration of Repair (day) 3

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

	Amount
Parts	828.10
Miscellaneous Items	0.00
Labour	670.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (\$\$) 1,498.10
+ GST 7.00% (\$\$) 104.87
Nett Amount (\$\$) 1,602.97

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 13 Nov 2019)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC3881T/13/11/2019 16:53**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER X(R)	20.00	0.00	*553.00 FL
2	1		*REAR BUMPER UNDER COVER CU	20.00	0.00	*228.00 FL
3	10		*REAR BUMPER CLIPS Xnn	20.00	0.00	*22.00 FL
4	1		*REVERSE SENSOR Xnn	0.00	0.00	*135.70 F
5	1		*REAR BUMPER PROTECTOR PLATE Xnn	0.00	0.00	*50.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) **988.70****- List Item Discount on L Items (S\$)** **160.60****Total Parts (S\$)** **828.10**

ComfortDelGro Engineering Pte Ltd/SHC3881T/13/11/2019 16:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	300.00 \$280
2	SPRAY PAINTING	New	250.00 \$200
3	R/I REVERSE SENSOR	New	120.00 \$30
Gross Labour Cost (\$\$)			670.00

ComfortDelGro Engineering Pte Ltd/SHC3881T/13/11/2019 16:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram/LKK
15/10/19 1200hrs
4S aft repair
Photo
ParaSuram@LKKauto.com
88622778
2 repair days