

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7539L**AAD1911-120***Not Authen**Reserve B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

14 NOV 2019

SHB 7539L

JTDKB3FU503082658

TOYOTA

PRIUS

13.11.19

EQ

16-08-19

PART			LIST		
1	1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	R 1,287.40	X
2	1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$	PL 321.10	} X
3	1	RUN, FRONT DOOR GLASS, RH	\$	PL 153.60	
4	1	WEATHERSTRIP, FRONT DOOR, RH	\$	PL 231.30	
5	1	LOCK ASSY, FRONT DOOR W/MOTOR, RH	\$	R 603.20	
6	1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	PL 390.60	
7	1	COVER, FRONT DOOR OUTSIDE HANDLE, RH	\$	PL 17.90	
8	1	FRAME SUB ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$	PL 193.50	
9	1	PAD, FRONT DOOR OUTSIDE HANDLE, REAR	\$	PL 16.40	
10	1	PAD, FRONT DOOR OUTSIDE HANDLE, FRONT	\$	PL 16.40	
11	1	CYLINDER SET, LOCK	\$	PL 287.50	} X
12	1	KEY, CUT	\$	PL 228.80	
13	1	KEY, BLANK	\$	PL 87.80	
14	1	TAPE, BLACK OUT, NO.1 FRT RH	\$	PL 13.30	
15	1	TAPE, BLACK OUT, NO.2 FRT RH	\$	PL 43.50	
16	1	TAPE, BLACK OUT, NO.3 FRT RH	\$	PL 26.30	
17	1	RIGHT SIDE VIEW MIRROR	\$	PL 1,436.60	
18	1	PANEL SUB-ASSY, REAR DOOR, RH	\$	R 1,281.70	✓
19	1	WEATHERSTRIP, REAR DOOR, RH	\$	PL 180.10	X
20	1	WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	\$	PL 293.00	X
21	1	MOULDING ASSY, REAR DOOR BELT, RH	\$	PL 113.50	X
22	1	WEATHERSTRIP, REAR DOOR, NO.3 RH	\$	PL 36.20	X
23	1	HINGE ASSY, REAR DOOR, LOWER RH	\$	R 87.10	X
24	1	HINGE ASSY, REAR DOOR, UPPER RH	\$	R 98.90	X
25	1	MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$	926.00	?
26	1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$	206.70	?
27	1	RUN, REAR DOOR GLASS, RH	\$	PL 122.50	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7539L**AAD1911-120**

28	1	CHECK ASSY, REAR DOOR, RH	\$	183.80	X
29	1	LOCK ASSY, REAR DOOR W/MOTOR, RH	\$	561.90	X
30	1	TAPE, BLACK OUT, NO.1 REAR RH	\$	21.90	✓
31	1	TAPE, BLACK OUT, NO.2 REAR RH	\$	34.90	✓
32	1	TAPE, BLACK OUT, NO.3 REAR RH	\$	15.40	✓
33	1	HANDLE ASSY, REAR DOOR, OUTSIDE RH	\$	97.40	X
34	1	FRAME SUB ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$	193.50	
35	1	PAD, REAR DOOR OUTSIDE HANDLE, REAR	\$	16.40	
36	1	PAD, REAR DOOR OUTSIDE HANDLE, FRONT	\$	16.40	
37	1	WIRE, REAR DOOR, NO. 1	\$	247.40	
38	1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	594.80	
39	1	PANEL SUB ASSY, QUARTER, RH	\$	854.80	
40	1	LINER, REAR WHEEL HOUSE, RH	\$	139.80	
41	1	SEAL, REAR BUMPER SIDE, RH	\$	88.50	
42	1	COVER, REAR BUMPER	\$	442.60	
43	1	RETAINER, REAR BUMPER SIDE, RH	\$	117.70	
TOTAL			\$	12,328.10	
25%			\$	3,082.03	
			\$	9,246.08	

Special Nett

1	1	FRONT DOOR STICKER 'TRANS-CAB'	\$	100.00	Goan
2	1	REAR DOOR STICKER "6555-3333"	\$	100.00	Goan
3	1	REAR WHEEL RIM	\$	1,570.55	X
4	1	REAR WHEEL RIM COVER	\$	175.80	
5	1	REAR TYRE 195/65/15	\$	350.00	
6	2	REAR WINDSCREEN SEALANT	\$	80.00	
7	1	WINDSCREEN MOULDING	\$	100.00	
8	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
9	1SET	REAR FENDER LINER CLIP	\$	35.00	
10	1SET	PARKING AID	\$	700.00	
11	1SET	REAR BUMPER CLIP	\$	66.00	
12	1SET	REAR BUMPER RETAINER CLIP	\$	20.00	
13	1	DOOR CHECK BOLT	\$	22.69	
14	1	DOOR HINGE BOLT	\$	10.85	
15	1	DOOR HINGE NUT LH	\$	14.60	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7539L**AAD1911-120**

16	1	DOOR CHECK BOLT	\$	Sn	22.69	X
17	1	DOOR CHECK NUT	\$	Sn	3.75	X
18	1	DOOR LOCK SCREW	\$	Sn	6.12	X
TOTAL			\$		3,478.06	
TOTAL PARTS			\$		12,724.14	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	8801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	4001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn	380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00 X
To transfer of front door fittings, attachment and perform water seepage test.	\$	nn	170.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00 X
To check steering geometry and computer wheel alignment	\$	nn	220.00 X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of rear door fittings, attachment and perform water seepage test.	\$	170.00	801
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	nn	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1911-120**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7539L

To reinstall rear bumper parking sensor. \$ *na* 170.00 X

To transfer of rear fender fittings, attachment to facilitate bodywork repair. \$ *na* 170.00 X

To transfer of rear bumper fittings, attachment to facilitate bodywork repair. \$ *na* 170.00 X

TOTAL \$ **17,510.00**

Over All Total \$ **30,234.14**

(PART-BY-PART) Repair Days *25 days*

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: