

22/01/2011

ASS. REC. BY:

REF:

CS/00119020318/Eg d3^{SY}

Special Instructions:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Li Si

of

UOI

Date/Time: 15/11/11 @ 11:05am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 5742R

Insured:

Public Liability

at Workshop no/s

Auto wheel

Tel:

9192 8963

of

No. 1 Bukit Bukit Crescent #02-46

Policy No:

Claim No:

L11D58221911

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10/11/2011

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:05am @ 15/11/11

Person Contacted:

Louis

Vehicle IN/OUT

Date/Time	Action/Instruction
	Exhaust ✓
	SLE 5742R - X
14/12/20	Submit Preli. report. - The vehicle has not send in for repair.

ASS. REC. BY:

Steve

REF: UOI

ASSIGNMENT

From:

Date:

9/12/19

Estimated Cost:

OE / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLE 5742R

at Workshop m/s

Autowheel

of No. 1 Bukit Batok Crescent #02-40

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

3pm (waiting)
see to go

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLE 5742R

Yr Regn:

27/7/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Veloster

c.c

1591

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

31175

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

K MHTC 61E4H4 303824

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/40R18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

10/11/19

D.O.I.

9/12/19

Survey held at

Autowheels

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/2/20

No documents (check with Insurance)
Owner mentioned hit by carpark gate barrier.
Vehicle no repair (Lans)
No GIA

RECEIVED 17 FEB 2020

Date/Time, File Pass by?



Preli. Report

1) 12/2 tyron

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Inv (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + FS: \$1

Photos

Other:

TOTAL

180

60

27

267

Report Format:

Lump Sum / L.B. / P.

Nivitha (LKK Auto)

From: CHAN LI SI <lisi@uoi.com.sg>
Sent: Friday, 15 November 2019 11:05 AM
To: mingkwang.lim@xpo.com
Cc: S Ganasan; assignments
Subject: Contact between carpark barrier arm at Westmall and vehicle SLE5742R on 10 November 2019 - UOI's ref: L11D58221911
Attachments: PDPA.zip

Without Prejudice

Dear Mr Lim,

We are the public liability insurers of Alprop Pte Ltd and the above matter is receiving our attention.

On a without prejudice basis, we are appointing our motor surveyor LKK Auto Consultants Pte Ltd to survey your vehicle and to review the provided quotation.

Our appointed surveyor will liaise with your workshop, Auto Wheels Motorworks Pte Ltd directly.

In accordance with our standard procedures, please find enclosed a copy of our "PDPA" letter for your attention.

Regards,

Chan Li Si

Executive
Claims

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9330 | Fax • (65) 6327 3869 | Email • lisi@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

Nivitha (LKK Auto)

From: CHAN LI SI <lisi@uoi.com.sg>
Sent: Friday, 15 November 2019 11:07 AM
To: assignments
Subject: FW: Contact between carpark barrier arm at Westmall and vehicle SLE5742R on 10 November 2019 - UOI's ref: L11D58221911
Attachments: Scan1.zip

Dear Denise,

I refer to our telephone conversation this morning.

Please arrange for a WP survey for this vehicle SLE 5742R.

Attached is a copy of the quotation.

Regards,

Chan Li Si

Executive
Claims

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9330 | Fax • (65) 6327 3869 | Email • lisi@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: CHAN LI SI
Sent: Friday, 15 November, 2019 11:05 AM
To: 'mingkwang.lim@xpo.com' <mingkwang.lim@xpo.com>
Cc: 'S Ganasan' <Ganasan@westmall.com.sg>; assignments <assignments@lkkauto.com>
Subject: Contact between carpark barrier arm at Westmall and vehicle SLE5742R on 10 November 2019 - UOI's ref: L11D58221911

Without Prejudice

Dear Mr Lim,

We are the public liability insurers of Alprop Pte Ltd and the above matter is receiving our attention.

On a without prejudice basis, we are appointing our motor surveyor LKK Auto Consultants Pte Ltd to survey your vehicle and to review the provided quotation.

Our appointed surveyor will liaise with your workshop, Auto Wheels Motorworks Pte Ltd directly.

In accordance with our standard procedures, please find enclosed a copy of our "PDPA" letter for your attention.

Regards,

Chan Li Si

Executive
Claims

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909

Main • (65) 6222 7733 | DID • (65) 6490 9330 | Fax • (65) 6327 3869 | Email • lsi@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	028F
Vehicle Details	
Vehicle No.:	SLE5742R
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Dec 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	VELOSTER FS 1.6 T-GDI GLS DCT 2WD SR
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	G4FJGU287454
Chassis No.:	KMHTC61EVHU303824
Maximum Power Output:	137.0 kW (183 bhp)
Open Market Value:	\$20,391.00
Original Registration Date:	27 Jul 2016
First Registration Date:	27 Jul 2016
Transfer Count:	1
Actual ARF Paid:	\$20,548.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2026
PARF Rebate Amount:	\$15,411.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,378.00
COE Rebate Amount:	\$37,077.00
Total Rebate Amount:	\$52,488.00

The information contained herein is correct as at 12 Dec 2019

OK





AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: UOI INSURANCE

DATE: 27/11/2019
VEHICLE NO: SLE5742R
MODEL: HYUNDAI
ACCIDENT DATE: 10/11/2019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
FRONT WINDSCREEN / SCR/CRA	1	\$ 1,023.10 814.60
FRONT WINDSCREEN MOULDING / NPC	1	\$ 291.20 47.30
RH FRONT PILLAR X R	1	REPAIR
RH FRONT FENDER X NN	1	REPAIR
TOTAL:		\$ 1,314.30 861.90
DISCOUNT 20%:		\$ 262.86 -20%
		\$ 1,051.44 689.52

S/NET		
FRONT WINDSCREEN SEALANT / NPC	1	\$ 80.00 40/
SOLAR FIRM / NPC	1	\$ 500.00 200/
IU BRACKET / NPC	1	\$ 30.00 25/
TOTAL:		\$ 610.00 265

LABOUR	PRICE
LABOUR FOR FACILITATE REPAIR	\$ 500.00 100/
TO RESPRAY RH A PILLAR	\$ 300.00 200/
TO RESPRAY RH FRONT FENDER	\$ 300.00 X
TO REMOVE AND REFIT FRONT WINDSCREEN	\$ 150.00 120/
TOTAL:	\$ 1,250.00 420

TOTAL: \$ 2,911.44
7% GST: \$ 203.80
\$ 3,115.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve CLKK)
9/12/19, 3.15pm
with prejudice
2 days
P/P
Ry before spy

P-689.52
N-265
L-420
P/P - 1374.52




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
UNITED OVERSEAS INSURANCE LTD		Ref : CS/UOI19020318/Eqd3s2	
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909		Date : 17-02-2020	
		Code : UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SLE 5742R
Policy No.		Coverage (\$)	0.00
Claim No.	L11D58221911	Excess (\$)	0.00
Assign From	LI SI CHAN	Assign Date	15/11/2019
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI VELOSTER	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHTC61EVHU303824	Colour	BLUE
Odometer	31175	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	HANKOOK	5 mm
L/H Front Tyre	225/40 R18	HANKOOK	5 mm
R/H Rear Tyre	225/40 R18	HANKOOK	5 mm
L/H Rear Tyre	225/40 R18	HANKOOK	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	10/11/2019	Inspection Date	09/12/2019
Survey held at	AUTO WHEELS MOTORWORKS PTE LTD NO 1 BUKIT BATOK CRESCENT #02-40 WCEGA PLAZA SINGAPORE 658064		
5a. Remarks			
A)THE VEHICLE HAS NOT SEND IN FOR REPAIR. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 5742R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT WINDSCREEN	SCRATCHED / CRACKED	1,023.10	1,023.10
1	FRONT WINDSCREEN MOULDING	NECESSARY	291.20	291.20
1	RH FRONT PILLAR (NPA)	TO REPAIR SEE LABOUR	-	-
1	RH FRONT FENDER (NPA)	NOT NECESSARY	-	-
	LESS 20% DISCOUNT		-262.86	-262.86
			1,051.44	1,051.44
SPECIAL NETT ITEMS				
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	SOLAR FILM (SN)	NECESSARY	500.00	200.00
1	IU BRACKET (SN)	NECESSARY	30.00	25.00
			610.00	265.00
LABOUR				
	LABOUR FOR FACILITATE REPAIR. INCLUSIVE OF THE REPAIR OF RH FRONT PILLAR.		500.00	100.00
	TO RESPRAY RH A PILLAR.		300.00	200.00
	TO RESPRAY RH FRONT FENDER.	NOT NECESSARY	300.00	-
	TO REMOVE AND REFIT FRONT WINDSCREEN.		150.00	120.00
			1,250.00	420.00
GRAND TOTAL			2,911.44	1,736.44
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				1,736.44

Report Ref No. CS/UOI19020318/Eqd3s2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.