

ASS. REC. BY:

REF: es/uo1191020319/Kvd3m Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Jenny Lew of UOI Date/Time: 15/11/19 @ 2.08pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 7829A Insured: GBH 8726X

at Workshop m/s Transcarb Tel: 62876666

of No. 2 Amic St 63

Policy No: _____ Claim No: GBH 8726X

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 12/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 2:37pm 15/11/19 Person Contacted: Candy Vehicle IN OUT

Date/Time	Action/Instruction	Estimated
	<u>SHB 7829A - (03/Nov/19) 7003324/Kwb392</u>	<u>Time/Pl: Acc</u>
	<u>GBH 8726X - X</u>	
<u>19/11/19</u>	<u>@ 9:44am Jenny said use OI vehicle as claim number.</u>	

ASS. REC. BY:

REF: U02/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s Taxi Cab

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: PHB 7829A Yr Regn: 07/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toy Prox c.c. 1798

Colour MP White / Red A/C: Insured / Std / NI / NA

Sp. Reading 07.084 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU 603082216

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Sailun 195/65R15

R: Yoko

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mm

R/Bal. 8 mm

L/Bal. 9 mm

L/Bal. 8 mm

D.O.A. 12/11/19

D.O.A. 13/11/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

18/11/19 @ 4651.63 (Recd 33,471.75 RTD Confirmed by email)

RECEIVED 19 NOV 2019

Date/Time, File Pass to?

: Prell. Report
 : Final Report

Days Of Repair: 3

Resurvey No. of Trip: _____

28 x 25 = 700

Date/Time, File Return to?

1) _____
2) 19/11 - typist

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee: _____
Transportation: _____
S + RS, SI _____
Fees _____
Others _____

250 + 700
60
19
580
TOTAL 19/11/19
1029

Report Format : TP

Lump Sum / I.B.I. (\$) 4651.63

TOTAL

Veron Chen (LKKAuto)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Monday, 18 November 2019 1:04 PM
To: Veron Chen (LKKAuto)
Cc: SUR
Subject: RE: ARRANGE FOR SURVEY SHB7829A

Dear Veron,

We have yet to create the claim

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Monday, 18 November, 2019 11:45 AM
To: LEW JENNY <jennylew@uoi.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: ARRANGE FOR SURVEY SHB7829A

Dear Jenny,

Please provide claim number.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 15 November 2019 2:56 PM
To: 'LEW JENNY' <jennylew@uoi.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: ARRANGE FOR SURVEY SHB7829A

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: LEW JENNY [mailto:jennylew@uoi.com.sg]

Sent: Friday, 15 November 2019 2:08 PM

To: Zhe Wei <zhewei.kek@transcab.com.sg>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: 'Candy Kong' <candy.kong@transcab.com.sg>

Subject: FW: ARRANGE FOR SURVEY SHB7829A

WITHOUT PREJUDICE

Dear Zhe Wei,

We will appoint LKK as requested.

Dear Shiau Chan,

Please arrange to survey the vehicle.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909 Main . (65) 6222

7733 | DID . (65) 6490 9329 | Fax . (65) 6327 3869 | Email .

jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

-----Original Message-----

From: Zhe Wei [mailto:zhewei.kek@transcab.com.sg]

Sent: Friday, 15 November, 2019 12:04 PM

To: LEW JENNY <jennylew@uoi.com.sg>

Cc: 'Candy Kong' <candy.kong@transcab.com.sg>

Subject: RE: ARRANGE FOR SURVEY SHB7829A

Hi Jenny,

Please arrange for survey as below :

GBH8726X - 12.11.2019 AT 1720Hrs - SHB7829A

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

Best Regards,
Kek Zhewei
Claims Officer

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

This email has been checked for viruses by AVG.
<https://www.avg.com>

Nivitha (LKK Auto)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Friday, 15 November 2019 2:08 PM
To: Zhe Wei; SUR; assignments
Cc: 'Candy Kong'
Subject: FW: ARRANGE FOR SURVEY SHB7829A
Attachments: img-Y15115716.zip

WITHOUT PREJUDICE

Dear Zhe Wei,

We will appoint LKK as requested.

Dear Shiau Chan,

Please arrange to survey the vehicle.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909 Main . (65) 6222 7733 | DID . (65) 6490 9329 | Fax . (65) 6327 3869 | Email . jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

-----Original Message-----

From: Zhe Wei [mailto:zhewei.kek@transcab.com.sg]
Sent: Friday, 15 November, 2019 12:04 PM
To: LEW JENNY <jennylew@uoi.com.sg>
Cc: 'Candy Kong' <candy.kong@transcab.com.sg>
Subject: RE: ARRANGE FOR SURVEY SHB7829A

Hi Jenny,

Please arrange for survey as below :

GBH8726X - 12.11.2019 AT 1720Hrs - SHB7829A

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

Best Regards,
Kek Zhewei
Claims Officer

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

This email has been checked for viruses by AVG.
<https://www.avg.com>

Veron Chen (LKKAuto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Monday, 18 November 2019 2:54 PM
To: Veron Chen (LKKAuto)
Cc: SUR; jasminetan@transcab.com.sg
Subject: FW: SHB 7829A-DOA: 12/11/2019 -- AAD1911-112
Attachments: MARKING.pdf

WITHOUT PREJUDICE

Dear Veron

Amount confirmed \$ 4,651.63 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Monday, 18 November, 2019 11:44 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; SUR <sur@lkkauto.com>
Cc: jasminetan@transcab.com.sg
Subject: SHB 7829A-DOA: 12/11/2019

Dear Wai Yin,

WITHOUT PREJUDICE

Finalize amount \$4651.63 @ 3 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHB7829A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2C37601
Chassis No.:	JTDKKB3FU603082216
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	18 Jul 2019
First Registration Date:	18 Jul 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jul 2027
PARF Rebate Amount:	\$10,685.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$24,410.00
COE Rebate Amount:	\$19,528.00
Total Rebate Amount:	\$30,213.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 13 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/11/2019 09:59
Date Of Accident	12/11/2019 17:20
Exact Location Of Accident	UPPER SERANGOON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB7829A
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.8 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P2203857
Cover Note Number	

Driver

Name of Driver	NG HOCK KIM
NRIC No	S1397254J
Date Of Birth	11/04/1959
Occupation	OUTDOOR
Date Of Driving Pass	04/05/1979
Driving Experience	40 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97296768
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 207B COMPASSVALE LANE #06-22
Postcode	543207
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 12/11/2019 AT ABOUT 1720HRS, I WAS TRAVELLING STRAIGHT ALONG THE SECOND LANE OF UPPER SERANGOON ROAD. THE VEHICLES IN FRONT OF ME STOPPED AND I FOLLOWED SUIT. SUDDENLY I FELT AN IMPACT FROM THE REAR OF MY TAXI. VEHICLE B(GBH8726X) HAS FAILED TO STOP IN TIME AND COLLIDED ONTO THE REAR PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH8726X
Vehicle Make/Model/Colour	LORRY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	NG HOCK KIM
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHB7829A
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GFA Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7829A

AAD1911-112

*Not Authorized
Presumptive B4 painting*

84651.63

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

15/11/2019

SHB 7829A

JTDKB3FU603082216

TOYOTA

PRIUS

12.11.19

UOI

18/7/2019

		PART		LIST	
1	1	REAR BUMPER	\$	<i>BU</i> 442.60	✓
2	1	REAR BUMPER RE-INFORCEMENT	\$	<i>BU</i> 332.70	✓
3	1	REAR BUMPER TOWING COVER	\$	<i>SL</i> 15.40	X
4	1	REAR BUMPER UNDER COVER (BLACK)	\$	<i>CM</i> 576.30	✓
5	1	REAR BUMPER SIDE RETAINER LH	\$	<i>SL</i> 116.50	X
6	1	REAR BUMPER SIDE RETAINER RH	\$	<i>SL</i> 117.70	X
7	1	SEAL, REAR BUMPER SIDE, LH	\$	<i>SL</i> 88.50	X
8	1	SEAL, REAR BUMPER SIDE, RH	\$	<i>SL</i> 88.50	X
9	1	REAR TAILGATE	\$	<i>R</i> 1,147.80	X
10	1	REAR TAILGATE OUTER GARNISH	\$	<i>CM</i> 925.60	✓
11	1	ANTENNA, ELECTRICAL KEY	\$	<i>SL</i> 72.00	} X
12	1	COVER, REAR COMBINATION LAMP, RH	\$	<i>SL</i> 64.50	
13	1	COVER, REAR COMBINATION LAMP, LH	\$	<i>SL</i> 64.50	
14	1	GARNISH, BACK DOOR SIDE, LH	\$	<i>SL</i> 95.60	
15	1	GARNISH, BACK DOOR SIDE, RH	\$	<i>SL</i> 95.60	
16	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	<i>SL</i> 56.50	
17	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	<i>SL</i> 56.50	
18	1	BOARD ASSY, BACK DOOR TRIM	\$	<i>SL</i> 259.20	
19	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>SL</i> 52.10	
20	1	REAR TAILGATE WEATHERSTRIP	\$	<i>SL</i> 372.30	
21	1	STRIKER ASSY, BACK DOOR LOCK	\$	<i>R</i> 25.80	
22	1	COVER, BACK DOOR LOCK	\$	<i>R</i> 30.20	
23	1	LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH	\$	<i>SL</i> 467.00	
24	1	SPOILER, SUB ASSY, REAR	\$	<i>CM</i> 1,575.40	✓
25	1	LAMP SUB ASSY, LICENSE PLATE	\$	<i>SL</i> 287.80	X
26	1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>R</i> 650.30	X
27	1	TAILLAMP LOWER RH	\$	<i>SL</i> 502.00	X

Trans-cab Auto Services Pte Ltd

AAD1911-112

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7829A

28	1	TAILLAMP UPPER RH	\$	Su	451.80	X
29	1	REAR BUMPER SIDE RH	\$	Su	123.70	X
30	1	REAR BUMPER SIDE LH	\$	ng/cm	123.70	✓
31	1	TAILLAMP LOWER LH	\$	Su	502.00	} X
32	1	TAILLAMP UPPER LH	\$	Su	443.30	
33	1	REAR FENDER LH	\$	R	854.80	
34	1	LINER, REAR WHEEL HOUSE, LH	\$	R	139.80	
35	1	DUCT ASSY, QUARTER VENT, LH	\$	Su	67.00	
36	1	DUCT ASSY, QUARTER VENT, RH	\$	Su	67.00	
37	1	BOARD, BACK DOOR TRIM	\$	Su	225.20	
38	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	Su	355.90	
39	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	Su	355.90	
40	1	COVER, FLOOR UNDER, NO.1	\$	Su	175.10	
41	1	COVER, FLOOR UNDER, NO.2	\$	Su	241.90	
42	1	COVER, REAR FLOOR	\$	Su	229.90	
43	1	COVER, DECK TRIM, REAR	\$	Su	126.70	
44	1	BOARD, REAR FLOOR, NO.1	\$	Su	519.00	
45	1	BOX, DECK FLOOR, RH	\$	Su	313.60	
46	1	BOX, DECK FLOOR, LH	\$	Su	313.00	
47	1	BOX, DECK FLOOR, REAR	\$	Su	105.80	
48	1	PAN, REAR FLOOR	\$	R	583.40	
49	1	EXTENSION, REAR FLOOR SIDE PANEL, RH	\$	Su	78.30	
50	1	EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	\$	Su	196.50	
51	1	EXTENSION, REAR FLOOR SIDE PANEL, LH	\$	Su	78.30	
52	1	EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	\$	Su	196.50	
53	1	PIPE ASSY, EXHAUST, TAIL	\$	R	1,655.40	
54	1	SUPPORT, EXHAUST PIPE, NO.4	\$	Su	49.10	
55	1	SUPPORT, EXHAUST PIPE, NO.5	\$	Su	49.10	
56	1	GASKET, EXHAUST PIPE	\$	Su	53.50	
57	1	TROUGH, BACK DOOR OPENING, RH	\$	Su	103.40	
58	1	TROUGH, BACK DOOR OPENING, LH	\$	Su	103.40	
59	1	CARRIER, SPARE WHEEL, NO.1	\$	Su	20.80	
TOTAL			\$		17,481.70	
25%			\$		4,370.43	
			\$		13,111.28	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7829A**AAD1911-112****SPECIAL NETT**

1	1SET PARKING AID	\$	Per 700.00	X
2	1SET REAR BUMPER CLIP	\$	na 66.00	✓
3	2 REAR WINDSCREEN SEALANT	\$	na 80.00	X
4	1 WINDSCREEN MOULDING	\$	na 100.00	X
5	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na 100.00	X
6	1 REAR TAILGATE TOYOTA LOGO	\$	na 47.00	✓
7	1 REAR TAILGATE WORDING 'PRIUS'	\$	na 52.90	✓
8	1 REAR TAILGATE WORDING 'HYBRID'	\$	na 53.50	✓
9	1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	na 80.00	30na
10	1 REAR TAILGATE STICKER '6555-3333'	\$	na 80.00	30na
11	1 REAR BUMPER PROTECTOR	\$	na 100.00	40na
12	1 REAR WHEEL RIM	\$	Per 1,570.55	} X
13	1 REAR WHEEL RIM COVER	\$	Per 175.80	
14	1 SPARE WHEEL RIM	\$	Per 1,570.55	
15	1 SPARE WHEEL RIM COVER	\$	Per 175.80	
16	1SET REAR RH FENDER LINER CLIP	\$	na 35.00	
17	1 REAR TYRE 195/65/15	\$	Per 350.00	
18	1 REAR NUMBER PLATE WITH MOULDING	\$	Per 200.00	
19	1 SPARE TYRE 195/65/15	\$	Per 350.00	
20	1SET REAR BUMPER RETAINER LH CLIP	\$	na 20.00	
21	1SET REAR BUMPER RETAINER RH CLIP	\$	na 20.00	
22	1SET REAR LH FENDER LINER CLIP	\$	na 35.00	
TOTAL		\$	5,962.10	

TOTAL PARTS \$ 19,073.38**LABOUR**

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	na 170.00	X
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	60/

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7829A**AAD1911-112**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	500
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	500
Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	720
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	200
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7829A

AAD1911-112

To drop rear exhaust box, renew the same, to repair and
realign centre exhaust pipe. \$ *~* 170.00 X

To repair and realign rear exhaust pipe. \$ *~* 170.00 X

To drop petrol tank, pipes, hoses and renew the necessary
parts and final checking and testing for leak. \$ *~* 440.00 X

TOTAL \$ 19,050.00

Over All Total \$ 38,123.38

(PART-BY-PART) Repair Days **25 Days**
3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
UNITED OVERSEAS INSURANCE LTD		Ref : CS/UOI19020319/Kvd3n2	
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909		Date : 20-11-2019	
		Code : UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBH 8726X	Veh. Inspected	SHB 7829A
Policy No.		Coverage (\$)	0.00
Claim No.	GBH 8726X	Excess (\$)	0.00
Assign From	JENNY LEW	Assign Date	15/11/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTDKB3FU603082216	Colour	M.P.WHITE / RED
Odometer	67084	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	SAILUN	9 mm
L/H Front Tyre	195/65 R15	SAILUN	9 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/11/2019	Inspection Date	15/11/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 7829A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BUCKLED	442.60	442.60
1	REAR BUMPER RE-INFORCEMENT	BENT	332.70	332.70
1	REAR BUMPER TOWING COVER	SERVICEABLE	15.40	-
1	REAR BUMPER UNDER COVER (BLACK)	CRACKED	576.30	576.30
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	116.50	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	117.70	-
1	SEAL,REAR BUMPER SIDE,LH	SERVICEABLE	88.50	-
1	SEAL,REAR BUMPER SIDE,RH	SERVICEABLE	88.50	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,147.80	-
1	REAR TAILGATE OUTER GARNISH	CRACKED	925.60	925.60
1	ANTENNA,ELECTRICAL KEY	SERVICEABLE	72.00	-
1	COVER,REAR COMBINATION LAMP,RH	SERVICEABLE	64.50	-
1	COVER,REAR COMBINATION LAMP,LH	SERVICEABLE	64.50	-
1	GARNISH,BACK DOOR SIDE,LH	SERVICEABLE	95.60	-
1	GARNISH,BACK DOOR SIDE,RH	SERVICEABLE	95.60	-
1	MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER RH	SERVICEABLE	56.50	-
1	MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER LH	SERVICEABLE	56.50	-
1	BOARD ASSY,BACK DOOR TRIM	SERVICEABLE	259.20	-
1	PANEL ASSY,BACK DOOR TRIM,UPPER	SERVICEABLE	52.10	-
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	372.30	-
1	STRIKER ASSY,BACK DOOR LOCK	TO REPAIR SEE LABOUR	25.80	-
1	COVER,BACK DOOR LOCK	TO REPAIR SEE LABOUR	30.20	-
1	LOCK ASSY,BACK DOOR,W/COURTESY LAMP SWITCH	SERVICEABLE	467.00	-
1	SPOILER SUB ASSY,REAR	CRACKED	1,575.40	1,575.40
1	LAMP SUB ASSY,LICENSE PLATE	SERVICEABLE	287.80	-
1	PANEL SUB-ASSY,BODY LOWER BACK	TO REPAIR SEE LABOUR	650.30	-
1	TAILLAMP LOWER RH	SERVICEABLE	502.00	-
1	TAILLAMP UPPER RH	SERVICEABLE	451.80	-
1	REAR BUMPER SIDE RH	SERVICEABLE	123.70	-
1	REAR BUMPER SIDE LH	MTG CRACKED	123.70	123.70
1	TAILLAMP LOWER LH	SERVICEABLE	502.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILLAMP UPPER LH	SERVICEABLE	443.30	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	854.80	-
1	LINER,REAR WHEEL HOUSE,LH	TO REPAIR SEE LABOUR	139.80	-
1	DUCT ASSY,QUARTER VENT,LH	SERVICEABLE	67.00	-
1	DUCT ASSY,QUARTER VENT,RH	SERVICEABLE	67.00	-
1	BOARD,BACK DOOR TRIM	SERVICEABLE	225.20	-
1	PANEL ASSY,DECK TRIM SIDE,RH	SERVICEABLE	355.90	-
1	PANEL ASSY,DECK TRIM SIDE,LH	SERVICEABLE	355.90	-
1	COVER,FLOOR UNDER,NO.1	SERVICEABLE	175.10	-
1	COVER,FLOOR UNDER,NO.2	SERVICEABLE	241.90	-
1	COVER,REAR FLOOR	SERVICEABLE	229.90	-
1	COVER,DECK TRIM,REAR	SERVICEABLE	126.70	-
1	BOARD,REAR FLOOR,NO.1	SERVICEABLE	519.00	-
1	BOX,DECK FLOOR,RH	SERVICEABLE	313.60	-
1	BOX,DECK FLOOR,LH	SERVICEABLE	313.00	-
1	BOX,DECK FLOOR,REAR	SERVICEABLE	105.80	-
1	PAN,REAR FLOOR	TO REPAIR SEE LABOUR	583.40	-
1	EXTENSION,REAR FLOOR SIDE PANEL,RH	SERVICEABLE	78.30	-
1	EXTENSION,REAR FLOOR PAN TO QUARTER PANEL,RH	SERVICEABLE	196.50	-
1	EXTENSION,REAR FLOOR SIDE PANEL,LH	SERVICEABLE	78.30	-
1	EXTENSION,REAR FLOOR PAN TO QUARTER PANEL,LH	SERVICEABLE	196.50	-
1	PIPE ASSY,EXHAUST,TAIL	TO REPAIR SEE LABOUR	1,655.40	-
1	SUPPORT,EXHAUST PIPE,NO 4	SERVICEABLE	49.10	-
1	SUPPORT,EXHAUST PIPE,NO 5	SERVICEABLE	49.10	-
1	GASKET,EXHAUST PIPE	SERVICEABLE	53.50	-
1	TROUGH,BACK DOOR OPENING,RH	SERVICEABLE	103.40	-
1	TROUGH,BACK DOOR OPENING,LH	SERVICEABLE	103.40	-
1	CARRIER,SPARE WHEEL,NO 1	SERVICEABLE	20.80	-
	LESS 25% DISCOUNT		-4,370.42	-994.07
			13,111.28	2,982.23
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	REAR TAILGATE TOYOTA LOGO (SN)	NECESSARY	47.00	47.00
1	REAR TAILGATE WORDING "PRIUS" (SN)	NECESSARY	52.90	52.90
1	REAR TAILGATE WORDING "HYBRID" (SN)	NECESSARY	53.50	53.50
1	REAR TAILGATE STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	30.00
1	REAR TAILGATE STICKER "6555-3333" (SN)	NECESSARY	80.00	30.00
1	REAR BUMPER PROTECTOR (SN)	NECESSARY	100.00	40.00
1	REAR WHEEL RIM (SN)	SERVICEABLE	1,570.55	-
1	REAR WHEEL RIM COVER (SN)	SERVICEABLE	175.80	-
1	REAR WHEEL RIM (SN)	SERVICEABLE	1,570.55	-
1	REAR WHEEL RIM COVER (SN)	SERVICEABLE	175.80	-
1	SET REAR RH FENDER LINER CLIP (SN)	NOT NECESSARY	35.00	-
1	REAR TYRE 195/65/15 (SN)	SERVICEABLE	350.00	-
1	REAR NUMBER PLATE WITH MOULDING (SN)	SERVICEABLE	200.00	-
1	SPARE TYRE 195/65/15 (SN)	SERVICEABLE	350.00	-
1	SET REAR BUMPER RETAINER LH CLIP (SN)	NOT NECESSARY	20.00	-
1	SET REAR BUMPER RETAINER RH CLIP (SN)	NOT NECESSARY	20.00	-
1	SET REAR LH FENDER LINER CLIP (SN)	NOT NECESSARY	35.00	-
			5,962.10	319.40
	LABOUR			
	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR TAILGATE, STRIKER ASSY, BACK DOOR LOCK, COVER, BACK DOOR LOCK, PANEL SUB-ASSY, BODY LOWER BACK, REAR FENDER LH, LINER, REAR WHEEL HOUSE, LH, PAN, REAR FLOOR AND PIPE ASSY, EXHAUST, TAIL.		7,500.00	500.00
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-

Report Ref No. CS/UOI19020319/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	50.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		7,500.00	720.00
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP PETROL TANK, PIPES, HOSES AND RENEW THE NECESSARY PARTS AND FINAL CHECKING AND TESTING FOR LEAK.	NOT NECESSARY	440.00	-
			19,050.00	1,350.00
GRAND TOTAL			38,123.38	4,651.63
RECOMMENDED COST OF REPAIRS				4,651.63

Report Ref No. CS/UOI19020319/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.