

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Gan, Hunchung

Date: 18 Nov 2019

## **Preliminary Advice**

Vehicle No	: SMG1305Z	Accident Date	: 07/11/2019
Make	: SUBARU FORESTER	Policy No.	: 1800145373
Assignment Date	: 18/11/2019	Excess	: S\$800.00
Date of Inspection	: 18/11/2019	Est. Duration of Repair	: 3 days
Inspection At	: Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh Singapore 319255		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,161.60
Revised Amount	:S\$	1,390.00
Check Items (Estimated)	:S\$	3,264.00
Total	:S\$	4,654.00

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	90,000.00
COE / PARF Rebate	:S\$	38,329.00
Salvage Value	:S\$	
Margin for Repair	:S\$	51,671.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :