

ASS. REC. BY:

REF:

CS/INC19020361/Evd3

Special Instruction:

Assigner: Heve

ASSIGNMENT (Office)

From (Person): Hazelisa B Ibrahim

of INC

Date/Time: 18/11/19 10:02am

Estimated Cost:

Bill to:

OD TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 5498S

Insured:

SLB 290B

at Workshop m/s

Weurves Automotive

Tel:

98187217

of

249 Alexandra Road

Policy No:

Claim No:

MT/1069720-002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

2/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time:

10:40am 18/11/19

Person Contacted:

Derek

Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>18/11/19</u>
	<u>SLT 5498S - X</u>
	<u>SLB 290B - X</u>

ASS. REQ. BY:

Steve

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No

SLT 5498S

Yr Regn:

31/10/17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Kadjar

c.c

1461

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

39283

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VFIRFE00756824017

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

225/45R19

R:

1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

2/11/19

D.O.I.

18/11/19

Survey held at

WARRIS

2.06pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/11/19 MV-7815
Finalbe conf. \$4610.98, 3 days (Richmond) (Red 4071.42, 4719)

RECEIVED 28 NOV 2019

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 28/11 - typist

Rep. Formed:

TP

Lump Sum / REP: /

4610.98

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

250

Nivitha (LKK Auto)

From: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Sent: Monday, 18 November 2019 10:02 AM
To: Admin-D (LKKAuto); assignments
Cc: Susan Ting; Hazalya Binte Ibrahim
Subject: TP CASES FARMED OUT TO LKK ON 18/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Serene Lim	MT/1071241-002	CB7507M	CT AUTO PTE LTD	10 BUKOH STREET #01-31 WEST CONNECT BUILDING SINGAPORE 627564	Daniel Tan/Cady Lee / 9353 3333	13:00-14:30	SJ13362P	08/11/19	owner waiting/6266-6727
2	Eng Huey Huey	MT/1071557-001	5FE22D	HIN LUNG WORKSHOP	BLK 1008 #01-20 BUKIT MERAH LANE 3 SINGAPORE 159722	Anna / 6858 3000	10:00-12:00	FV1933P	13/11/19	
3	Helena Tan	MT/1070807-002	GBD2836Y	MOTORWAY CAR CARE CENTRE PTE LTD	1094 LOWER DELTA ROAD MOTORWAY BUILDING SINGAPORE 169205	Annie Tew / 6571 9642		PC5664X	10/11/19	
4	Chryllis Quah	MT/1071066-002	GBE9864P	SIN SHENG ENGINEERING SERVICES	NO 8 TUAS AVENUE 18, #05-00 SINGAPORE 638892	Susan / 68639595		YM7508S	07/11/19	68636477
5	Azhari	MT/1069720-002	SLT5498S	WEARNES AUTOMOTIVE PTE LTD	249 ALEXANDRA ROAD SINGAPORE 159935	Derek Oh / 9818 72176	10:00-12:00	5LB290B	02/11/19	6430 4895
6	Helena Tan	MT/1068626-002	SMD1010P	WEARNES AUTOMOTIVE PTE LTD	249 ALEXANDRA ROAD SINGAPORE 159935	Derek Oh / 9818 72176	10:00-12:00	5DL7722T	25/10/19	6430 4895

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 134E

Vehicle Details

Vehicle No.: SLT54985
Vehicle to be Exported: No
Intended Deregistration Date: 18 Nov 2019
Vehicle Make: RENAULT
Vehicle Model: KADJAR 1.5 DCI EDC 6AT S&S EU6
Primary Colour: Black
Manufacturing Year: 2016
Engine No.: K9KF647D057841
Chassis No.: VF1RFE00756824017
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$25,631.00
Original Registration Date: 31 Oct 2017
First Registration Date: 31 Oct 2017
Transfer Count: 0
Actual ARF Paid: \$12,884.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 30 Oct 2027
PARF Rebate Amount: \$9,663.00

Intended COE Rebate Details

COE Expiry Date: 30 Oct 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$41,761.00
COE Rebate Amount: \$33,195.00
Total Rebate Amount: \$42,858.00

The information contained herein is correct as at 18 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/11/2019 19:43
Date Of Accident	02/11/2019 12:05
Exact Location Of Accident	PIE LANE 1 LAMP POST 724A EXIT 16A
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT5498S
Insured/Policyholder	
Name Of Registered Owner	CHAN WEI KEONG FRANCIS
NRIC No	S1803134E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94500485
Alternative Phone No	OTHERS-94500485

Vehicle Particulars

Manufacturer	RENAULT
Model	KADJAR-1.5 DCI (M)
Exact Purpose for which vehicle was being used at time of accident	SOCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD19V13040
Cover Note Number	

Driver

Name of Driver	CHAN WEI KEONG FRANCIS
NRIC No	S1803134E
Date Of Birth	17/11/1967
Occupation	INDOOR
Date Of Driving Pass	16/09/1985
Driving Experience	34 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-94500485
Fax Number	
Contact Number	OTHERS-94500485
Email Address	NOEMAIL

Address	233 SIMEI ST 4 #09-162
Postcode	520233
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : ISAAC GENDER: : MALE
Passenger 2	NAME: : MEI KUEN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB290B
Vehicle Make/Model/Colour	NISSAN SYLPHY / RED
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM SENG HIN STEVEN
NRIC/Passport Number	S1509557A
Contact Number	98233669
Address	
Postcode	

Insurance Company Name

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Nature Of Damage

No. Of Passenger (including Driver)

2

Passenger 1

NAME: : UNKNOWN

GENDER: : MALE

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing w ith my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying w ith applicable law in administering, processing, handling and/or dealing w ith my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstance of the Accident

I was on my way home traveling along PIE. My wife and my son ~~was~~ in the car together. After entering into PIE from BKE, I progressively filter to lane 1. When I was near Steven Road Exit, I noticed a few cars ahead of me brake abruptly. Therefore, I make extra precaution, to give enough braking distance. As I entered the stretch of road (Jalan Toa Payoh). due to the volume of vehicles on the road, I reduce my speed to approximately 73km/h. As I ~~reached~~ come near toward Exit 16A, the 5th car in front ~~to~~ Brake abruptly again. As I have kept a good distance ~~from~~ from the car in front of me, I was managed to stop in time. However the car behind me (SLB290B) could not stopped in time and hit the back of my vehicle. Both cars suffered some damaged both were able to continue the rest of the journey after exchanging drivers' details.


It cause an accident between the 5th and 4th car in front. Car 3rd, 2nd and 1st (the car in front of mine) stopped in time to avoid accident.

IMPORTANT NOTE

Under General Condition – Conduct of Claim of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature | Date & Time
4/11/19
1:20 pm


Driver's Signature (if driver is not the policyholder) / Date & Time
4/11/19
1:20 pm

Witnessed by Reporting Centre Personnel

SERVICE ESTIMATE

93627 - C00001 SL: SERVICE SALES - PC

Mr Chan Wei Keong Francis
BLK 233 Simei Street 4
#09-162

Singapore 520233

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Chan Wei Keong Fr

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 06/11/2019

WIP No. . : 46046

Veh.In/Out: 04/11/2019

*Tel.No. . : Mobile: 94500485

Reg.No. . : SLT5498S

Reg.date . : 31/10/2017

Mileage ... : 0

Chassis No: VF1RFE00756824017

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BUMPER, REAR BRACKET, REAR LOWER SPOILER, REAR SENSOR, ETC	450	0	1350.00	0	1,350.00 S	675
-----	--	-----	---	---------	---	------------	-----

800	TO PUTTY SPRAY PAINT ON REAR BUMPER, ETC	400	0	800.00	0	800.00 S	X (New cap pad photo)
-----	--	-----	---	--------	---	----------	-----------------------

R06	TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER		0	60.00	0	60.00 S	/
-----	---	--	---	-------	---	---------	---

280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES		0	360.00	0	360.00 S	/
-----	---	--	---	--------	---	----------	---

BUMPER REAR (E2S)	1.0 EA	847.20	847.20 S	762.48
BUMPER REAR TRIM RH	1.0 EA	589.90	589.90 S	
BUMPER REAR TRIM LH	1.0 EA	409.90	409.90 S	
BUMPER RETAINER RR L	1.0 EA	33.20	33.20 S	
BUMPER RETAINER RR R	1.0 EA	33.20	33.20 S	
BRACKET SUPPORT, BUM	1.0 EA	27.80	27.80 S	
BRACKET SUPPORT, BUM	1.0 EA	27.80	27.80 S	

Signature
19/11/19

Steve (LKK) with trial 18/11/19, 2.30 pm

P/P

Ry Ref spy

3 dy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SERVICE ESTIMATE

93627 - C00001 SL: SERVICE SALES - PC

Mr Chan Wei Keong Francis
BLK 233 Simei Street 4
#09-162

Singapore 520233

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Chan Wei Keong Fr

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 06/11/2019

WIP No. . : 46046

Veh.In/Out: 04/11/2019

*Tel.No. . : Mobile: 94500485

Reg.No. . : SLT5498S

Reg.date. : 31/10/2017

Mileage . : 0

Chassis No: VF1RFE00756824017

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

BUMPER LOWER CTR SUP	MC	3.0 EA	29.20			87.60 S	76.84
RIVET G4,8- M4S KJ	MC	10.0 EA	5.90			59.00 S	53.10
TOW COVER REAR KJ	X NN	1.0 EA	47.30			47.30 S	
FOG LAMP REAR LH KJ	X NN	1.0 EA	231.10			231.10 S	
FOG LAMP REAR RH KJ	X NN	1.0 EA	323.80			323.80 S	
PARKING SENSOR FRT/B	X NN	2.0 EA	199.80			399.60 S	
PARK SENSOR BOTH CTR	X NN	2.0 EA	429.90			859.80 S	773.82
REINFORCEMENT RR	X NN	1.0 EA	439.50			439.50 S	395.55
ADHESIVE SEALER FL2	X NN	1.0 EA	669.10			669.10 S	602.19
PRIMER	X NN	1.0 EA	176.60			176.60 S	

8682.40

Gross Total. 7,832.40

Labour Total	2,570.00
Parts Total	5,262.40
Package Total	0.00

Net.....	7,832.40
GST @ 7.0%	548.27
Total.....	8,380.65
Paid.....	0.00
Please Pay..	8,380.65

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - N00001 SL: NTUC INCOME INSURANCE CO-OPERATIVE
 NTUC INCOME INSURANCE CO-OPERATIVE GST Reg.No:M28920628X
 73 Bras Basah Inv.No. : B&P 0 Page 1
 #05-01 Inv.date. : 27/11/2019
 NTUC Trade Union House WIP No. : 46046
 Singapore 189556 Veh.In/Out: 16/11/2019 27/11/2019
 *Tel.No. :
 Reg.No. : SLT5498S
 Closed by : Richmond Ho Reg.date : 31/10/2017
 Svc Consultant : Mileage .. : 0
 Remarks : Mr Chan Wei Keong Pr Chassis No: VF1RFE00756824017

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR	0	675.00	0		675.00	S
	BRACKET, REAR LOWER SPOILER,						
	REAR SENSOR, ETC						
R06	TO INSTALL REAR NUMBER PLATE	0	60.00	0		60.00	S
	INCLUDE HOLDER						
280	TO CHECK WIRING INCLUDE	0	360.00	0		360.00	S
	RESETTING OF ALL ELECTRICAL						
	MODULES						
802	TO REPAIR END PANEL	0	450.00	0		450.00	S
800	TO PUTTY SPRAY PAINT ON REAR	0	400.00	0		400.00	S
	END PANEL						
	BUMPER REAR (E2S) ①	1.0 EA	847.20	10		762.48	S
	BUMPER LOWER CTR SUP ⑤	3.0 EA	29.20	10		78.84	S
	RIVET G4, 8- M4S KJ ⑦	10.0 EA	5.90	10		53.10	S
	PARK SENSOR BOTH CTR ④	2.0 EA	429.90	10		773.82	S
	ADHESIVE SEALER FL2 ⑪	1.0 EA	669.10	10		602.19	S
	REINFORCEMENT RR ⑬	1.0 EA	439.50	10		395.55	S

Gross Total. 4,610.98

Labour Total 1,945.00
 Parts Total 2,665.98
 Package Total 0.00

Net..... 4,610.98
 GST @ 7.0% 322.77
 Total..... 4,933.75
 Paid..... 0.00
 Please Pay.. 4,933.75

GST: S=StdRated; O=OutOfScope; Z=ZeroRated



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19020361/Evd3n2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 28-11-2019



ATTN: AZHARI

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLB 290B	Veh. Inspected	SLT 5498S
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1069720-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	18/11/2019

2. Vehicle Particulars & Condition

Make & Model	RENAULT KADJAR	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VF1RFE00756824017	Colour	BLACK
Odometer	39283 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R19	CONTINENTAL	6 mm
L/H Front Tyre	225/45 R19	CONTINENTAL	6 mm
R/H Rear Tyre	225/45 R19	CONTINENTAL	6 mm
L/H Rear Tyre	225/45 R19	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/11/2019	Inspect Date / Time	18/11/2019 (02:06 PM)
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 5498S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER REAR (E2S)(SN)	CUT	847.20	762.48
1	BUMPER REAR TRIM RH (SN)	NOT NECESSARY	589.90	-
1	BUMPER REAR TRIM LH (SN)	NOT NECESSARY	409.90	-
1	BUMPER RETAINER RR L (SN)	NOT NECESSARY	33.20	-
1	BUMPER RETAINER RR R (SN)	NOT NECESSARY	33.20	-
1	BRACKET SUPPORT,BUM (SN)	NOT NECESSARY	27.80	-
1	BRACKET SUPPORT,BUM (SN)	NOT NECESSARY	27.80	-
3	BUMPER LOWER CTR SUP (SN)	NECESSARY	87.60	78.84
10	RIVET G4,8-M4S KJ (SN)	NECESSARY	59.00	53.10
1	TOW COVER REAR KJ (SN)	NOT NECESSARY	47.30	-
1	FOG LAMP REAR LH KJ (SN)	NOT NECESSARY	231.10	-
1	FOG LAMP REAR RH KJ (SN)	NOT NECESSARY	323.80	-
2	PARKING SENSOR FRT/B (SN)	NOT NECESSARY	399.60	-
2	PARK SENSOR BOTH CTR (SN)	SHORTED	859.80	773.82
1	REINFORCEMENT RR (SN)	DENTED	439.50	395.55
1	ADHESIVE SEALER FL2 (SN)	NECESSARY	669.10	602.19
1	PRIMER (SN)	NOT NECESSARY	176.60	-
			5,262.40	2,665.98
	LABOUR			
	TO REPLACE REAR BUMPER,REAR BRACKET,REAR LOWER SPOILER,REAR SENSOR,ETC.		1,350.00	675.00
	TO PUTTY SPRAY PAINT ON REAR BUMPER,ETC.	NOT NECESSARY	800.00	-
	TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER.		60.00	60.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		360.00	360.00
	TO REPAIR END PANEL (ADDITIONAL).		450.00	450.00
	TO PUTTY SPRAY PAINT ON REAR END PANEL (ADDITIONAL).		400.00	400.00
			3,420.00	1,945.00
GRAND TOTAL			8,682.40	4,610.98



RECOMMENDED COST OF REPAIRS (CONFIRMED)		4,610.98
---	--	----------

Report Ref No. CS/INC19020361/Evd3n2

CHEN TSUE YEE
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.