



明福汽車服務

MING HOCK MOTOR SERVICE

11 OPAL CRESCENT, SINGAPORE 328406
TEL: 6291 9090 FAX: 6292 2376

9836 5383 No. 28403

SERVICE ESTIMATE

82945 - C00001
Mr Soo Ming Chong
444 Macpherson Road

SL: SERVICE SALES - PC

GST Reg. No: M28020621

Inv. No. : I 0 Page

Inv. date. : 19/11/2014

WIP No. : 48710

Veh. In/Out:

*Tel. No. : Mobile: 98365383

Reg. No. : SMJ3573L

Reg. date. : 28/05/2014

Mileage : 0

Chassis No: JN1TCNS5170570057

Singapore 368155

Closed by : Wong Wai Kit

Svc Consultant :

Remarks : Mr Soo Ming Chong

Op. No	Description	Mech Qty	Price	Disc%	Pkg	Amount
--------	-------------	----------	-------	-------	-----	--------

UC12A1	REINFORCE/SHOCK ABS (ALL) - RP	0 / (labour)	148.50	0		148.50
--------	--------------------------------	--------------	--------	---	--	--------

FD34A4	REAR EXHAUST TUBE & MUFFLER	0	54.00	0		54.00
--------	-----------------------------	---	-------	---	--	-------

Parts - 1168-38

Labr - 148.50

1316-88

L/S - 1053-50

= 1050

BUMPER COVER REAR FX	1.0 EA	1124.80	1,124.80
ENERGY ABSORBER	1.0 EA	173.40	173.40
REINF-BUMPER RR	1.0 EA	809.80	809.80
MUFFLER ASSY	1.0 EA	1360.10	1,360.10

Gross Total. 3,670.60

Net..... 3,670

GST @ 7.0% 256

Total..... 3,927

Paid..... 0

Please Pay.. 3,927

Labour Total 202.50

Parts Total 3,468.10

Package Total 0.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Steve (LKK)

8322 8813

Stevechen@lkkauto.com

with M/L

19/11/14, 2.00pm

2 days

L/S

Ry Def



INFINITI
EMPOWER THE DRIVE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Regn. No.: 337279/00D

E. & O. E.

MING HOCK MOTOR SERVICE