

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

JH1MC2E2620003525

INDOBOX PTE LTD

11 LORONG 21A GEYLANG

#6 LAM THONG BUILDING

S 388429

TPAIG.
Vic

Date

:21.11.2019

Vehicle No

:GBD 7619 A

Make/Model

:NISSAN NV350

Accident date

:12.11.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear tailgate <i>Dented</i>	1	\$ 1998.4 1742
2	Rear tailgate hinges @ \$59.60 <i>new</i>	2	\$ 119.2 X
3	Rear tailgate upper lock <i>Damaged</i>	1	\$ 356.1 ✓
4	Rear tailgate lower lock <i>new</i>	1	\$ 196.4 X
5	Rear tailgate shock absorber @ \$237.50 <i>new</i>	2	\$ 475 +
6	Rear tailgate side lock @ \$60.60	2	\$ 121.2 +
7	Rear tailgate inner side lock @ \$50.60 <i>new</i>	2	\$ 101.2 +
8	Rear tailgate inner board <i>new</i>	1	\$ 242 X
9	Rear tailgate weather strip <i>new</i>	1	\$ 154.9 ✓
10	Rear tailgate centre emblem <i>new</i>	1	\$ 87 ✓
11	Rear tailgate handle <i>new</i>	1	\$ 589.3 +
12	Rear tailgate NV 350 emblem	1	\$ 121 ✓
13	Rear tailgate 70 sticker	1	\$ 29.7 10(SN)
14	Rear tailgate 8 pax sticker	1	\$ 29.7 10(SN)
15	Rear end panel <i>Repr</i>	1	\$ 270.8 X
16	Rear end panel top alum <i>new</i> SN: 20	1	\$ 109 X
17	Rear bumper <i>Dented</i>	1	\$ 733.9 ✓
18	Rear step panel <i>Bent</i>	1	\$ 178.6 ✓
19	Rear lamp @ \$247.30 <i>could</i>	2	\$ 494.6 ✓

Special Nett Items

- 1 Rear bumper reverse sensor (1 set) *Damaged*
- 2 Rear bumper clips (1 set) *new*

	\$ 6408
Less 10% Disc	\$ 640.8
Total	\$ 5767.2
	\$ 380 200
230	\$ 70 30
Total	\$ 450

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

INDOBOX PTE LTD

11 LORONG 21A GEYLANG

#6 LAM THONG BUILDING

S 388429

Date

:21.11.2019

Vehicle No

:GBD 7619 A

Make/Model

:NISSAN NV350

Accident date

:12.11.2019

No	DESCRIPTION	Qty	Amount (S\$)
Labour Cost			
1	To supply rear end panel sealant		\$ 200 x
2	To supply rear windscreen sealant		\$ 50 ✓
3	Remove & reinstall rear windscreen	1880	\$ 150 120
4	Remove & reinstall reverse sensor		\$ 150 50
5	Remove ,replace & repair consistent to the accident		\$ 1800 750
6	Respray painting		\$ 1500 750
7	Tuff kote		\$ 150 80
8	Remove and reinstall upholstery.	150 80	
Total			\$ 4000
Grand Total			\$ 10217.2

total: 5611.29

h/s: A.S.K.

06 Days

4.5K.

06 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: