



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

<b>Type of Claim :</b> <u>TP</u>	Vehicle No. :	<u>GBF8481L</u>
	Make & Model :	<u>NISSAN NV 200 1.5 MT</u>
	Year of Manufacture :	<u>2017</u>
	Chassis No. :	<u>VSKYBAM20Z0138931</u>
Ins Company :	Engine No. :	<u>K9KC400D056310</u>
Excess :	Policy No. :	
Date of Accident :	Time of Accident :	<u>19.30</u>
Suggested Days of Repair :	In-house Vehicle Assessor	

**Repair Estimates**

<b>Parts (a) Cost / List Price Items</b>	<b>\$ 7,750.60</b>
Plus/Less <u>30%</u>	<b>\$ 2,316.18</b>
<b>Total of Cost / List</b>	<b>\$ 7,720.60</b>
<b>(b) Nett Price Items</b>	<b>\$ -</b>
Less _____	_____
<b>Total of Nett Item</b>	_____
<b>(c) Special Nett Items</b>	<b>\$ 30.00</b>
<b>Total Parts Cost (Appendix A)</b>	<b>\$ 7,750.60</b>
<b>Labour (Appendix B)</b>	<b>\$ 3,360.00</b>
<b>Total Repair Cost</b>	<b>\$ 11,110.60</b>

Case Owner : \_\_\_\_\_  
 Signature : \_\_\_\_\_  
 Contact No  
 68438736 – THOMAS

The above total will be subjected to 7% G.S.T.

Name of Surveyor	:	<u>Adrian Ng</u>	<u>96893735</u>
Company	:	<u>LKK</u>	
Survey conducted on	:	<u>18/11/19</u>	at <u>10:45am</u>
<b>Remarks By Surveyor</b>			
(a) The repair of this vehicle is authorized / is not authorized until further notice.			
(b) Recommended Days of Repair	:	<u>04</u>	day(s)
(c) Resurvey	:	<u>Required</u>	Not Required
(d) Excess	:\$	<u>889</u>	
(e) Signature of surveyor	:	<u>[Signature]</u>	Date: <u>18/11/19</u>

# Spark Car Care

ComfortDelGro Engineering Pte Ltd  
320 UBI ROAD 3 SINGAPORE 408649  
TEL :68438723/68438736 Fax:67436072

## Spare Parts

Vehicle No : GBF 8481 L Case Owner : JOHARI  
 Make & Model : NISSAN NV 200 1.5 MT Year Manufacture : 2017  
 Chassis No : VSKYBAM20Z0138931 Engine No : K9KC400D056310  
 Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_  
 Order By : \_\_\_\_\_ Type of Claim : \_\_\_\_\_

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	LHR DOOR <i>dent d</i>	1		\$ 1,983.96	✓ 1545		
2	LHR DOOR HINGE LOWER <i>2</i>	1		\$ 147.81	+		
3	LHR DOOR HINGE UPPER <i>2</i>	1		\$ 147.81	+		
4	LHR DOOR CHECKER	1		\$ 141.75	+		
5	RHR DOOR <i>dent d</i>	1		\$ 1,352.70	✓ 1165		
6	RHR DOOR HINGE LOWER <i>2</i>	1		\$ 147.81	+		
7	RHR DOOR HINGE UPPER <i>2</i>	1		\$ 147.81	+		
8	RHR DOOR CHECKER	1		\$ 141.75	+		
9	REAR DOOR WEATHER STRIP <i>new</i>	1		\$ 150.66	+		
10	REAR DOOR LOCK LH <i>new</i>	1		\$ 188.73	+		
11	REAR DOOR LOCK RH <i>new</i>	1		\$ 188.73	+		
12	NUMBER PLATE LAMP GARNISH <i>new</i>	1		\$ 475.20	+		
13	REAR BUMPER <i>dent d</i>	1		\$ 946.00	✓ 624.80		
14	REAR BUMPER CLIP'S <i>on</i>	10		\$ 56.10	—		
15	REAR BUMPER SIDE BRACKET <i>new</i>	2		\$ 105.60	+		
16	REAR END PANEL OUTER <i>Reps</i>	1		\$ 255.75	+		
17	REAR BUMPER REFLECTOR LAMP <i>new</i>	2		\$ 170.50	+		
18	TAIL LAMP <i>LH cover</i>	2		\$ 598.84	✓ 299.42		
19	EMBLEM <i>2</i>	1		\$ 216.15	✓ 55.30		
20	NV 200 WORDING <i>new</i>	1		\$ 187.00	✓ 79.90		
21	70 KM / H	1				\$ 15.00	✓
22	6 PAX STICKER	1				\$ 15.00	✓
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

3867.10  
3480.39 P.N:30.

## Spark Car Care

ComfortDelGro Engineering Pte Ltd

