



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : GBF8481LMake & Model : NISSAN NV 200 1.5 MTYear of Manufacture : 2017Chassis No. : VSKYBAM20Z0138931

Ins Company : _____

Engine No. : K9KC400D056310

Excess : _____

Policy No. : _____

Date of Accident : 09.11.2019Time of Accident : 19.30

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**

Case Owner : _____

Signature : _____

Contact No : _____

68438736 – THOMAS

Parts (a) Cost / List Price Items \$ 7,750.60Plus/Less 30% \$ 2,316.18Total of Cost / List \$ 7,720.60(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 30.00Total Parts Cost (Appendix A) \$ 7,750.60Labour (Appendix B) \$ 3,360.00Total Repair Cost \$ 11,110.60

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Adrian Lj 96893735Company : LKKSurvey conducted on : 18/11/19 at 10:45amRemarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)(c) Resurvey : Required / Not Required(d) Excess : \$ 88.8(e) Signature of surveyor : [Signature] Date: 18/11/19

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : GBF 8481 L Case Owner : JOHARI

Make & Model : NISSAN NV 200 1.5 MT Year Manufacture : 2017

Chassis No : VSKYBAM20Z0138931 Engine No : K9KC400D056310

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : _____

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	LHR DOOR <i>dent d</i>	1		\$ 1,983.96	✓ 1545		
2	LHR DOOR HINGE LOWER <i>2</i>	1		\$ 147.81	+		
3	LHR DOOR HINGE UPPER <i>2</i>	1		\$ 147.81	+		
4	LHR DOOR CHECKER	1		\$ 141.75	+		
5	RHR DOOR <i>dent d</i>	1		\$ 1,352.70	✓ 1165		
6	RHR DOOR HINGE LOWER <i>2</i>	1		\$ 147.81	+		
7	RHR DOOR HINGE UPPER <i>2</i>	1		\$ 147.81	+		
8	RHR DOOR CHECKER	1		\$ 141.75	+		
9	REAR DOOR WEATHER STRIP <i>new</i>	1		\$ 150.66	+		
10	REAR DOOR LOCK LH <i>new</i>	1		\$ 188.73	+		
11	REAR DOOR LOCK RH <i>new</i>	1		\$ 188.73	+		
12	NUMBER PLATE LAMP GARNISH <i>new</i>	1		\$ 475.20	+		
13	REAR BUMPER <i>dent d</i>	1		\$ 946.00	✓ 624.80		
14	REAR BUMPER CLIP'S <i>on</i>	10		\$ 56.10	✓		
15	REAR BUMPER SIDE BRACKET <i>new</i>	2		\$ 105.60	+		
16	REAR END PANEL OUTER <i>new</i>	1		\$ 255.75	+		
17	REAR BUMPER REFLECTOR LAMP <i>new</i>	2		\$ 170.50	+		
18	TAIL LAMP <i>LH can be</i>	2		\$ 598.84	✓ 299.42		
19	EMBLEM <i>2</i>	1		\$ 216.15	✓ 55.30		
20	NV 200 WORDING <i>new</i>	1		\$ 187.00	✓ 79.90		
21	70 KM / H	1				\$ 15.00	✓
22	6 PAX STICKER	1				\$ 15.00	✓
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

3867.10
3480.39 P.W:30.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 FAX : 67436072

Vehicle No.	: <u>GBF 8481 L</u>	Case Owner	: <u>JOHARI</u>
Make & Model	: <u>NISSAN NV 200 1.5 MT</u>	Year of Manufacture	: <u>2017</u>

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.