



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TP

Vehicle No. : GBF8481L

Make & Model : NISSAN NV 200 1.5 MT

Year of Manufacture : 2017

Chassis No. : VSKYBAM20Z0138931

Ins Company : \_\_\_\_\_

Engine No. : K9KC400D056310

Excess : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Date of Accident : 09.11.2019

Time of Accident : 19.30

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor

**Repair Estimates**

Case Owner : \_\_\_\_\_

Signature : \_\_\_\_\_

Parts (a) Cost / List Price Items \$ 7,750.60

Contact No

Plus/Less 30% \$ 2,316.18

68438736 – THOMAS

Total of Cost / List \$ 7,720.60

(b) Nett Price Items \$ -

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$ 30.00

**Total Parts Cost (Appendix A) \$ 7,750.60**

**Labour (Appendix B) \$ 3,360.00**

**Total Repair Cost \$ 11,110.60**

*The above total will be subjected to 7% G.S.T.*

Name of Surveyor	:	_____
Company	:	_____
Survey conducted on	:	_____ at _____
<u>Remarks By Surveyor</u>		
(a) The repair of this vehicle is authorized / is not authorized until further notice.		
(b) Recommended Days of Repair	:	_____ day(s)
(c) Resurvey	:	Required / Not Required
(d) Excess	:\$	_____
(e) Signature of surveyor	:	_____ Date: _____

# Spark Car Care

ComfortDelGro Engineering Pte Ltd  
320 UBI ROAD 3 SINGAPORE 408649  
TEL :68438723/68438736 Fax:67436072

## Spare Parts

Vehicle No : GBF 8481 L Case Owner : JOHARI  
 Make & Model : NISSAN NV 200 1.5 MT Year Manufacture : 2017  
 Chassis No : VSKYBAM20Z0138931 Engine No : K9KC400D056310  
 Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_  
 Order By : \_\_\_\_\_ Type of Claim : \_\_\_\_\_

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	LHR DOOR	1		\$ 1,983.96			
2	LHR DOOR HINGE LOWER	1		\$ 147.81			
3	LHR DOOR HINGE UPPER	1		\$ 147.81			
4	LHR DOOR CHECKER	1		\$ 141.75			
5	RHR DOOR	1		\$ 1,352.70			
6	RHR DOOR HINGE LOWER	1		\$ 147.81			
7	RHR DOOR HIINGE UPPER	1		\$ 147.81			
8	RHR DOOR CHECKER	1		\$ 141.75			
9	REAR DOOR WEATHER STRIP	1		\$ 150.66			
10	REAR DOOR LOCK LH	1		\$ 188.73			
11	REAR DOOR LOCK RH	1		\$ 188.73			
12	NUMBER PLATE LAMP GARNISH	1		\$ 475.20			
13	REAR BUMPER	1		\$ 946.00			
14	REAR BUMPER CLIP'S	10		\$ 56.10			
15	REAR BUMPER SIDE BRACKET	2		\$ 105.60			
16	REAR END PANEL OUTER	1		\$ 255.75			
17	REAR BUMPER REFLEXTOR LAMP	2		\$ 170.50			
18	TAIL LAMP	2		\$ 598.84			
19	EMBLEM	1		\$ 216.15			
20	NV 200 WORDING	1		\$ 187.00			
21	70 KM / H	1				\$ 15.00	
22	6 PAX STICKER	1				\$ 15.00	
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

## Spark Car Care

ComfortDelGro Engineering Pte Ltd

