

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/FWD19020382/R1GA3Q2

**Date:** 08/04/2021

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd.	Policy No:	PNPV2018-00013734
<b>Claimant</b>		
<b>Vehicle No :</b> SFK9929H	<b>Insured Vehicle No :</b>	SLU848T
Date of Loss: 15/11/2019	Nature of Claim: TP	Claim No: 1201900035440

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFK9929H	Engine No:	583773333FC
Make & Model:	JAGUAR XF, 3.0 V6 LUXURY (A)	Chassis No:	SAJAC05D7AFR62139
Reg. Date:	30/12/2009 (Man. Year: 2009)	Odometer:	129728 km
Colour:	Brown		
Engine Capacity:	2967 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/40Z R19	Rear Tyre Size:	245/40Z R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>1,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>1,800.00</b>	<b>-1,800.00</b>	
<b>+ Car Rental (12.0 x S\$107.00/day) (S\$)</b>		1,284.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>+ Other Costs (S\$)</b>		100.00		
<b>+ Other Doc Fees (S\$)</b>		300.00		
<b>Nett Liability (S\$)</b>		<b>3,486.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,900.00</b>		

### INSPECTION

Date of Assignment:	15/11/2019		
Date Inspected:	18/11/2019	Inspected At:	Tan Lim Motor Pte Ltd (Defu)
			1 Defu Lane 6
			Singapore 539365
Estimated Period of Repair:	0.0 days		

---

**Adjuster:** MOHD RASUL**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$32,500.00

LTA REIMBURSEMENT VALUE (RV) : \$30,687.00

NETT VALUE : \$1,813.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jan 2020)
<b>Parts:</b>	143	JAGUAR XF 3.0 V6 LUXURY (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFK9929H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**