



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

FWD Insurance Insured's Veh No : SLU848T

Date of Accident : 15 November 2019

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Egg Creatives Pte Ltd

Date : 16 November 2019

Estimate To Repair SFK9929H - JAGUAR XF 3.0 V6 LUXURY AT ABS D/AB H
Chassis No : SAJAC05D7AFR62139

Rasi-LK4
18/11/19 @ 1340h

S/No	Quantity	Description	Amount
		NETT ITEMS	
01	1 pc	bonnet	\$ 2,795.00
02	1 pc	n/s headlamp <i>SCA</i>	\$ 2,954.00
03	1 pc	n/s headlamp lower bracket ?	\$ 350.00
04	1 pc	n/s front fender <i>bt</i>	\$ 1,720.00
05	1 pc	n/s front fender inner cowling <i>de</i>	\$ 271.50
06	8 ps	n/s front fender inner cowling clips @ \$4.50 <i>re</i>	\$ 36.00
07	1 pc	front bumper <i>de</i>	\$ 2,599.00
08	1 pc	front bumper side retainer <i>right left - can</i>	\$ 97.00
09	1 pc	front bumper chrome garnish	\$ 300.00
10	1 pc	front bumper lower centre air grille X	\$ 415.00
11	1 pc	front bumper reinforcement X	\$ 675.00
12	1 pc	front bumper absorber foam centre X	\$ 300.00
13	1 pc	front bumper lower splashshield cover ?	\$ 294.00
14	1 pc	front bumper air scoop n/s ?	\$ 180.00
15	1 pc	radiator grille <i>can</i>	\$ 1,153.00
		Less 10 %	\$ 14,139.50
			\$ 1,413.95
			\$ 12,725.55
		SPECIAL NETT ITEMS	
16	1 set	sundries and clips <i>re</i>	\$ 150.00
			\$ 150.00
		LABOUR & MISC. CHARGES	
01		To check electrical lighting concerned.	\$ 60.00
02		To rust-proofing of the affected areas.	\$ 80.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 950.00
04		Putty and spray painting of the affected portion.	\$ 1,200.00
			\$ 2,290.00
		Total	\$ 15,165.55

Rasi
HP 90010088

6 days

L/S

18/11/19 @ 1350

Rey after repair

80

30

40

500

750

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Comp.

Acknowledged by Repairer

Signature:

Date: