

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19020390/T1PA3Q2

Date: 09/07/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SME4456L	Insured Vehicle No :	SHD4493T
Date of Loss: 11/11/2019	Nature of Claim: TP	Claim No: MCT19110258

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME4456L	Engine No:	CZD162076
Make & Model:	VOLKSWAGEN TOURAN, 1.4 TSI (A)	Chassis No:	WVGZZZ1TZJW120877
Reg. Date:	28/09/2018 (Man. Year: 2018)	Odometer:	14416 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	900.00	800.00	100.00	11.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	911.00	811.00	100.00	10.98
+ GST 7.00/7.00% (S\$)	63.77	56.77	7.00	10.98
Nett Amount (S\$)	974.77	867.77	107.00	10.98
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,196.26		

INSPECTION

Date of Assignment:	18/11/2019 Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	20/11/2019 Inspected At:	Mova Automotive Pte Ltd (Bukit Merah)
		Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3
		Singapore 159722
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Jan 2020)	
Parts:	N/A	VOLKSWAGEN TOURAN 1.4 TSI (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME4456L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH - REPAIR (NPA)	Repair	-	*- FL
2	1		*REAR FENDER LH - REPAIR (NPA)	Repair	-	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					0.00	0.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					0.00	0.00
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK & STRAIGHTEN ON REAR DOOR LH & REAR FENDER LH. TO REMOVE & REFIT AFFECTED ATTACHMENT, REALIGN CONNECTION	New	400.00	400.00
2	TO SPRAY PAINT ON REPAIRED AREAS	New	500.00	400.00
Gross Labour Cost (\$\$)			900.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >