



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER:
UNKNOWN

India International Insurance Pte Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	11/11/2019
Vehicle Reg. No.:	SME4456L	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	VOLKSWAGEN TOURAN, 1.4 TSI (A)	Vehicle Reg. Date:	28/09/2018
Vehicle Colour:	SILVER	Chassis No:	WVGZZZ1TZW120877
Engine No:	CZD162076		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	0.00
Miscellaneous Items	11.00
Labour	900.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	911.00
+ GST 7.00% (S\$)	63.77
Nett Amount (S\$)	974.77

This claim is handled by: JACELYN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taufik 97495749
WP
20/11/19 1140
Resurvey after repair.
taufik@lkkauto.com
0.3 days

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 15 Nov 2019)

Parts: N/A VOLKSWAGEN TOURAN 1.4 TSI (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SME4456L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR DOOR LH - REPAIR	10.00	0.00	-
2	1		*REAR FENDER LH - REPAIR	10.00	0.00	-
Total Parts (S\$)						0.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK & STRAIGHTEN ON REAR DOOR LH & REAR FENDER LH. TO REMOVE & REFIT AFFECTED ATTACHMENT, REALIGN CONNECTION	New	400.00
2	TO SPRAY PAINT ON REPAIRED AREAS	New	500.00
Gross Labour Cost (\$\$)			900.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >