



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Tanpin 97495749
- WP

Date: 18.11.2019

China Taiping Insurance (S) Pte Ltd
2 Anson Road #16-00
Springleaf Tower
Singapore 079909

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

18/11/19 @ 348pm
Lumpsum
Resurvey after repair
8 days
sur @ 14h auto-com
To check repair limit

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO SHD2321U PRIUS HYBRID 1.8 (2014)

To supply

1)	1pc	rear bumper	\$	449.20	de
2)	1pc	rear bumper sponge	\$	105.00	X
3)	1pc	rear bumper right side retainer	\$	122.25	de
4)	1pc	rear bumper left side retainer	\$	122.25	de
5)	1pc	rear bumper right side bracket	\$	132.10	?
6)	1pc	rear bumper left side bracket	\$	132.10	-
7)	1pc	rear floor step under cover sub-assy 58308-47011	\$	512.43	de
8)	1pc	rear bumper left side seal 52592-47021	\$	85.30	X
9)	1pc	rear bumper right side seal 52591-47021	\$	85.30	X
10)	1pc	rear right tail lamp unit	\$	680.00	X
11)	1pc	rear left tail lamp unit	\$	680.00	ang
12)	1pc	rear end panel	\$	608.10	bt
13)	1pc	rear end panel top garnish	\$	561.40	de
14)	1pc	rear deck trim cover	\$	782.00	X
15)	1pc	tail gate	\$	1,450.00	bt
16)	1pc	tail gate weatherstrip	\$	284.00	de
17)	1pc	tail gate lower trim board assy	\$	421.20	de
18)	1pc	tail gate "Toyota" emblem	\$	62.00	new
19)	1pc	tail gate "Prius" emblem	\$	72.00	new
20)	1pc	tail gate "Hybrid Synergy Drive" emblem	\$	51.00	new
21)	1pc	tail gate lock stricker assy	\$	106.40	bt
22)	1pc	tail gate lock stricker cover	\$	41.80	de
23)	1pc	tail gate lock assy	\$	552.02	bt
24)	1pc	rear spare tyre top board	\$	561.60	de
25)	1pc	rear deck floor box	\$	560.00	de
26)	1pc	rear floor pan	\$	972.85	Ry
27)	1pc	spare wheel screw	\$	16.60	X

28)	1pc	spare wheel cushion	\$	197.22	<i>R</i>
29)	1pc	front bumper	\$	522.70	<i>de</i>
30)	1pc	front no plate garnish	\$	75.00	<i>de</i>

Sub total parts	\$	11,003.82
Less:25% discount	\$	(2,750.96)
	\$	8,252.86

To Supply S.Nett Parts

1)	1set	rear bumper clip	\$	30.00	<i>ue</i>
2)	1set	rear end panel top garnish clip	\$	15.00	<i>Re</i>
3)	1set	front bumper clip	\$	30.00	<i>ue</i>
4)	2tube	rear glass sealant	@\$40.00	\$	80.00 <i>ue</i>
5)	1pc	"Prime Taxi" sticker	\$	55.00	<i>ue</i>
6)	1pc	"Dial-A-Cab" sticker	\$	45.00	<i>ue</i>
7)	2pcs	tail gate lower glass moulding (2pcs)	\$	60.00	<i>ue</i>
8)	1set	tail gate glass moulding (3pcs)	\$	240.00	<i>ue</i>
9)	1pc	front no plate	\$	30-35.00	<i>ava</i>
10)	1pc	rear no plate	\$	30-35.00	<i>ave</i>

Sub total S.Nett Parts	\$	625.00
------------------------	----	--------

L/charge

1)	To tuff-kote rear portion	\$	150.00	<i>40</i>
2)	To remove & refit tail gate glass	\$	120.00	<i>✓</i>
3)	To remove & replace tail gate center glass	\$	60.00	<i>✓</i>
4)	To transfer tail gate trim board, mechanism parts & etc	\$	80.00	<i>60</i>
5)	To cut / welding rear end panel, floor panel, straighten left wheel house panel, remove tailgate, rear bumper, right & left tail lamp & etc. Adjust & align tailgate & rear bumper	\$	800.00	<i>700</i>
6)	To putty, respray painting tail gate inlet & outer, rear bumper, end panel, floor panel, left wheel house panel. To polish	\$	1,000.00	<i>800</i>
7)	To remove & replace front bumper, front no plate garnish. To repair front bumper reinforcement	\$	200.00	<i>✓</i>
8)	To putty, respray painting front bumper	\$	250.00	<i>200</i>

Sub total L/charges	\$	2,660.00
Estimated Grand Total	\$	11,537.86