MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 # 01-61 SINGAPORE 408717

Tel: 67484422 / 67454422 Fax: 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE Charts Building 78 Shenton Way #07-16 Singapore 079120 Tel: 6419 - 3000 Fax: 6835 - 7416	E PTE LTD	DATE VEH NO MODEL D O A YR REF	Quotation : 19.11.2019 : SLQ5935M : BMW 640i : 17.11.2019 : SLR5533J	
Attn: Motor Claim Dept	(Pls arrange vehicle survey & check liability)			

RE: ESTIMATE FOR ACCIDENT REPAIR SLQ5935M (BMW 640i)

<u>Item</u>	Description	Qty		<u>Amt</u>
NO	LIST ITEMS			
1	Front Bumper Delad	1		1,928.00
2	Front Bumper Clips A	1 set		50.00
3	Front Bumper Side Holder - RH	1		98.00
4	Front Bumper Nozzle Cover Missing	1	68.00	
5	Front Bumper Nozzle Pump Could	1	298.00	
6	Front Bumper Reinforcement ?	1	686.00	
7	Front Bumper Sponge	1	225.00	
8	Front Bumper Sensor Dand	1		358.00
9	Front Bumper Lamp - RH Front Bumper Lamp Cover - RH Head Lamp - RH Lt	1		289.00
10	Front Bumper Lamp Cover - RH	1		125.00
11	Head Lamp - RH Cut	, 1		4,366.00
12	BMW Logo Xer	7255 1		89.00
		6528.50		
				8,580.00
	Less 10%			(858.00)
			\$	7,722.00
	Total Parts		\$	7,722.00
	LABOUR CHARGE			
1	To knocking & pull out front RH portion & renew above parts		\$	700.00 400
2	To putty & spray up paint works		\$	600.00 250
3	To check wiring		\$	50,00 30
4	4 To perform dianogstic test		\$	700.00 403 600.00 250 50.00 30 150.00 100

RE: ESTIMATE FOR ACCIDENT REPAIR SLQ5935M (BMW 640i)

Total Labour

\$ 1,500.00

Grand Total

\$ 9,222.00

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 7309.50 (P/P).
04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: