

*KK*  
**Cheng Hoe Motor Pte Ltd**

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

**GBH 4856E**  
**TP/AIG**

**M/S :** AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120

**TEL:** 64193000 **FAX:** 64153727  
**ATTN:** Motor Claim Department

**Estimate No:** ES1992335/YISHUN  
**Date:** 03 Dec 2019  
**Policy No:** 5110002120  
**Veh Reg No:** **GBH4856E**  
**Make/Model:** TOYOTA TOYOTA  
HIACE VAN TURBO  
4DR AT

**WS Ref:** TP/AIG/YS  
**Claim Type:** Third Party  
**Accident Date:** 06/11/2019  
**TP Veh Reg No:** SLH2592K

*Not Authorized*  
*Permy Bepain*  
*3 days*

**Chassis No:** JTFHT02P000243058  
**Engine No:** 1KD2806094  
**Reg. Date:** 18/06/2018

**Estimate Repair Cost to Vehicle No :GBH4856E**

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
<b>List Price</b>				
1 FRONT BUMPER	498.10	1 PC	<i>Bu</i> 498.10	✓
2 FRONT BUMPER RH RETAINER	149.00	1 PC	<i>O/I</i> 149.00	✓
3 FRONT BUMPER CLIPS	3.50	6 PCS	<i>m</i> 21.00	✓
4 FRONT BUMPER REINFORCEMENT	304.00	1 PC	<i>B</i> 304.00	✓
5 RH HEADLAMP	737.10	1 PC	<i>W</i> 737.10	✓
			1,709.20	
		Less 25%	427.30	1,281.90
<b>Labour</b>				
6 REMOVE & REFIX FRT BUMPER, HEADLAMP, FRT BUMPER REINFORCEMENT & REALIGN THE SAME	400.00	1 LA	400.00	<i>250</i>
7 PUTTY & RESPRAY ON FRT BUMPER, REINFORCEMENT	400.00	1 LA	400.00	<i>280</i>
			800.00	800.00
		<b>Total</b>	<b>S\$ 2,081.90</b>	
		<b>Add GST @ 7%</b>	<b>145.73</b>	
		<b>Total Amount Payable</b>	<b>S\$ 2,227.63</b>	

*75/*  
\$ 1709.20  
427.30  
-----  
\$ 1281.90  
530  
-----  
\$ 1811.90 ✓ ok

**For Cheng Hoe Motor Pte Ltd**

*[Signature]*  
AUTHORISED SIGNATURE

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: