

Attn: Advisory

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Asher

Quotation

DATE : 19.11.2019
 VEH NO : SLC8433Z
 MODEL : Honda Jazz
 D O A : 15.11.2019
 YR REF : SLR5897J

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLC8433Z (HONDA JAZZ)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Rear Bumper <i>Del'd</i>	1	474.50 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - RH & LH <i>new</i>	2	64.80 ✓
4	Rear End Panel <i>Painted</i>	1	305.70 ✓
5	Rear End Panel Top Garnish <i>Del'd</i>	1	123.90 ✓
6	Tail Lamp - RH & LH <i>cut</i>	2	482.40 ✓
7	Tailgate <i>Distorted</i>	1	771.50 ✓
8	Tailgate Lock <i>Turned</i>	1	239.00 ✓
9	Tailgate Weatherstripe <i>cut</i>	1	92.30 ✓
10	Tailgate Inner Trim Board <i>Del'd</i>	1	282.40 ✓
11	Tailgate Inner Trim Board Clips <i>new</i>	1	30.00 ✓
12	Tailgate Glass Moulding <i>new</i>	1	90.10 ✓
13	Jazz Emblem <i>new</i>	1	37.90 ✓
14	Rear Fender Inner Trim Board - Upper & Lower <i>LH Del'd</i>	2	532.40 <i>4487.20</i> 266.20
15	Rear Fender Inner Trim Board Clips <i>new</i>	1	60.00 <i>3589.76</i> 30
16	Spare Tyre Panel Top Board <i>Del'd</i>	1	190.70 ✓
17	Tools Tray Sponge <i>Crushed</i>	1	238.60 ✓
18	Spare Tyre Panel <i>Brickend.</i>	137.20 ✓	
			4,046.20
Less 20%			(809.24)
			\$ 3,236.96

S/NET ITEMS

1	Rear Number Plate <i>2 yrs new</i>	1	\$ 30.00 <i>x</i>
2	Rear Number Plate Holder	1	\$ 30.00 <i>x</i>
3	Reverse Sensor <i>Damaged</i>	1	\$ 280.00 <i>200</i>
4	Rear End Panel Sealant <i>new</i>	1	\$ 60.00 ✓
5	Tailgate Glass Sealant <i>new</i>	1	\$ 60.00 ✓
6	Spare Tyre Panel Insulation Pad <i>new</i>	200 <i>200</i>	\$ 460.00

520

RE: ESTIMATE FOR ACCIDENT REPAIR SLC8433Z (HONDA JAZZ)

Total Parts \$ 3,696.96

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1600 1300
2	To putty & spray up paint works	\$	1400 1200
3	To check wiring	\$	50.00 30
4	To underseal	\$	150.00 80
5	To remove reverse sensor	\$	100.00 60
6	To remove upholstery and rear seat	\$	300 200
7	To remove tailgate glass	\$	180.00 120
8	To transfer tailgate fittings	\$	150.00 80

Total Labour \$ 3,180.00

Grand Total \$ 6,876.96

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 7129.76
L/S: 5750

09 Days

- LKK Auto Consultants** hence hereby
the Repairer of the follow:
- To resurvey before/after repair
 - To display damaged parts during resurvey
 - Parts prices must be confirmed
 - Third party must be on a "Without Prejudice" basis
 - No re-estimate is allowed
 - All elementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: