Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19020417/KPA3Q2

Date: 12/05/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00014455

Claimant Insured Vehicle No: SKM967L **GBF6286Y**

Vehicle No:

ΤP Date of Loss: Nature of Claim: 12/11/2019 Claim No: 1201900036062

DESCRIPTION & IDENTIFICATION OF VEHICLE

GBF6286Y Reg No:

Make & Model: TOYOTA HIACE, 3.0 D DX (A) Engine No: 1KD2647146 Reg. Date: 11/01/2017 (Man. Year: 2016) Chassis No: KDH2010204929 Colour: White Odometer: 121601 km

Engine Capacity: 2982 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15 Front Left Side: Rear Left Side: Firemax 7 mm Firemax 7 mm Front Right Side: Rear Right Side: Firemax 7 mm Firemax 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,027.00	849.00	2,178.00	71.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	1,050.00	410.00	28.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,487.00	1,899.00	2,588.00	57.68
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	4,487.00	1,500.00	2,987.00	66.57
+ GST 7.00/7.00% (S\$)	314.09	105.00	209.09	66.57
Nett Amount (S\$)	4,801.09	1,605.00	3,196.09	66.57
+ Loss of Use (3.0 x S\$	80.00/day) (S\$)	240.00		
	(S\$)	1,845.00		
Liable Amoun	t (50.00%) (S\$)	922.50		
+ Doc/S	earch Fee (S\$)	2.00		
Ne	tt Liability (S\$)	924.50		
Global Sum Settlement (S\$)		900.00		

INSPECTION

Date of Assignment: 14/11/2019

10/01/2020 Inspected At: Date Inspected: Efficient Motor & Engineering Works

Pte Ltd (HQ)

56 Loyang Way #06-07, Loyang

Adjuster Report Page 2 of 4

Enterprise Building Singapore 508775

Estimated Period of Repair: 3.0 days

Adjuster: PARASURAM SHANMUGAM Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Feb 2020)

Parts: 213 TOYOTA HIACE 3.0 D DX (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBF6286Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	496.00 FL	*496.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Dented	320.00 FL	*320.00 FL
3	1		*FRONT BUMPER SIDE RETAINER LH	Cracked	193.00 FL	*125.00 FL
4	1		*LH FRONT HEADLAMP	Not Necessary	2,506.00 FL	*- FL
5	1		*FRONT GRILLE UPPER	Scratched	191.00 FL	*191.00 FL
6	1		*FRONT GRILLE LOWER	Not Necessary	330.00 FL	*- FL
F=Fra	anchise	part. L=ListIt	emDisc.	_		
				Sub Total (S\$)	4,036.00	1,132.00
	- List Item Discount on L Items 25.00/25.00% (S\$)			1,009.00	283.00	
				Total Parts (S\$)	3,027.00	849.00

C = = = | | |

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR FOR PANEL BEATING	New	800.00	600.00
2	LABOUR FOR SPRAY PAINTING	New	600.00	400.00
3	WIRING	New	60.00	50.00
		Gross Labour Cost (S\$)	1,460.00	1,050.00
	Damantu			
	Report w	as unsubmitted during this print-out.		

< END OF ESTIMATES >