

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933
Tel : 6844-1985 Fax : 6844-5185
Reg : 201838521G

Repair Estimate

Date :09/11/2019

Reference: CHEVROLET
Make: ORLANDO

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SFQ7002M
CHASSIS NO.: KL1YA7589EK566605
ENGINE NO.: A14NET133520020

Name of insured : ISMERLI B IBRAHAIM
Date of accident : 08/11/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	REAR BUMPER STEP PLATE	\$ 166.00
2	1	REAR BUMPER UPPER	\$ 1,330.00
3	1	REAR BUMPER LOWER	\$ 493.00
4	1	REAR BUMPER SILL PLATE(SILVER)	\$ 223.00
5	1	REAR BUMPER TOWING COVER	\$ 93.00
6	1	LHR BUMPER REFLECTOR	\$ 140.00
7	1	RHR BUMPER REFLECTOR	\$ 140.00
8	1	REAR REVERSE LIGHT AND BRAKE LIGHT	\$ 307.00
9	1	REAR TAILGATE	\$ 1,528.00
10	1	REAR END PANEL	\$ 776.00
11	1	REAR END PANEL TRIM	\$ 186.00
12	1	REAR BUMPER CENTRE GUIDE	\$ 148.00
13	1	RHR BUMPER GUIDE, OTR	\$ 118.00
14	1	LHR BUMPER GUIDE, OTR	\$ 118.00
15	1	REAR BUMPER LEFT CENTRE GUIDE, INR	\$ 112.00
16	1	REAR BUMPER RIGHT CENTRE GUIDE, INR	\$ 112.00
17	1	REAR BUMPER BEAM	\$ 863.00
18	1	RR TAILGATE LOGO	\$ 187.00
19	1	RR TAILGATE EMBLEM "CHEVROLET"	\$ 133.00
20	1	RR TAILGATE EMBLEM "ORLANDO LS"	\$ 148.00
21	1	RR TAILGATE EMBLEM TURBO	\$ 151.00
22	1	RR TAILGATE LOCK - Latch	\$ 331.00
23	1	RR TAILGATE LOCK CATCH - Striker	\$ 121.00
24	1	RR TAILGATE RUBBER BEADING	\$ 272.00
25	2	RR BUMPER REVERSE SENSOR	\$ 430.00
26	4	RR BUMPER REVERSE SENSOR SEAL	\$ 40.00
27	1	RR BUMPER REVERSE SENSOR WIRE HARNESS	\$ 291.00

4841

Parts Total: \$ 8,957.00

435690

Less 10%: \$ 895.70
Total: \$ 8,061.30

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,000.00
2	Carry out spray painting on affected area, RR BUMPER, RR TAILGATE, RR END PANEL, RR FENDER RH	\$ 1,000.00
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 120.00
4	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 200.00
5	To remove and refix reverse sensor and conduct test	\$ 120.00
6	To conduct transfer of parts from old tailgate to new tailgate	\$ 200.00
7	To conduct water leakage test after repairs of vehicle	\$ 80.00
8	To conduct reset of engine light on	\$ 200.00
9	To remove and refix rear tail gate windscreen	\$ 180.00

Labour Total: \$ 3,100.00

Others

No.	Other Description	Price (SGD)
1	RR BUMPER CLIP	\$ 40.00
2	RR TAILGATE INNER TRIM BOARD CLIP	\$ 40.00
3	RR WINDSCREEN SEALANT	\$ 65.00
4	RR WINDSCREEN INNER SEAL	\$ 40.00
5	RR TAILGATE STICKER	\$ 150.00

Other Total: 335.00

TOTAL: 11,496.30

GRAND TOTAL: 11,496.30

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor
Kelvin Chew
HP: 8292 5595 Fax: 68445185

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Admin G
4/5 15/11/18
OSR
Total: 5584.90
4/5: HK (Nett Value)