

ASS. REC. BY:

REF: CS/FCI/19020440/Myd3n2

Special Instruction:

Signature: Melrose

ASSIGNMENT (Office)

AWB

From (Person): Melrose Chua

of FCI

Date/Time: 8:47am @ 19/11/19

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGF 7854S

Insured: SHB 3223Z

at Workshop m/s: Fastech Auto

Tel: 6746 5405

of 1 Kerli Bukit Ave 6 # 01-46

Policy No:

Claim No: D19007266 MFST

Sum Insured:

Excess:

Make of Veic:

(Client's Record)

D.O.A. 16/11/2019

CA / REV / REP. / REV 24 HRS ^(wp)

H.O.D. Endorsement:

Date/Time: 9:01am @ 19/11/19

Person Contacted: Lin

Vehicle IN OUT

Date/Time

Action/Instruction

SGF 7854S - X

SHB 3223Z CS / FCI / 7002762 / 11/19 hnd

SWA: 312/2019

26/12/19 Sent Preli by email

ASS. FILED BY:

File:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SGF 7854S
 at Workshop m/s LL
 of _____
 Insured: SHS32232
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 44K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 15 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGF 7854S Yr Regn: 24/4/06Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota wish C.O. 1794Colour: Blue A/C: _____ Insured / Std / NI / NASp. Reading: 39484 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2NE100289208Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Pain / STD A/Rim orTyre Size: F: 205/55 R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or G.S.T

Front

Rear

R/Bal: 5 mm R/Bal: 5 mmL/Bal: 5 mm L/Bal: 5 mmD.O.A. 16/11/19 D.O. 18/11/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction by S. S. S. 6800
Loc. until 23-4-2026 17A 30486
NH 13/14

21/11/19 Sent E-Mail (Pending Estimate) RECEIVED 27 DEC 2019

24/12/19 F/S \$13,500 confirmed with Ales. (Red \$22,707.70, 62%)

MV = \$44,000/-

LTA = \$30,486/-

Nett = \$13,514/-

Data/Time, File Pass to: _____

1) ☐ : Final Report

Data/Time, File Return to: _____

2) 27/12/19 Typist

Policy Form: _____

Comp Form / LEJ: \$13,500/-

Days Of Repair: 15Resurvey No. of Trip: 2Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Wash & Dry (\$)

Survey Fee: _____

Transportation: _____

S + RS \$1

Parking: 580

Other: _____

Total: 32/12/19Total: 930

26x15 = 390

170 + 390

50

50 + 50

220

Total: 930



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007266MFSH

Date: 26 Dec 2019

Our Ref: CS/FCI19020440/Uyd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SGF7854S

Please be informed that we had conducted the inspection of the abovementioned vehicle on 16/11/2019 at the premises of M/s FASTECH AUTO PTE LTD. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>36,207.70</u>
Revised Estimate Amount	: S\$ <u>15,066.73</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
at the rear & front portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	18-11-2019	Our Ref No. D19007266MFSH
Accident Date	16-11-2019	Claim Type. Third Party
Insured Vehicle	SHB3223Z	Third Party Vehicle. SGF7854S
Survey Location	1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY	
Contact Person.	LINA	
Contact No.	67465405/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FASTECH AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Thursday, December 26, 2019 8:05 PM
To: 'CWS Motor Claims'
Cc: 'Merina Chia'; SUR
Subject: RE: SURVEY ASSESSMENT - D19007266MFSH/1
Attachments: SGF7854S DOA 16112019 REVERT.pdf

Dear Sir/ Madam

Enclosed preliminary revised of vehicle SGF 7854S

Date of survey : 19/11/2019

Number of days : 15 days

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yvonne Wong (LKK Auto)
Sent: Thursday, November 21, 2019 8:00 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: SURVEY ASSESSMENT - D19007266MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SGF7854S on 18/11/2019.

We are still pending estimate from repairer.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Thursday, November 21, 2019 8:00 PM
To: 'CWS Motor Claims'
Cc: 'Merina Chia'; SUR
Subject: SURVEY ASSESSMENT - D19007266MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SGF7854S on 18/11/2019.

We are still pending estimate from repairer.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, November 19, 2019 9:01 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19007266MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Tuesday, 19 November 2019 8:47 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia <MerinaChia@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19007266MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Price Range

Depreciation

> 10 year()

Vehicle Type

[Advanced Search](#)

Home » Used Cars » Imperium Car Motor Pte Ltd » Toyota Wish 1.8A (COE till 07/2026)

Toyota Wish 1.8A (COE till 07/2026)

[Overview](#) [Financial](#) [Insurance](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)



Imperium Car Motor

Price	\$43,800		
Depreciation	\$6,530 /yr	Reg Date	07-Aug-2006 (6yrs 8mths 13days COE left)
Mileage	N.A.	Manufactured	2006
Road Tax	\$1,264 /yr	Transmission	Auto
Dereg Value	\$34,613 as of today <i>(change)</i>	OMV	\$20,685
COE	\$51,630	ARF	\$22,754
Engine Cap	1,794 cc	Power	97.0 kW (130 bhp)
Curb Weight	1,300 kg	No. of Owners	2
Type of Vehicle	MPV		

Features

Original Condition.

Accessories

Factory Fitted Interior.

Description

Road Tax Paid Till Aug 2020. Premium Grooming And Brand New Paint Coat Provided. Bank And In House Full Loan Available. STA/Vicom Evaluation Welcome. Trade In Welcome. Kindly Contact Our Sales Advisor For Viewing And Test Drive.

Category

COE Car

Status

Available

Resources



Car Valuation - Free
Find out the market value of your existing car for free. [Get started](#)



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)



[Shortlist](#) [Compare](#) [Add note](#)

[Report Error](#) [More Actions](#)

Seller Information

Imperium Car Motor Pte Ltd

11 vehicles for sale. 16 sold in past 3 mths.

25 Kaki Bukit Road 4 #01-49
Synergy @ KB
Tel: 65572663
[Search cars nearby](#)

[imperiumcarmotor.com](#)

Melvin Teo

87870008

Eugene Lim

92725924

Exclusive Year End Sale

Fly to your next destination and enjoy great fares. Book by 18 Nov

wish Price Range Depreciation > 10 year(s) Vehicle Type Submit Advanced Search

Home > Used Cars > AA Trust Automotive > Toyota Wish 1.8A (COE till 05/2026)

Toyota Wish 1.8A (COE till 05/2026)

Overview Financial Insurance Accessories Similar Research Photos Map



Price	\$43,800		
Depreciation	\$6,780 /yr	Reg Date	05-May-2006 (6yrs 5mths 16days COE left)
Mileage	N.A.	Manufactured	2006
Road Tax	\$1,264 /yr	Transmission	Auto
Dereg Value	\$29,761 as of today (change)	OMV	\$19,355
COE	\$46,048	ARF	\$21,291
Engine Cap	1,794 cc	Power	97.0 kW (130 bhp)
Curb Weight	1,300 kg	No. of Owners	4
Type of Vehicle	MPV		

Features

16 Valves VVT-i DOHC Engine, Smooth Super 4 Speed ECT Steptronic Auto, Digital Auto Climate Control Aircon, Airbags, ABS, 7 Seaters.

Accessories

Sports Rims Leather Seats, Upgraded Brake Kit, JVC Head Unit, Reverse Sensors, Solar Films, Knockdown Rear Seats.

Description

New Paint Work! AA Trust Certified Vehicle! Extremely Well Maintain By Previous Owner! Powerful And Responsive Engine And Fuel Efficient! MPV With Ample Space For The Whole Family! Highly Recommended Popular Family Car! Flexible Bank/In House Loan Available! Trade In Most Welcome! Hurry Sowin To Our Showroom Before Its Gone!

Category

COE Car

Status

Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more.



Shortlist Compare Add note
Report Error More Actions

Seller Information

AA Trust Automotive

103 vehicles for sale, 76 sold in past 3 mths



PREMIUM DEALER 2019

73 Mackenzie Road Lot 03/04/07/08

Mackenzie Used Car Centre

Tel: 63450381

Search cars nearby

Wiley	91692071
Clement	93365036
Dave	98500051

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 723J

Vehicle Details

Vehicle No.: SGF7854S

Vehicle to be Exported: No

Intended Deregistration Date: 20 Nov 2019

Vehicle Make: TOYOTA

Vehicle Model: WISH 1.8 A

Primary Colour: Blue

Manufacturing Year: 2005

Engine No.: 1ZZ2485103

Chassis No.: ZNE100289208

Maximum Power Output: 97.0 kW (130 bhp)

Open Market Value: \$19,849.00

Original Registration Date: 24 Apr 2006

First Registration Date: 24 Apr 2006

Transfer Count: 0

Actual ARF Paid: \$21,834.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 23 Apr 2026

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

PQP Paid: \$47,450.00

COE Rebate Amount: \$30,486.00

Total Rebate Amount: \$30,486.00

The information contained herein is correct as at 18 Nov 2019

OK

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

VEHICLE NO: **SGF78545**

QTY	PARTICULAR
1 PCS	REAR WINDSCREEN
1 PCS	REAR WINDSCREEN MOULDING
1 PCS	TAILGATE 1248-10
1 PCS	TAILGATE INNER LOCK
1 PCS	TAILGATE REAR LOGO
1 PCS	TAILGATE 'WISH' EMBLEM 480-10
1 PCS	TAILGATE INNER TRIM BOARD
1 SET	TAILGATE INNER TRIM BOARD CLIPS
1 PCS	TAILGATE WEATHERSTRIP
1 PCS	TAILGATE OUTER CHROME MOULDING
2 PCS	TAILGATE DAMPERS @\$350.00
1 PCS	TAILGATE INNER HOLDER GARNISH
1 PCS	REAR BUMPER 892.30
2 PCS	REAR BUMPER REFLECTORS @\$105.00 68.50
2 PCS	REAR BUMPER SIDE HOLDERS @\$68.50
1 SET	REAR BUMPER CLIPS
2 PCS	REAR BUMPER DAMPERS @\$55.60
1 PCS	REAR END PANEL
1 PCS	REAR END PANEL LOWER MEMEBR
1 PCS	REAR END PANEL TOP GARNISH
2 PCS	TAILLAMPS @\$458.10 408-10
2 PCS	TAILLAMP HOUSING PANELS @\$455.10
1 PCS	REAR FLOOR PANEL
1 PCS	REAR FLOOR PANEL TOP BOARD 499-10
2 PCS	REAR FENDERS @\$977.10
2 PCS	REAR FENDER INNER TRIM BOARDS @\$605.10
1 SET	REAR FENDER INNER TRIM BOARD CLIPS
1 PCS	REAR EXHAUST
2 PCS	REAR EXHAUST MOUNTINGS @\$65.00
1 PCS	REAR EXHAUST HEAT SHIELD
1 PCS	REAR SPARE TYRE BRACKET & CARRIAGE 399.50
1 PCS	REAR AIR VENT
1 PCS	BONNET
1 PCS	BONNET INSULATOR
1 SET	BONNET INSULATOR CLIPS
1 PCS	BONNET LOCK
1 PCS	BONNET OUTER CHROME MOULDING
2 PCS	HEADLAMPS @\$689.10
1 PCS	FRONT BUMPER 645-10
1 PCS	FRONT BUMPER REINFORCEMENT
1 PCS	FRONT BUMPER SPONGE
2 PCS	FRONT BUMPER SIDE HOLDERS @\$65.50
1 SET	FRONT BUMPER CLIPS
2 PCS	FRONT BUMPER FOG LAMP COVERS @\$68.00
1 PCS	FRONT BUMPER CENTRE GRILLE
1 PCS	FRONT GRILLE

Not Authorized
Mark
19/11/19
To be paid After repair
15th. 1/5 \$13,500

11	\$1,288.50	X
guc	\$128.70	—
304/10	\$1,866.10	—
2/10m	\$388.80	—
rec	\$68.10	—
MF	\$60.50	X
20/10m	\$845.10	—
11	\$50.00	X
11	\$299.50	—
304/10	\$388.20	—
11	\$700.00	Y
11	\$45.00	X
D/S	\$665.30	—
n/s cm	\$210.00	IPC
n/s set	\$137.00	IPC
rec	\$50.00	—
n/s set	\$111.20	IPC
304/10	\$699.10	—
304/10	\$211.50	—
11	\$288.60	—
n/s cm	\$916.20	IPC
n/s 27	\$910.20	IPC
crumpled/304	\$1,120.10	—
wagon	\$588.20	—
n/s Body	\$1,954.20	IPC
n/s torn	\$1,210.20	IPC
11	\$50.00	X
11	\$788.50	X
11	\$130.00	X
11	\$211.10	X
304	\$450.50	—
11	\$121.00	X
304	\$678.10	—
10m	\$211.50	—
rec	\$50.00	—
10m	\$145.50	—
CRA	\$155.30	—
n/s 304 2/10m	\$1,378.20	—
D/S	\$830.00	—
304	\$266.20	—
Torn	\$166.50	—
11	\$131.00	X
rec	\$50.00	—
11	\$136.00	X
11	\$188.20	X
304	\$166.60	—

257

1 PCS	FRONT BRACE PANEL
1 PCS	FRONT SUPPORT PANEL
1 PCS	AIR CON CONDENSER
1 PCS	AIR CON SUCTION HOSE
1 PCS	AIR CON DISCHARGE HOSE
1 PCS	RADIATOR
1 PCS	RADIATOR FAN MOTOR
1 PCS	RADIATOR FAN BLADE
1 PCS	RADIATOR FAN COWLING
2 PCS	HORN UNITS @\$105.00
2 PCS	FRONT FENDERS @\$650.10
2 PCS	FRONT FENDER INNERSHIELDS @\$195.10

1 PCS	S.NETT
1 PCS	REAR BUMPER REVERSE SENSOR
1 PCS	REAR END PANEL SEALANT
1 PCS	REAR FLOOR PANEL INSULATOR
1 PCS	REAR WINDSCREEN SEALANT
1 SET	REAR LICENCE PLATE W/HOLDER
1 SET	FRONT LICENCE PLATE W/HOLDER
1 BOL	RADIATOR COOLANT

LABOUR CHARGES:

TO CHECK WIRING
TO DISMANTLE & REPLACING REAR REVERSE SENSOR
TO DISMANTLE & REFIX REAR WINDSCREEN
TO TRANSFER TAILGATE MECHANISM
TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTREY
TO DISMANTLE & REFIX REAR EXHAUST
TO DISMANTLE & REFIX PETROL TANK
TO MOUNT VEHICLE ON CAR O-LINER
TO REFILL AIRCON GAS
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

4w1	\$121.50	✓
6w1	\$688.10	✓
6w1/2w1	\$1,213.10	✓
17	\$395.50	X
17	\$388.10	X
6w1/2w1	\$1,866.50	✓
7w1	\$450.50	✓
6w1	\$150.40	✓
CR	\$209.10	✓
5w1	\$210.00	X
17s 6w1	\$1,300.20	17C
17	\$390.20	X
	\$28,687.70	

CR	\$280.00	200
2w1	\$50.00	✓
2w1	\$200.00	100
2w1	\$50.00	40
6w1	\$50.00	40
5w1	\$50.00	40
2w1	\$50.00	30

	\$80.00	30
	\$80.00	50
	\$150.00	120
	\$100.00	60
	\$150.00	80
17	\$100.00	X
	\$100.00	60
17	\$380.00	X
	\$150.00	100
	\$200.00	150
	\$2,800.00	2400
	\$2,500.00	1800
TOTAL	\$36,207.70	

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- This work is on a "Without Reserve" basis
- No day of modification is allowed
- Supplementary item(s) must be re-surveyed and subject to final approval from Indulink Company

Acknowledged by Repairer
Signature:
Date:

17977.9
13483.42
18833.42
15066.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19020440/Uyd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-01-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3223Z	Veh. Inspected	SGF 7854S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19007266MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	19/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH (A)	c.c	1794	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	ZNE100289208	Colour	BLUE	
Odometer	394984	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	GST	5 mm	
L/H Front Tyre	205/55 R16	GST	5 mm	
R/H Rear Tyre	205/55 R16	GST	5 mm	
L/H Rear Tyre	205/55 R16	GST	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/11/2019	Inspection Date	19/11/2019	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGF 7854S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN	NOT NECESSARY	1,288.50	-
1	REAR WINDSCREEN MOULDING	NECESSARY	128.70	128.70
1	TAILGATE	BADLY DENTED	1,866.10	1,248.10
1	TAILGATE INNER LOCK	DENTED / JAMMED	388.80	388.80
1	TAILGATE REAR LOGO	NECESSARY	68.10	68.10
1	TAILGATE "WISH" EMBLEM	NOT FITTED	60.50	-
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	645.10	485.10
1	SET TAILGATE INNER TRIM BOARD CLIPS	NOT NECESSARY	50.00	-
1	TAILGATE WEATHERSTRIP	TWISTED	299.50	299.50
1	TAILGATE OUTER CHROME MOULDING	BENT / CRACKED	388.20	388.20
2	TAILGATE DAMPERS @\$350.00	NOT NECESSARY	700.00	-
1	TAILGATE INNER HOLDER GARNISH	NOT NECESSARY	45.00	-
1	REAR BUMPER	DISTORTED	665.30	492.30
2	REAR BUMPER REFLECTORS @\$105.00	N/S CRACKED	210.00	68.50
2	REAR BUMPER SIDE HOLDERS @\$68.50	N/S BENT	137.00	68.50
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER DAMPERS @\$55.60	N/S BENT	111.20	55.60
1	REAR END PANEL	BADLY DENTED	699.10	699.10
1	REAR END PANEL LOWER MEMBER	BADLY DENTED	211.50	211.50
1	REAR END PANEL TOP GARNISH	TWISTED	288.60	288.60
2	TAILLAMPS @\$458.10	N/S CRACKED	916.20	408.10
2	TAILLAMP HOUSING PANELS @\$455.10	N/S DENTED	910.20	455.10
1	REAR FLOOR PANEL	CRUMPLED / BUCKLED	1,120.10	1,120.10
1	REAR FLOOR PANEL TOP BOARD	WARPED	588.20	499.10
2	REAR FENDERS @\$977.10	N/S BADLY DENTED	1,954.20	977.10
2	REAR FENDER INNER TRIM BOARDS @\$605.10	N/S TORN	1,210.20	605.10
1	SET REAR FENDER INNER TRIM BOARD CLIPS	NOT NECESSARY	50.00	-
1	REAR EXHAUST	NOT NECESSARY	788.50	-
2	REAR EXHAUST MOUNTINGS @\$65.00	NOT NECESSARY	130.00	-

Report Ref No. CS/FCI19020440/Uyd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	211.10	-
1	REAR SPARE TYRE BRACKET & CARRIAGE	BROKEN	450.50	399.50
1	REAR AIR VENT	NOT NECESSARY	121.00	-
1	BONNET	BUCKLED	678.10	678.10
1	BONNET INSULATOR	TORN	211.50	211.50
1	SET BONNET INSULATOR CLIPS	NECESSARY	50.00	50.00
1	BONNET LOCK	TWISTED	145.50	145.50
1	BONNET OUTER CHROME MOULDING	CRACKED	155.30	155.30
2	HEADLAMPS @\$689.10	N/S BROKEN / O/S CRACKED	1,378.20	1,378.20
1	FRONT BUMPER	DISTORTED	830.00	645.10
1	FRONT BUMPER REINFORCEMENT	BENT	266.20	266.20
1	FRONT BUMPER SPONGE	TORN	166.50	166.50
2	FRONT BUMPER SIDE HOLDERS @\$65.50	NOT NECESSARY	131.00	-
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
2	FRONT BUMPER FOG LAMP COVERS @\$68.00	NOT NECESSARY	136.00	-
1	FRONT BUMPER CENTRE GRILLE	NOT NECESSARY	188.20	-
1	FRONT GRILLE	BROKEN	166.60	166.60
1	FRONT BRACE PANEL	TWISTED	121.50	121.50
1	FRONT SUPPORT PANEL	BENT	688.10	688.10
1	AIR CON CONDENSER	BENT / PUNCTURE	1,213.10	1,213.10
1	AIR CON SUCTION HOSE	NOT NECESSARY	395.50	-
1	AIR CON DISCHARGE HOSE	NOT NECESSARY	388.10	-
1	RADIATOR	BENT / PUNCTURE	1,866.50	1,866.50
1	RADIATOR FAN MOTOR	JAMMED	450.50	450.50
1	RADIATOR FAN BLADE	BENT	150.40	150.40
1	RADIATOR FAN COWLING	CRACKED	209.10	209.10
2	HORN UNITS @\$105.00	SERVICEABLE	210.00	-
2	FRONT FENDERS @\$650.10	N/S BUCKLED	1,300.20	650.10
2	FRONT FENDER INNERSHIELDS @\$195.10	NOT NECESSARY	390.20	-
	LESS 25% DISCOUNT		-	-4,666.75
			28,687.70	14,000.25

Report Ref No. CS/FCI19020440/Uyd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN)	CRACKED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR FLOOR PANEL INSULATOR (SN)	NECESSARY	200.00	100.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	SET REAR LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	SET FRONT LICENCE PLATE W/HOLDER (SN)	BROKEN	50.00	40.00
1	BOL RADIATOR COOLANT (SN)	NECESSARY	50.00	30.00
			730.00	500.00
	LABOUR			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REAR REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO TRANSFER TAILGATE MECHANISM.		100.00	60.00
	TO DISMANTLE & REFIX SEAT, CUHION UPHOLSTERY.		150.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX PETROL TANK.		100.00	60.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	TO REFILL AIRCON GAS.		150.00	100.00
	TO SPRAY RUST PROOFING.		200.00	150.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.		2,800.00	2,400.00
	TO PUTTY & SPRAY PAINTING.		2,500.00	1,800.00
			6,790.00	4,850.00
	GRAND TOTAL		36,207.70	19,350.25
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			13,500.00

Report Ref No. CS/FCI19020440/Uyd3n2

MARKET VALUE: \$44,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$30,486.00=NETT VALUE: \$13,514.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.