

INS. CASE OWNER:

CC⁶ /AIG1902 0476, Adh⁶LKK:
IDAC

Surveyor:

Adnan

DOI:

ASSIGNMENT

18/11/18

Date / Time:

18/11/18

Registered in Merimen:

1A/11/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

GPD 8068H

Name of Insured:

PORKA INTERNATIONAL PTE

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A:

18/11/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

99994478/10084777

TOYOTA

RIVERIA RD (RBS MULTI STORY CP 4 BLOCK

If NO, Driver Name / Age:

WED HOCK SAW

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

Final ? Yes / No

IMP 2787P



INSRS:

WSP:

Tel:

Liability:

RMKS:

MHT



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

4/3/2020 - File PM to Hock to COTB

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 25/2/2020

Confirm with: Sukhy

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 23

If NO or B 28, Ass. Lia :

Repair Cost: (w/lat)

S\$ 2461.00

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ 240.00

(5 60 x 4 days)

Loss of Income (LOI):

S\$ -

(5 x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LO ☐

(Tick only one)

GIA/LTA Search

S\$ 7.45

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 2708.45

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 2708.45

Name 1:

New Hock Tech Motor Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$320

COPY SENT
4/3/2020

Verb. Nr.: smf27871² et Regn: 2018 oct.

Date: Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

LKK
ALG

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP ALG

Jra Le.

18/11/2019

GPS3416810

Accident date: 16/11/2019

Estimated repair cost for vehicle no: SMF2787P HONDA FIT HYBRID 1.5 A '18

CHASSIS: GP53416810

S/n	Qty	Items	U/price	Amount
1	1	Front Grille <i>cracked</i>		\$382.90 ✓
2	8	Front Grille Clip <i>new</i>	\$6.50	\$52.00 ✓ 10.
3	1	Front Grille Emblem Logo <i>new</i>		\$37.00 ✓
4	1	Front Grille Top Chrome Moulding <i>ut</i>		\$254.10 ✓
5	1	Front Grille Lower Chrome Moulding <i>ut</i>		\$265.00 ✓
6	1	Front Bumper <i>detached</i>		\$801.50 ✓
7	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 ✓ 50.
8	1	Front Bumper Reinforcement <i>new</i>		\$253.10 ✗
10	1	Front L/H Bumper Side Retainer <i>new</i>		\$25.60 ✓
11	1	Front L/H Bumper Fog Lamp Cover <i>cracked</i>		\$127.50 ✓
12	1	Front L/H Headlamp <i>ut</i>		\$901.50 ✓
13	1	Front L/H Headlamp Lower Bracket <i>cracked</i>		\$27.00 ✓
14	1	Front L/H Fender <i>2nd</i>		\$408.50 ✗
15	1	Front L/H Fender Cowling <i>new</i>		\$101.50 ✗

Subtotal :- \$3,702.20

2882.10

228868

Labour charges

To check wiring		\$100.00 30
Tuff kote		\$150.00 X
Panel beating	580	\$1,000.00 300
Spray painting		\$1,000.00 250

Subtotal :- \$2,250.00

Total:- \$5,952.20

total: 2869.68

L/S: 2-31c

03 Days

2-31c

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 083J

Vehicle Details

Vehicle No.: SMF2787P
Vehicle to be Exported: No
Intended Deregistration Date: 18 Nov 2019
Vehicle Make: HONDA
Vehicle Model: FIT HYBRID 1.5F AUTO
Primary Colour: Purple
Manufacturing Year: 2018
Engine No.: LEB6071731
Chassis No.: GP53416810
Maximum Power Output: 101.0 kW (135 bhp)
Open Market Value: \$20,506.00
Original Registration Date: 31 Oct 2018
First Registration Date: 31 Oct 2018
Transfer Count: 0
Actual ARF Paid: \$10,709.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 30 Oct 2028
PARF Rebate Amount: \$8,031.00

Intended COE Rebate Details

COE Expiry Date: 30 Oct 2028
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$32,429.00
COE Rebate Amount: \$29,020.00
Total Rebate Amount: \$37,051.00

The information contained herein is correct as at 18 Nov 2019

OK

View Received Message

This mail is associated with :

***SMF2787P (4713845494SG)
[GBD8068H]**

TP
LEE MUN KEONG
Nov 16 2019 2:00AM
[POKKA INTERNATIONAL PTE LTD]
New Hock Teck Motor Pte Ltd

Reply	Reply All	Mark as Unread	Print Message	Delete Message	Forward
-------	-----------	----------------	---------------	----------------	---------

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 25/02/2020 14:22 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2708.45) - SMF2787P - Claim Handler: Chan, Kian-Meng

Approved:2708.45:Kindly settle at best

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Nov 2019 Edit Reg		18 Nov 2019 00:00 Edit Adj Rpt	S\$2,300.00 Edit Estimates	S\$2,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	POKKA INTERNATIONAL PTE LTD, Co. Reg. No.: 199800637N								
Main Claimant:	LEE MUN KEONG, ID: S85740833								
Vehicle Reg. No.:	SMF2787P	Date of Loss:	16/11/2019 02:00 - :59 [12 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4713845494SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	GBD8068H	Policy No. (Claimant):	1900160415						
	Excess:								
Repairer:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 28/11/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (25/02/2020): Alert - Adj Mandate Approved (S\$2708.45) - SMF2787P - Claim Handler: Chan, Kian-...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMF2787P (4713845494SG)
 [GBD8068H]
 TP
 LEE MUN KEONG
 Nov 16 2019 2:00AM
 [POKKA INTERNATIONAL PTE LTD]
 New Hock Teck Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown												1			Edit			
Assessment Reports															1 per page			☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print			
1	06/02/20 15:53	Adjuster Immediate Advice												1			Load HTM			
Photos/Images															3 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print			
1	12/12/19 11:54	General View												1			Load JPG			
2	12/12/19 11:54	General View												1			Load JPG			
3	12/12/19 11:54	General View												1			Load JPG			
4	12/12/19 11:54	General View												1			Load JPG			
5	12/12/19 11:54	General View												1			Load JPG			
6	12/12/19 11:54	General View												1			Load JPG			
7	12/12/19 11:54	General View												1			Load JPG			
8	12/12/19 11:54	General View												1			Load JPG			
9	12/12/19 11:54	General View												1			Load JPG			
10	12/12/19 11:54	General View												1			Load JPG			
11	12/12/19 11:54	General View												1			Load JPG			
12	12/12/19 11:54	General View												1			Load JPG			
13	12/12/19 11:58	Reinspection Photo												1			Load JPG			
14	12/12/19 11:58	Reinspection Photo												1			Load JPG			
15	12/12/19 11:58	Reinspection Photo												1			Load JPG			
16	12/12/19 11:58	Reinspection Photo												1			Load JPG			
17	12/12/19 11:58	Reinspection Photo												1			Load JPG			
18	12/12/19 11:58	Reinspection Photo												1			Load JPG			
19	12/12/19 11:58	Reinspection Photo												1			Load JPG			
20	12/12/19 11:58	Reinspection Photo												1			Load JPG			
21	12/12/19 11:58	Reinspection Photo												1			Load JPG			
22	12/12/19 11:58	Reinspection Photo												1			Load JPG			
23	12/12/19 11:58	Reinspection Photo												1			Load JPG			
24	12/12/19 11:58	Reinspection Photo												1			Load JPG			
25	12/12/19 11:58	Reinspection Photo												1			Load JPG			
26	12/12/19 11:58	Reinspection Photo												1			Load JPG			
27	12/12/19 11:58	Reinspection Photo												1			Load JPG			
28	12/12/19 11:58	Reinspection Photo												1			Load JPG			
29	12/12/19 11:58	Reinspection Photo												1			Load JPG			
30	12/12/19 11:58	Reinspection Photo												1			Load JPG			
31	12/12/19 11:58	Reinspection Photo												1			Load JPG			
32	12/12/19 11:58	Reinspection Photo												1			Load JPG			
33	12/12/19 11:58	Reinspection Photo												1			Load JPG			
34	12/12/19 11:58	Reinspection Photo												1			Load JPG			
Documentation															1 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print			

Letters/Correspondences				1 per page	☒
No	Finalized On			Thumbnail	Print
LKK Auto Consultants Pte Ltd (HQ)					
1	19/11/19 15:00	TP GIA REPORT		Load PDF	
2	06/02/20 15:31	TP ESTIMATE - MARKED (FINAL)		Load PDF	
3	06/02/20 15:39	LOD		Load PDF	
4	06/02/20 15:39	LTA SEARCH FEE		Load PDF	
5	05/03/20 09:50	WORKSHOP INVOICE		Load PDF	
6	05/03/20 09:50	AUTHORISATION TO ACT FORM		Load PDF	
7	05/03/20 09:50	Release Voucher		Load PDF	
8	05/03/20 09:50	LETTER TO OI		Load PDF	
AIG Asia Pacific Insurance Pte. Ltd. (SG)					
No	Finalized On			Thumbnail	Print
1	20/11/19 14:39	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBD8068H (Insd veh)	Model:	HONDA FIT 1.5 HYBRID (A)
	SMF2787P (TP veh)		
Date of Accident:	16/11/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	6,368.85
Final Repair Cost	:	\$	2,461.00
Loss of Use	:	\$	240.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	2,708.45

4.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	New Hock Teck Motor Pte Ltd	:	\$ 2,708.45
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

05 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19020475/ADS3Q2

Date: 05/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SMF2787P

Insured Vehicle No : GBD8068H

Date of Loss: 16/11/2019

Nature of Claim: TP

Claim No: 4713845494SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMF2787P

Make & Model: HONDA FIT, 1.5 HYBRID (A)

Engine No: LEB6071731

Reg. Date: 31/10/2018 (Man. Year: 2018)

Chassis No: GP53416810

Colour: Pink

Odometer: 15469 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,702.20	2,289.68	1,412.52	38.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	580.00	1,670.00	74.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,952.20	2,869.68	3,082.52	51.79
Approved Total (Overridden) (S\$)		2,300.00		
(S\$)	5,952.20	2,300.00	3,652.20	61.36
+ GST 7.00/7.00% (S\$)	416.65	161.00	255.65	61.36
Nett Amount (S\$)	6,368.85	2,461.00	3,907.85	61.36
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,708.45		

INSPECTION

Date of Assignment: 18/11/2019

Date Inspected: 18/11/2019 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, Blk C #01-43
 Autobay@Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Cracked	382.90 F	*382.90 FL
2	8		*FRONT GRILLE CLIP	Necessary	52.00 F	*10.00 FL
3	1		*FRONT GRILLE EMBLEM LOGO	Necessary	37.00 F	*37.00 FL
4	1		*FRONT GRILLE TOP CHROME MOULDING	Cut	254.10 F	*254.10 FL
5	1		*FRONT GRILLE LOWER CHROME MOULDING	Cut	265.00 F	*265.00 FL
6	1		*FRONT BUMPER	Deformed	801.50 F	*801.50 FL
7	10		*FRONT BUMPER CLIP	Necessary	65.00 F	*30.00 FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	253.10 F	*- FL
9	1		*FRONT L/H BUMPER SIDE RETAINER	Necessary	25.60 F	*25.60 FL
10	1		*FRONT L/H BUMPER FOG LAMP COVER	Cracked	127.50 F	*127.50 FL
11	1		*FRONT L/H HEADLAMP	Cut	901.50 F	*901.50 FL
12	1		*FRONT L/H HEADLAMP LOWER BRACKET	Cracked	27.00 F	*27.00 FL
13	1		*FRONT L/H FENDER	Not Necessary	408.50 F	*- FL
14	1		*FRONT L/H FENDER COWLING	Not Necessary	101.50 F	*- FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	3,702.20	2,862.10
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	572.42
Total Parts (\$\$)	3,702.20	2,289.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	100.00	30.00
2	TUFF KOTE	New	150.00	0.00
3	PANEL BEATING	New	1,000.00	300.00
4	SPRAY PAINTING	New	1,000.00	250.00
Gross Labour Cost (S\$)			2,250.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >