

LCRF Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

MS AIG Asia Pacific Insurance Pte Ltd

Date: 19/11/2019

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLG7543A

CHASSIS NO : NHP1707037637

MAKE / MODEL : Toyota Sienta Hybrid 1.5 G CVT

DATE OF ACCIDENT : 15/11/2019

YOUR INSURED VEHICLE NUMBER : SMM2924Z

MILEAGE: 186499 km

<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1 F/L door / DO.	1PC	\$ 1,610.00	\$ 1,610.00
		LIST TOTAL S\$:	\$ 1,610.00
		25%DISCOUNT S\$:	\$ 402.50
			\$ 1,207.50

<u>SPECIAL NETT</u>			
1 Front bumper clips	1 SET / nec.	\$ 100.00	30
2 F/Lwheel rim	1PC / SCR.	\$ 250.00	80
Special Nett Total S\$:		\$ 350.00	

<u>LABOUR CHARGES</u>			
1 To labour charge for removing out F/L door and F/L fender out to facilitate replacement of damaged parts		\$ 900.00	400
2 To respray F/L fender, F/L door and front bumper		\$ 700.00	400 500
3 To apply rustproofing on all replacement parts		\$ 180.00	X
4 To conduct 4 wheel alignment		\$ 200.00	60
LABOUR TOTAL S\$:		\$ 1,980.00	
TOTAL S\$:		\$ 3,537.50	
7% GST		\$ 247.63	
GRAND TOTAL S\$:		\$ 3,785.13	

Repair days - 4 days.

Lump Sum Repair.

After spray photo.

Sun Pin

19/11/2019.

TP without prejudice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: