



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS/INC19020491/Kvd3e2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date : 13-12-2019

189556



ATTN : JARED LIU

Code : INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJM 5479H	Veh. Inspected	SKV 8059H
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1070409-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	19/11/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ B180 (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD2462422J356679	Colour	WHITE
Odometer	99083	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	PIRELLI	8 mm
L/H Front Tyre	205/55 R16	PIRELLI	8 mm
R/H Rear Tyre	205/55 R16	PIRELLI	7 mm
L/H Rear Tyre	205/55 R16	PIRELLI	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	07/11/2019	Inspection Date	19/11/2019
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------