

ASS. REC. BY: _____ REF: ES/INC19020491/Krd301 Special Instruction: _____

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Hazelysa Bt Ibrahim of INC Date/Time: 19/11/2019 9:52am

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKV 8059H Insured: 8JM 5479H

at Workshop in/s Tong Luck Auto Tel: 6250 0088.

of 160 Sin Ming Drive # 07-01

Policy No: _____ Claim No: MT/1070409-002

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 7/11/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 10:15am @ 19/11/19 Person Contacted: candy H.O.D. Endorsement: _____

Vehicle: IN/OUT

Date/Time	Action/Instruction
	<u>Johnnie</u>
	<u>SKV 8059H -X</u>
	<u>8JM 5479H -X.</u>
<u>9/12</u>	<u>112m @ 39001 Confirm (Red 6370.80, 6270)</u>

REF: 122/

Kenneth

From: _____ Date: _____

Veh No: JKV 805914 Yr Regn: 10, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Wagon
MC B180 C.C. 1595

Make: Mc B180 C.C. 1585
Colour: White A/C: Insured / Std / Nil / NA

Sp. Reading 99083 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: WDD 2462422 J 3 56678
Gen. Cond: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In ~~order~~ / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD ~~A/R~~lm or

Tyre Size: F: 205/55R16
R: _____

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
TOYO/YOKO or

Front  Rear 

R/Bal.  mm R/Bal.  mm

L/Bal. 9 mm

D.O.A. 7/11/19 D.O.I. 19/4/19

Survey held at _____ ✓ 1111 AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 & B

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

1	File pass -
---	-------------

RECEIVED 9 9 DEC 2019

Date/Time, File Pass to?

☐: *Prell. Report*

11

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

Transportation:

___ S - R.S. ___ SI

Add Fee: ☐ : Site Insp (\$

☐: Interview (\$

) 7.4.25

	Tech Invs (\$)
1980-84	16.7
1985-89	17.5
1990-94	18.3
1995-99	19.1
2000-04	19.9
2005-09	20.7
2010-14	21.5
2015-19	22.3
2020-24	23.1
2025-29	23.9
2030-34	24.7
2035-39	25.5
2040-44	26.3
2045-49	27.1
2050-54	27.9
2055-59	28.7
2060-64	29.5
2065-69	30.3
2070-74	31.1
2075-79	31.9
2080-84	32.7
2085-89	33.5
2090-94	34.3
2095-99	35.1
2100-04	35.9
2105-09	36.7
2110-14	37.5
2115-19	38.3
2120-24	39.1
2125-29	39.9
2130-34	40.7
2135-39	41.5
2140-44	42.3
2145-49	43.1
2150-54	43.9
2155-59	44.7
2160-64	45.5
2165-69	46.3
2170-74	47.1
2175-79	47.9
2180-84	48.7
2185-89	49.5
2190-94	50.3
2195-99	51.1
2200-04	51.9
2205-09	52.7
2210-14	53.5
2215-19	54.3
2220-24	55.1
2225-29	55.9
2230-34	56.7
2235-39	57.5
2240-44	58.3
2245-49	59.1
2250-54	59.9
2255-59	60.7
2260-64	61.5
2265-69	62.3
2270-74	63.1
2275-79	63.9
2280-84	64.7
2285-89	65.5
2290-94	66.3
2295-99	67.1
2300-04	67.9
2305-09	68.7
2310-14	69.5
2315-19	70.3
2320-24	71.1
2325-29	71.9
2330-34	72.7
2335-39	73.5
2340-44	74.3
2345-49	75.1
2350-54	75.9
2355-59	76.7
2360-64	77.5
2365-69	78.3
2370-74	79.1
2375-79	79.9
2380-84	80.7
2385-89	81.5
2390-94	82.3
2395-99	83.1
2400-04	83.9
2405-09	84.7
2410-14	85.5
2415-19	86.3
2420-24	87.1
2425-29	87.9
2430-34	88.7
2435-39	89.5
2440-44	90.3
2445-49	91.1
2450-54	91.9
2455-59	92.7
2460-64	93.5
2465-69	94.3
2470-74	95.1
2475-79	95.9
2480-84	96.7
2485-89	97.5
2490-94	98.3
2495-99	99.1
2500-04	99.9
2505-09	100.7
2510-14	101.5
2515-19	102.3
2520-24	103.1
2525-29	103.9
2530-34	104.7
2535-39	105.5
2540-44	106.3
2545-49	107.1
2550-54	107.9
2555-59	108.7
2560-64	109.5
2565-69	110.3
2570-74	111.1
2575-79	111.9
2580-84	112.7
2585-89	113.5
2590-94	114.3
2595-99	115.1
2600-04	115.9
2605-09	116.7
2610-14	117.5
2615-19	118.3
2620-24	119.1
2625-29	119.9
2630-34	120.7
2635-39	121.5
2640-44	122.3
2645-49	123.1
2650-54	123.9
2655-59	124.7
2660-64	125.5
2665-69	126.3
2670-74	127.1
2675-79	127.9
2680-84	128.7
2685-89	129.5
2690-94	130.3
2695-99	131.1
2700-04	131.9
2705-09	132.7
2710-14	133.5
2715-19	134.3
2720-24	135.1

1. Others

Weekend (\$)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

TP

3900/2

Nivitha (LKK Auto)

From: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Sent: Tuesday, 19 November 2019 3:26 PM
To: Admin-D (LKKAuto); assignments
Cc: Hazalya Binte Ibrahim
Subject: RE: TP CASES FARMED OUT TO LKK ON 19/11/2019

Dear LKK,

Re-send with details.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Operations, Motor & Personal Lines (PL)
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

From: Hazalya Binte Ibrahim
Sent: Tuesday, 19 November 2019 9:52 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Alice Low <alice.lowkc@income.com.sg>
Subject: TP CASES FARMED OUT TO LKK ON 19/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Serene Lim	MT/1071694-002	SLR1040R	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		SJP7344J	16/11/19	
2	Eng Huey Huey	MT/1071605-001	SLD8452M	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		SJN6985B	15/11/19	
3	Serene Lim	MT/1071721-001	SLF9471R	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		PC601K	15/11/19	
4	Azhari	MT/1071695-002	SLL3057L	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		SLZ3659B	15/11/19	
5	Eng Huey Huey	MT/1071993-001	SLA1405J	OPTIMA WERKZ PTE LTD	9A SERANGOON NORTH AVE 5	Sharon Ten / 6481 1522		SJU5625K	17/11/19	avoid 1PM - 2PM
6	Wo Jessie	MT/1071949-001	SHC3281A	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SLN9343K	16/11/19	65425119 or 6542 7162
7	Quek Swee Keng	MT/1071863-002	SHD3009R	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SMK5648L	16/11/19	65425119 or 6542 7162
8	Quek Swee Keng	MT/1071765-002	SHA7757D	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SJN4823Z	16/11/19	65425119 or 6542 7162
9	Serene Lim	MT/1070016-002	EW3366U	TROPICAL SUCCESS AUTO CARE	BLK 5032 #01-299/303 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569535	Calvin / 64817773		SLG4655E	05/11/19	
10	Muhammad Airwan	MT/1071969-001	YP9666P	WENG KEE MOTOR	BLK 1019 #01-366 YISHUN INDUSTRIAL PARK A	Victor Wong Qi Zhi / 6854 1273 / 8182 1895		SJL9527G	07/11/19	
11	Jeff Lin	MT/1071637-002	SGK775G	AT AUTO CONSULTANT	BLK 01 SIN MING INDUSTRIAL ESTATE	Alan Tan / 8386989		SKD8863Y	15/11/19	

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	778Z
Vehicle Details	
Vehicle No.:	SKV8059H
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Nov 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	B180 STYLE (R16 LED)
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	27091030768740
Chassis No.:	WDD2462422J356679
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$25,384.00
Original Registration Date:	01 Oct 2015
First Registration Date:	01 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$22,538.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Sep 2025
PARF Rebate Amount:	\$16,903.00
Intended COE Rebate Details	
COE Expiry Date:	30 Sep 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,209.00
COE Rebate Amount:	\$32,944.00
Total Rebate Amount:	\$49,847.00

The information contained herein is correct as at 20 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/11/2019 14:35
Date Of Accident	07/11/2019 08:05
Exact Location Of Accident	ALG MARYMOUNT RD TOWARDS TOA PAYOH
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKV8059H
Insured/Policyholder	
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD
Co Reg No	199803778Z
Email Address	EUGENE.KOH@DAIMLER.COM
Mobile Phone No	
Alternative Phone No	OFFICE-82821711
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	B180 STYLE (R16 LED)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995580
Cover Note Number	
Driver	
Name of Driver	YONG KIM SIONG
NRIC No	S6938641E
Date Of Birth	03/11/1969
Occupation	INDOOR
Date Of Driving Pass	28/10/1992
Driving Experience	27 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81273609
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was stationary in queue in the middle lane as there was traffic ahead. Suddenly I felt a big impact from my rear vehicle. The impact made my vehicle moved forward and eventually hit the rear of the vehicle ahead of mine. I was actually quite a safe distance from the vehicle ahead and I had my foot on my brake pedal at that point of time. All vehicles stop and we exchange particulars. No injury involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM5479H
Vehicle Make/Model/Colour	TOYOTA / WISH 1.8 AUTO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAY TECK HUI
NRIC/Passport Number	S6823885D
Contact Number	85812038
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMC4376U
Vehicle Make/Model/Colour	HONDA / SHUTTLE 1.5G CVT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG HUI LI FELICIA
NRIC/Passport Number	S6824739Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

SKV8059H

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: **7/11/19, 1:20**
PM

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMMAD AZALY BIN ABDULLAH

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Sketch Plan #2

SKETCH PLAN

MARYMOUNT RD.



A-SKV8059H
(STATIONARY)

B-SJM5479H

C-SMC4376U
(STATIONARY)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 7/11/19.

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMMAD AZALY BIN ABDULLAH

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #3

ACCIDENT STATEMENT (2000 characters)

I was stationary in queue in the middle lane as there was traffic ahead. Suddenly I felt a big impact from my rear vehicle. The impact made my vehicle moved forward and eventually hit the rear of the vehicle ahead of mine. I was actually quite a safe distance from the vehicle ahead and I had my foot on my brake pedal at that point of time.

All vehicles stop and we exchange particulars.

No injury involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMMAD AZALY BIN ABDULLAH

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

7 November 2019 at 1:20 PM

Date/Time:

7 November 2019 at 1:20 PM



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO :

CLAIM TYPE : THIRD PARTY

TP INS. CO. : NTUC INCOME INSURANCE CO-OPERATIVE LT REG. DATE : 2015

ACCIDENT DATE : 07/11/2019

TP VEH REG NO : SJM5479H

ESTIMATE

NO : QUOT201911-000045(00)

DATE : 15/11/2019

POLICY NO : 999995580

VEH REG NO : SKV8059H

MAKE/MODEL : MERCEDES BENZ B180 STYLE
(R16 LED)

CHASSIS NO : WDD2462422J356679

ENGINE NO : 27091030768740

REG. DATE : 2015

*Not Authorized
After
Primary Repair
6/11/19 @ ?*

4 days

Estimate Repair Cost to Vehicle No : SKV8059H

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Support panel	1	658.00	658.00
2 Front bumper	1	1,425.00	1,425.00
3 Front bumper reinforcement	1	330.00	330.00
4 Front bumper sponge	1	140.00	140.00
5 Front bumper basic mounting	1	158.00	158.00
6 Front bumper centre logo	1	65.00	65.00
7 Front bumper lower chrome	1	195.00	195.00
8 Front bumper sensor	2	188.00	376.00
9 Front bumper sensor seals	6	12.00	72.00
10 Front bumper clips	15	9.00	135.00
11 Front number plate garnish	1	105.00	105.00
12 Front grille	1	170.00	170.00
13 Front grille emblem	1	138.00	138.00
14 Front grille emblem base	1	78.00	78.00
15 Front grille beam	1	173.00	173.00
16 Rear bumper	1	1,520.00	1,520.00
17 Rear bumper reinforcement	1	480.00	480.00
18 Rear bumper sensor	2	188.00	376.00
19 Rear bumper sensor seals	6	12.00	72.00
20 Rear bumper lower spoiler	1	155.00	155.00
21 Rear bumper lower chrome	1	211.00	211.00
22 Rear bumper step chrome	1	245.00	245.00
23 Rear bumper clips	15	9.00	135.00
			7,412.00
		Less 10%	741.20
			6,670.80
SPECIAL NET			
24 Front number plate	1	40.00	40.00
			40.00
LABOUR			
25 To remove and refix air-con condenser, pipes, radiator assy, top up air-con gas	1	150.00	150.00
26 To remove and refix front bumper sensor, rear bumper sensor	1	200.00	200.00
27 To check and rectify wiring system	1	80.00	80.00

(Silver)

10d

120

4d



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO :

CLAIM TYPE : THIRD PARTY

TP INS. CO. : NTUC INCOME INSURANCE CO-OPERATIVE LT REG. DATE : 2015

ACCIDENT DATE : 07/11/2019

TP VEH REG NO : SJM5479H

ESTIMATE

NO : QUOT201911-000045(00)

DATE : 15/11/2019

POLICY NO : 999995580

VEH REG NO : SKV8059H

MAKE/MODEL : MERCEDES BENZ B180 STYLE
(R16 LED)

CHASSIS NO : WDD2462422J356679


ENGINE NO : 27091030768740

REG. DATE : 2015

Estimate Repair Cost to Vehicle No : SKV8059H

Description	Quantity	Unit Price	Amount
		S\$	S\$
28 To panel beat and straighten front chassis frame, rear end panel, rear floorboard panel, rear chassis frame including replacement of parts and align where necessary, to refit and adjust the same	1	1,500.00	1,500.00
29 To putty and spray same on affected areas	1	1,200.00	1,200.00
30 To apply rust proofing on repaired and replaced panels	1	80.00	80.00
31 To reset and re-programme headlamp faulty code	1	350.00	350.00
			3,560.00
		TOTAL	S\$ 10,270.80
		ADD GST @ 7%	718.96
		GRAND TOTAL	S\$ 10,989.76

SINGAPORE DOLLAR TEN THOUSAND NINE HUNDRED EIGHTY-NINE AND CENTS SEVENTY-SIX ONLY



FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19020491/Kvd3e2

73 BRAS BASAH ROAD

Date: 13-12-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN : JARED LIU

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJM 5479H	Veh. Inspected	SKV 8059H
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1070409-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	19/11/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ B180 (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD2462422J356679	Colour	WHITE
Odometer	99083 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	PIRELLI	8 mm
L/H Front Tyre	205/55 R16	PIRELLI	8 mm
R/H Rear Tyre	205/55 R16	PIRELLI	7 mm
L/H Rear Tyre	205/55 R16	PIRELLI	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	07/11/2019	Inspect Date / Time	19/11/2019 (11:11 AM)
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 8059H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SUPPORT PANEL (N)	CRACKED	658.00	658.00
1	FRONT BUMPER (N)	BUCKLED	1,425.00	1,425.00
1	FRONT BUMPER REINFORCEMENT (N)	BENT	330.00	330.00
1	FRONT BUMPER SPONGE (N)	CRACKED	140.00	140.00
1	FRONT BUMPER BASIC MOUNTING (N)	SERVICEABLE	158.00	-
1	FRONT BUMPER CENTRE LOGO (N)	NECESSARY	65.00	65.00
1	FRONT BUMPER LOWER CHROME (N)	SERVICEABLE	195.00	-
2	FRONT BUMPER SENSOR @\$188.00 (N)	SERVICEABLE	376.00	-
6	FRONT BUMPER SENSOR SEALS @\$12.00 (N)	NECESSARY	72.00	72.00
15	FRONT BUMPER CLIPS @\$9.00 (N)	NECESSARY	135.00	135.00
1	FRONT NUMBER PLATE GARNISH (N)	DENTED	105.00	105.00
1	FRONT GRILLE (N)	CRACKED	170.00	170.00
1	FRONT GRILLE EMBLEM (N)	MISSING	138.00	138.00
1	FRONT GRILLE EMBLEM BASE (N)	CRACKED	78.00	78.00
1	FRONT GRILLE BEAM (SILVER) (N)	DENTED	173.00	173.00
1	REAR BUMPER (N)	TO REPAIR SEE LABOUR	1,520.00	-
1	REAR BUMPER REINFORCEMENT (N)	TO REPAIR SEE LABOUR	480.00	-
2	REAR BUMPER SENSOR @\$188.00 (N)	SERVICEABLE	376.00	-
6	REAR BUMPER SENSOR SEALS @\$12.00 (N)	SERVICEABLE	72.00	-
1	REAR BUMPER LOWER SPOILER (N)	SERVICEABLE	155.00	-
1	REAR BUMPER LOWER CHROME (N)	SERVICEABLE	211.00	-
1	REAR BUMPER STEP CHROME (N)	NECESSARY	245.00	245.00
15	REAR BUMPER CLIPS @\$9.00 (N)	NOT NECESSARY	135.00	-
	LESS 10% DISCOUNT		-741.20	-373.40
			6,670.80	3,360.60
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	BENT	40.00	40.00
			40.00	40.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE AND REFIX AIR-CON CONDENSER, PIPES, RADIATOR ASSY, TOP UP AIR-CON GAS.		150.00	100.00
	TO REMOVE AND REFIX FRONT BUMPER SENSOR, REAR BUMPER SENSOR.		200.00	120.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	40.00
	TO PANEL BEAT AND STRAIGHTEN FRONT CHASSIS FRAME, REAR END PANEL, REAR FLOORBOARD PANEL, REAR CHASSIS FRAME INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR BUMPER REINFORCEMENT.		1,500.00	500.00
	TO PUTTY AND SPRAY SAME ON AFFECTED AREAS.		1,200.00	500.00
	TO APPLY RUST PROOFING ON REPAIRED AND REPLACED PANELS.	NOT NECESSARY	80.00	-
	TO RESET AND RE-PROGRAMME HEADLAMP FAULTY CODE.		350.00	220.00
			3,560.00	1,480.00
	GRAND TOTAL		10,270.80	4,880.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,900.00

Report Ref No. CS/INC19020491/Kvd3e2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.