

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721


Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: RENAULT GRAND SCENIC
 Engine/Chassis No.: VF1RFA00761665863
 Date of accident:
 Damaged area: O/S Rear

Date: 19/11/2019

Claim Type: TP

VRN: SMG4160D



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Rear Bumper upper ✓ cut	1	\$ 1,650.00	\$ 1,650.00	1281.32 480
2	Rear Bumper lower ✓ cut	1	\$ 752.00	\$ 752.00	
3	Rear Bumper tow cover X nn	1	\$ 85.00	\$ 85.00	
4	Rear bumper side retainer X nn	2	\$ 85.00	\$ 170.00	
5	Rear Bumper reflector o/s X nn	1	\$ 186.00	\$ 186.00	
6	Rear Bumper lower moulding X nn	1	\$ 551.00	\$ 551.00	
7	Rear Bumper inner pad X nn	1	\$ 345.00	\$ 345.00	
8	Rear Bumper reinforcement X nn	1	\$ 769.00	\$ 769.00	
9	Rear Bumper side support X nn	2	\$ 154.00	\$ 308.00	
10	Rear Bumper Centre support X nn	2	\$ 147.00	\$ 294.00	
11	Rear Bumper side cover X nn	2	\$ 484.00	\$ 968.00	
12	Rear bumper lower cowling X nn	1	\$ 337.00	\$ 337.00	
13	Rear fender inner cowling o/s X nn	1	\$ 243.00	\$ 243.00	
14	Rear fender splash guard o/s X nn	1	\$ 56.00	\$ 56.00	
15	Rear fender air vent o/s X nn	1	\$ 216.00	\$ 216.00	
16	Rear wheel bearing o/s X nn	1	\$ 396.00	\$ 396.00	
17	Rear knuckle o/s X nn	1	\$ 573.00	\$ 573.00	
18	Rear shock absorber o/s X nn	1	\$ 499.00	\$ 499.00	
19	Rear shock absorber top mount o/s X nn	1	\$ 85.00	\$ 85.00	
Subtotal				\$ 8,483.00	1761.32
List discount				10.00%	
Total				\$ 7,634.70	1585.18

Special nett items					
No.	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Rear fender inner cowling clips o/s X nn	8	\$ 6.50	\$ 52.00	
2	Rear Bumper clips ✓ nec	10	\$ 6.50	\$ 65.00	40
3	Reverse sensor X nn	2	\$ 280.00	\$ 560.00	
4	Rear alloy wheel 20" o/s ✓ scr	1	\$ 550.00	\$ 550.00	100(local repair)
5	Rear tyre 20" o/s X nn	1	\$ 380.00	\$ 380.00	
6	Sundries X nn	1	\$ 50.00	\$ 50.00	
Total				\$ 1,657.00	140

Repair Estimate

Labour				
No.	Description	Work unit	Amount	
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$ 1,000.00	200
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00	× nn
3	To remove and refit o/s rear tyre & rim. To perform tyre balancing.	0.25	\$ 50.00	20
4	To remove and refit o/s rear undercarriage for replacement of parts.	1	\$ 200.00	× nn
5	Supply spray paint material and necessary items to respray rear bumper, end panel, o/s rear fender and other affected area / panel.	4	\$ 800.00	200
6	To rust proof all affected portions after repair.	0.5	\$ 100.00	× nn
7	To conduct computerized wheel alignment.	0.5	\$ 100.00	60
Total labour			\$ 2,300.00	480
Estimate Grand Total			\$ 11,591.70	

2205.18

20%: 1750

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____