

ASS. REC. BY:

REF: 08/INC19020505/ Dyd3 | n2
Special Instructions

Survey: Bryon

ASSIGNMENT (Office)

From (Person): Hardysa B Ibrahim of INC Date/Time: 9:52am @ 19/11/19

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHA 7757D Insured: BJN 48232

at Workshop m/s: 800n Hycle Motor Tel: 6542 5119

of Blk 10 Avank Ind. Phase 2A # 01-05/06

Policy No: _____ Claim No: MT/1071765-002

Sum Insured: _____ Excess: _____

Make of Vch: _____ D.O.A. 16/11/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 9:59am @ 19/11/19 Person Contacted: Lynn Vehicle: IN OUT


Date/Time	Action/Instruction
	<u>Johny</u>
	<u>SHA 7757D - MBA / 11/11/19 18:156 / 64</u>
	<u>BJN 48232 - X</u>

D.O.A. 19/08/2019

CDE May 2023
2015 May

ASSIGNMENT

From: _____
To: _____
Insured: _____
Policy No: _____
Claims No: _____
Date Insured: _____
(Client's Record)
Make of Veh: _____



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: _____
IDAC Accident Report Consistent? : Yes or No
GIA / PR Seen Consistent? : Yes or No
Est. Repair: 6 days Res: Yes or No
Turn Date: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Veh No: SHA 7757 D
Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /
Truck / Trailer or
Motor: Hyundai I40
Color: Blue
Sp. Reading: 601049
Eng No: D4FDFU503323
C/Nr: KMHLB41UMFU069420
Car. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brakes: In order / Jammed / Leaked / Burnt or
Mod: Nil / SRim / STD A/Rim or

Tyre Size: F: 205/60 R16
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Westlake

Front: _____ Rear: _____
R/Bal: 5 mm L/Bal: 5 mm
D.O.A: 12/11/2019 D.O.I: 19/11/2019
Survey hold at Churni MK

Dist. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rw o/s
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

HTUC SJN 48232

07/01/2020 Jmayer 2/5 11000/- with 6 days of rev (Red \$8799-18, 49%)

RECEIVED 08 JAN 2020

Date/Time, File Pass to: ☐ : Prelim. Report

h) ☐ : Final Report

Date/Time, File Return to:

7/1/20 Typist

Report Form:

Lump Sum: \$11,000/-

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Insp (\$) ☐ Wheel and

Survey Fee:

Transportation

\$ + 15% 50

Police

Others

04/21

250

Nivitha (LKK Auto)

From: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Sent: Tuesday, 19 November 2019 3:26 PM
To: Admin-D (LKKAuto); assignments
Cc: Hazalya Binte Ibrahim
Subject: RE: TP CASES FARMED OUT TO LKK ON 19/11/2019

Dear LKK,

Re-send with details.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Operations, Motor & Personal Lines (PL)
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

From: Hazalya Binte Ibrahim
Sent: Tuesday, 19 November 2019 9:52 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Alice Low <alice.lowkc@income.com.sg>
Subject: TP CASES FARMED OUT TO LKK ON 19/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Serene Lim	MT/1071694-002	SLR1040R	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		SIP7344J	16/11/19	
2	Eng Huey Huey	MT/1071605-001	SLD8452M	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		SJNG985B	15/11/19	
3	Serene Lim	MT/1071721-001	SIF9471R	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		PC601K	15/11/19	
4	Azhari	MT/1071695-002	SLL3057L	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		SLZ3659B	15/11/19	
5	Eng Huey Huey	MT/1071993-001	SLA1405J	OPTIMA WERKZ PTE LTD	9A SERANGOON NORTH AVE 5	Sharon Ten / 6481 1522		SJU5625K	17/11/19	avoid 1PM - 2PM
6	Wo Jessie	MT/1071949-001	SHC3281A	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SLN9343K	16/11/19	65425119 or 6542 7162
7	Quek Swee Keng	MT/1071863-002	SHD3009R	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SMK5048L	16/11/19	65425119 or 6542 7162
8	Quek Swee Keng	MT/1071765-002	SHA7757D	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SJN4823Z	16/11/19	65425119 or 6542 7162
9	Serene Lim	MT/1070016-002	EW3366U	TROPICAL SUCCESS AUTO CARE	BLK 5032 #01-299/303 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569535	Calvin / 64817773		SLG4655E	05/11/19	
10	Muhammad Airwan	MT/1071969-001	YP9666P	WENG KEE MOTOR	BLK 1019 #01-366 YISHUN INDUSTRIAL PARK A	Victor Wong Qi Zhi / 6854 1273 / 8182 1895		SJL9527G	07/11/19	
11	Jeff Lin	MT/1071637-002	SGK775G	AT AUTO CONSULTANT	BLK 01 SIN MING INDUSTRIAL ESTATE	Alan Tan / 83868989		SKD8863Y	15/11/19	

[illegible]

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg



in with
you

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at Income.com.sg/careers

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHA7757D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Nov 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	I40 1.7L CRDI AT ABS AIRBAG 4DR
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	D4DFU503323
Chassis No.:	KMHLB41UMFU069420
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$19,793.00
Original Registration Date:	30 May 2015
First Registration Date:	30 May 2015
Transfer Count:	0
Actual ARF Paid:	\$12,293.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 May 2023
PARF Rebate Amount:	\$9,219.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,756.00
COE Rebate Amount:	\$22,325.00
Total Rebate Amount:	\$31,544.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 22 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/11/2019 09:45
Date Of Accident	16/11/2019 12:00
Exact Location Of Accident	PIONEER RD NORTH TWDS AYE JUST AFTER JURONG WEST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA7757D
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH

Cover Note Number

Driver

Name of Driver	SEE CHET PIN
NRIC No	S0117247F
Date Of Birth	15/08/1954
Occupation	OUTDOOR
Date Of Driving Pass	25/10/1974
Driving Experience	45 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98384584
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 672A JURONG WEST STREET 65 #02-132
Postcode	641672
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJN4823Z
Vehicle Make/Model/Colour	MITSUBISHI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LOUIS THAM KIM SENG
NRIC/Passport Number	
Contact Number	90226188
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT LH
No. Of Passenger (Including Driver)	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: **Loke vver Tieng**
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16/11/19 at about 12.00 hrs, I
 Veh A stopped at above said location
 to pick up passenger. Suddenly I felt an
 impact from behind. I went down to have a
 check and found Veh B in front left portion
 collided onto the rear right portion of my
 stationary taxi. The passenger get to board my
 taxi. No injury at the point of accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 COMFORT TRANSPORTATION PTE LTD
 CO. REG. NO. 199303821R

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name: Loke Wei Yeng
 NRIC/FIN No.:

GIARMC SketchPlanForm_V3

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 7757 D

Technician:

Mileage: 601074

Time Printed 19.11.19 11:42 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°02'		-3°00' 3°00'
4°34'		-0°19' 5°41'
0°25'		-1°30' 1°30'
20°20'		
20°18'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°55'		-3°00' 3°00'
4°54'		-0°19' 5°41'
-0°30'		-1°30' 1°30'
15°24'		
14°29'		

Front

	Actual	BEFORE	Specified Range
Cross Camber	0°53'		-3°00' 3°00'
Cross Caster	-0°20'		-3°00' 3°00'
Cross SAI	4°56'		-3°00' 3°00'
Total Toe	-0°06'		-3°00' 3°00'
Cross Turn Diff.			

Rear : Left

Actual	BEFORE	Specified Range
2°20'		-3°30' 2°30'
0°07'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°33'		-3°30' 2°30'
2°24'		-1°30' 1°30'

Rear

	Actual	BEFORE	Specified Range
Cross Camber	3°53'		-3°00' 3°00'
Total Toe	2°31'		-3°00' 3°00'
Thrust Angle	-1°08'		-3°00' 3°00'

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7757D

DATE : 18.11.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Wine

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid			\$ 2,174.90	✓
	Boot Lid Rubber			\$ 96.50	X
	Boot Lid Lock Upper			\$ 102.60	X
	Boot Lid Lock Lower			\$ 31.70	X
	Boot Lid 'H' Emblem			\$ 28.70	✓
	Boot Lid CRDI Plate			\$ 27.90	✓
	Boot Lid Lamp (RH)			\$ 565.60	✓
	Boot Lid Trimboard			\$ 116.40	X
	Boot Lid Trimboard Clips (10pcs)			\$ 11.00	X
	Bootlid Moulding			\$ 85.00	X
	Bootlid i40 Emblem			\$ 27.90	X
	Bootlid Lower Garnish			\$ 227.90	X
	Rear Bumper			\$ 553.00	✓
	Rear Bumper Reinforcement			\$ 428.40	✓
	Rear Bumper Reinforcement Bracket (LH/RH)	0/3 N/S	\$ 80.30	\$ 160.60	✓
	Rear Bumper Clip 10 pcs			\$ 22.00	✓
	Rear Bumper Bracket	broken 0/3 N/S	\$ 35.60	\$ 71.20	✓
	Rear Bumper Sponge			\$ 118.40	✓
	Rear Bumper Under Cover			\$ 228.00	✓
	Rear Bumper Reflector Lamp (RH)			\$ 30.60	✓
	Tail Lamp (RH)			\$ 697.80	✓
	Tail Lamp Quarter Panel (RH)			\$ 226.50	✓
	Exhaust Pipe Insulator		\$ 58.55	\$ 117.10	X
	Exhaust Silencer	0/3 N/S	\$ 967.70	\$ 1,935.40	✓
	Exhaust Pipe Hanger		\$ 58.55	\$ 117.10	X
	Exhaust Pipe Centre			\$ 730.10	X
	Rear Fender With Housing (RH)			\$ 4,736.80	✓
	Rear Fender Inner Lining (RH)			\$ 169.30	✓
	Rear Fender Air-Duct			\$ 51.60	X
	Rear Windscreen Moulding			\$ 28.30	✓
	Rear Tyre Rim (RH)			\$ 325.30	✓
	Rear Wheel Hub-Cap (RH)			\$ 107.10	✓
	Rear Wheelbearing IN & Hub			\$ 362.00	✓
	Rear Trailing Arm (RH)			\$ 192.00	✓
	Rear Assist (RH)			\$ 145.70	✓
	Rear Shock Absorber (RH)			\$ 276.30	✓
	Rear Shock Absorber Mounting (RH)			\$ 81.30	X
	Rear Crossmember			\$ 1,021.50	X
	Stabilizer Bar			\$ 199.60	X
	Stabilizer Link			\$ 85.90	X
	Rear Upper Arm (RH)			\$ 335.75	✓
	Rear Lower Arm (RH)			\$ 353.80	✓
	Rear Knuckle Arm (RH)			\$ 545.60	✓
	SUB TOTAL			\$ 17,950.15	
	LESS 20%			\$ 3,590.03	
	DISCOUNTED TOTAL			\$ 14,360.12	

13536.85
10829.48

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid Comfort Logo & Tel No. Sticker <i>New</i>			S 30.00	Nett ✓
	Boot Lid Advertisement Logo <i>New</i>			S 100.00	Nett ✓
	Rear Bumper Reverse Sensor <i>Down</i>			S 135.70	Nett ✓
	Rear Bumper Advertisement Logo <i>New</i>			S 50.00	Nett ✓
	Rear Bumper Rubber Mat <i>New</i>			S 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>New</i>		S 100.00	S 200.00	Nett ✓
	Rear Windscreen Sealant <i>New</i>			S 46.00	Nett ✓
	Rear Tyre (RH) <i>New</i>		611.70	S 216.00	Nett X
				S 827.70	
	Labour Charge				
	Panel Beating			S 1,200.00	700/-
	Spray Painting Charge			S 1,000.00	600/-
	Wiring Charge			S 50.00	30/-
	Tuff Kote			S 50.00	40/-
	Towing Charge			S 50.00	40/-
	Remove/Refix Cushion & Upholstery Rear			S 150.00	80/-
	Remove/Refix Rear Windscreen Glass		1990.00	S 120.00	80/-
	Remove/Refix Reverse Sensor			S 120.00	40/-
	Remove/Refix Fuel Tank			S 150.00	40/-
	Remove/Refix Exhaust Pipe			S 300.00	60/-
	Remove/Refix Undercarriage (RR)			S 200.00	150/-
	Rear Wheel Alignment			S 120.00	60/-
	Re-set Rear ABS System			S 200.00	150/-
	Diagnostic & Resetting To Erase Fault Code			S 480.00	150/-
	TOTAL LABOUR			S 4,190.00	
	ESTIMATE TOTAL			S 19,377.82	19799.18
	19/11/2019 @ 1030am		13431.18		
	NA Amount		Supp 421.36		
	1/5mm		13852.54		
	6 days.				
	yan				
	LKK Auto				
	LKK Auto Consultants hence notify the Repairer of the following: • To survey before/after spray painting • To display damaged part(s) during survey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be returned and				
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				
	Signature:				
	Date:				

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7757D (Supplementary)

DATE : 21.11.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Panel <i>Dented</i>			\$ 526.70
	SUB TOTAL			\$ 526.70
	LESS 20%			\$ 105.34
	DISCOUNTED TOTAL			\$ 421.36
	 LKK Auto 			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19020505/Dyd3n2

73 BRAS BASAH ROAD

Date: 13-01-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN: QUEK SWEE KENG

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJN 4823Z	Veh. Inspected	SHA 7757D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1071765-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	19/11/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KMHLB41UMFU069420	Colour	BLUE
Odometer	601049 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/11/2019	Inspect Date / Time	19/11/2019 (05:11 PM)
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND, PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7757D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOT LID	BENT	2,174.90	2,174.90
1	BOOT LID RUBBER	SERVICEABLE	96.50	-
1	BOOT LID LOCK UPPER	SERVICEABLE	102.60	-
1	BOOT LID LOCK LOWER	SERVICEABLE	31.70	-
1	BOOT LID "H" EMBLEM	NECESSARY	28.70	28.70
1	BOOT LID CRDI PLATE	NECESSARY	27.90	27.90
1	BOOT LID LAMP (RH)	CRACKED	565.60	565.60
1	BOOT LID TRIMBOARD	NOT NECESSARY	116.40	-
10	BOOT LID TRIMBOARD CLIPS	NOT NECESSARY	11.00	-
1	BOOTLID MOULDING	SERVICEABLE	85.00	-
1	BOOTLID I40 EMBLEM	SERVICEABLE	27.90	-
1	BOOTLID LOWER GARNISH	SERVICEABLE	227.90	-
1	REAR BUMPER	TORN	553.00	553.00
1	REAR BUMPER REINFORCEMENT	CRACKED / BROKEN	428.40	428.40
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$80.30	O/S BENT / N/S NOT NECESSARY	160.60	80.30
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET @\$35.60	O/S BROKEN / N/S NOT NECESSARY	71.20	35.60
1	REAR BUMPER SPONGE	TORN	118.40	118.40
1	REAR BUMPER UNDER COVER	DISTORTED / SCRATCHED	228.00	228.00
1	REAR BUMPER REFLECTOR LAMP (RH)	BROKEN	30.60	30.60
1	TAIL LAMP (RH)	MOUNTING BROKEN	697.80	697.80
1	TAIL LAMP QUARTER PANEL (RH)	TO REPAIR SEE LABOUR	226.50	-
2	EXHAUST PIPE INSULATOR @\$58.55	NOT NECESSARY	117.10	-
2	EXHAUST SILENCER @\$967.70	O/S BENT / N/S NOT NECESSARY	1,935.40	967.70
2	EXHAUST PIPE HANGER @\$58.55	NOT NECESSARY	117.10	-
1	EXHAUST PIPE CENTRE	NOT NECESSARY	730.10	-

Report Ref No. CS/INC19020505/Dyd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER WITH HOUSING (RH)	BUCKLED	4,736.80	4,736.80
1	REAR FENDER INNER TRIM (RH)	DEFORMED	169.30	169.30
1	REAR FENDER AIR-DUCT	SERVICEABLE	51.60	-
1	REAR WINDSCREEN MOULDING	NECESSARY	28.30	28.30
1	REAR TYRE RIM (RH)	DISTORTED	325.30	325.30
1	REAR WHEEL HUP-CAP (RH)	CUT	107.10	107.10
1	REAR WHEELBEARING ING & HUB	DAMAGED	362.00	362.00
1	REAR TRAILING ARM (RH)	DISTORTED	192.00	192.00
1	REAR ASSIST (RH)	DISTORTED	145.70	145.70
1	REAR SHOCK ABSORBER (RH)	DISTORTED	276.30	276.30
1	REAR SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	81.30	-
1	REAR CROSSMEMBER	NOT NECESSARY	1,021.50	-
1	STABILIZER BAR	NOT NECESSARY	199.60	-
1	STABILIZER LINK	NOT NECESSARY	85.90	-
1	REAR UPPER ARM (RH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (RH)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (RH)	DISTORTED	545.60	545.60
1	REAR PANEL (ADDITIONAL)	DENTED	526.70	526.70
	LESS 20% DISCOUNT		-3,695.37	-2,812.71
			14,781.48	11,250.84
	SPECIAL NETT ITEMS			
1	BOOT LID COMFORT LOGO & TEL NO STICKER (SN)	NECESSARY	30.00	30.00
1	BOOT LID ADVERTISEMENT LOGO (SN)	NECESSARY	100.00	100.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	135.70	135.70
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR TYRE (RH)(SN)	NOT NECESSARY	216.00	-
			827.70	611.70



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING, INCLUSIVE OF THE REPAIR OF TAIL LAMP QUARTER PANEL (RH).		1,200.00	700.00
	SPRAY PAINTING CHARGE.		1,000.00	600.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		50.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	150.00	-
	REMOVE/REFIX EXHAUST PIPE.		300.00	60.00
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	REAR WHEEL ALIGNMENT.		120.00	60.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE. }		480.00	150.00
	RE-SET REAR ABS SYSTEM. }		200.00	-
			4,190.00	1,990.00
	GRAND TOTAL		19,799.18	13,852.54
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			11,000.00

Report Ref No. CS/INC19020505/Dyd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.