

ACC. REC. BY:

REF: 08/INC19020506 / Dvd3m2 Special Instruction:

Surveyor: Dyer

ASSIGNMENT (Office)

From (Person): Harzalya B / Ibrahim

of INC

Date/Time: 9:50am @ 19/11/19

Estimated Cost: _____ Bill to: _____

OI / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 3009R

Insured: SMK 5648L

at Workshop m/s: Swan Huckle Motor

Tel: GS425119

of 10 Amle Ind. park 2A #01-05/06

Policy No: _____

Claim No: MT / 1071863-002

Sum Insured: _____

Excess: _____

Make of Veh:
(Client's Record)

D.O.A. 16/11/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 9:50am @ 19/11/19

Person Contacted: Lynn

Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>fishmold ✓</u>
	<u>SHD 3009R - cc + ASM / 19003071 / klph 3q2 D.O.A. 15/2/2019</u>
	<u>SMK 5648L - X</u>

APP. REC. BY:

REF:

ASSIGNMENT

02 June 2024

2016 June

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHD 3009R

yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai I40

c.c.

1685

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading:

325428

T/Radio: Insured / Std / NI / NA

Eng/No:

D4FDGU650714

C/No:

KMHLB41UMGU091335

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

16/11/2019

D.O.I.

17/11/2019

Survey held at

Chunni

AMK

11.24

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NTUC SMK 5648L

07/01/2020 Jman 2/s 10600/- with 7 dys of rev (Red 15,076-40,5870)

RECEIVED 08 JAN 2020

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 7/1 - typist

Report Form:

TP

Lum. Sum / REP.:

10,600/-

Days Of Repair:

7

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Wheel stud (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Film

TOTAL

290

Nivitha (LKK Auto)

From: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Sent: Tuesday, 19 November 2019 3:26 PM
To: Admin-D (LKKAuto); assignments
Cc: Hazalya Binte Ibrahim
Subject: RE: TP CASES FARMED OUT TO LKK ON 19/11/2019

Dear LKK,

Re-send with details.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Operations, Motor & Personal Lines (PL)
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

From: Hazalya Binte Ibrahim
Sent: Tuesday, 19 November 2019 9:52 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Alice Low <alice.lowkc@income.com.sg>
Subject: TP CASES FARMED OUT TO LKK ON 19/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Serene Lim	MT/1071694-002	SLR1040R	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		5JP7344J	16/11/19	
2	Eng Huey Huey	MT/1071605-001	SLD8452M	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		5JN6985B	15/11/19	
3	Serene Lim	MT/1071721-001	SLF9471R	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		PC601K	15/11/19	
4	Azhari	MT/1071695-002	SLL3057L	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		SLZ3659B	15/11/19	
5	Eng Huey Huey	MT/1071993-001	SLA1405J	OPTIMA WERKZ PTE LTD	9A SERANGOON NORTH AVE 5	Sharon Ten / 6481 1522		5JUS625K	17/11/19	avoid 1PM - 2PM
6	Wo Jessie	MT/1071949-001	SHC3281A	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms. Irene / 65425119		5LN9343K	16/11/19	65425119 or 6542 7162
7	Quek Swee Keng	MT/1071863-002	SHD3009R	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms. Irene / 65425119		5MK5648L	16/11/19	65425119 or 6542 7162
8	Quek Swee Keng	MT/1071765-002	SHA7757D	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms. Irene / 65425119		5JN4823Z	16/11/19	65425119 or 6542 7162
9	Serene Lim	MT/1070016-002	EW3366U	TROPICAL SUCCESS AUTO CARE	BLK 5032 #01-299/303 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569535	Calvin / 64817773		5LG4655E	05/11/19	
10	Muhammad Airwan	MT/1071969-001	YP9666P	WENG KEE MOTOR	BLK 1019 #01-366 YISHUN INDUSTRIAL PARK A	Victor Wong Qi Zhi / 6854 1273 / 8182 1895		5JL9527G	07/11/19	
11	Jeff Lin	MT/1071637-002	SGK775G	AT AUTO CONSULTANT	BLK 01 SIN MING INDUSTRIAL ESTATE	Alan Tan / 83868989		5KD8863Y	15/11/19	

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg

income
made different



in with
you

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/11/2019 14:40
Date Of Accident	16/11/2019 11:20
Exact Location Of Accident	UPP PICKERING ST (PARK ROYAL HOTEL)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD3009R
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH

Cover Note Number

Driver

Name of Driver	CHUA LEONG BOON
NRIC No	S6912052J
Date Of Birth	22/03/1989
Occupation	OUTDOOR
Date Of Driving Pass	28/03/1991
Driving Experience	28 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98384314
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 162 BUKIT BATOK STREET 11 #09-92
 Postcode 650162
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3

Passenger 1
 NAME: : -
 GENDER: : FEMALE
 Passenger 2
 NAME: : -
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED / Type Of Accident : HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMK5648L
 Vehicle Make/Model/Colour -
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver IVAN LIM FANG WEI
 NRIC/Passport Number
 Contact Number 91509864
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

NTUC INCOME INSURANCE CO-OPERATIVE LTD

RIGHT CENTRE

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

17/11/19
Jackson Heng
CSO

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16/11/2019 at about 11:20 hrs, I vehicle A was driving my taxi from New bridge road toward Park Royal hotel. while I was on the extreme right lane wanted to turn right into Park Royal hotel. vehicle B came from my lane suddenly cuts sharply into my lane. but I couldn't brake in time collided onto vehicle B right side body. no one was injured at that time.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3009R

DATE : 18.11.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Nml

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet Est <i>Destroyed</i>			\$ 2,265.90
	Bonnet Hinge (LH/RH) <i>Nml</i>		\$ 41.00	\$ 82.00
	Radiator Grille <i>Cut</i>			\$ 1,110.10
	Radiator Grille H Emblem <i>Svc</i>			\$ 39.50
	Front Bumper Cover <i>distorted</i>			\$ 1,052.20
	Front Bumper Sponge <i>Svc</i>			\$ 99.20
	Front Bumper Reinforcement <i>Est</i>			\$ 402.10
	Front Bumper Grille (LH) <i>Cut / deformed</i>			\$ 93.60
	Front Bumper Grille Airduct (LH) <i>Nml</i>			\$ 26.20
	Front Bumper Lip <i>Nml</i>			\$ 54.90
	Front Bumper Bracket Top (LH) <i>Nml</i>			\$ 22.40
	Front Bumper Bracket (LH) <i>broken</i>			\$ 24.60
	Headlamp Support Top Cover <i>Nml</i>			\$ 222.60
	Headlamp Support Panel Assy <i>broken</i>			\$ 907.40
	Headlamp (LH) <i>broken / scratched</i>			\$ 1,388.00
	Front Fender (LH) <i>Destroyed</i>			\$ 566.30
	Front Fender Apron Panel (LH) <i>Destroyed</i>			\$ 637.00
	Front Fender Shield (LH) <i>Svc</i>			\$ 174.90
	Air Cleaner Bottom Assy <i>Nml</i>			\$ 325.00
	Front Wheel Rim (LH) <i>Est</i>			\$ 325.30
	Front Wheel Hub Cap (LH) <i>Nml Cut</i>			\$ 107.10
	Front Wheel Bearing <i>Nml Down</i>			\$ 540.50
	Front Shock Absorber (Assy) (LH) <i>Nml distorted</i>			\$ 342.20
	Front Shock Absorber Mounting (LH) <i>Nml</i>			\$ 108.80
	Front Drive Shaft (LH) <i>Nml</i>			\$ 1,030.80
	Rack & Pinion Assy <i>Nml</i>			\$ 969.60
	STG Tie End <i>Nml</i>			\$ 62.60
	Front Suspension Lower Arm (LH) <i>Est distorted</i>			\$ 529.30
	Knuckle Arm (LH) <i>Est distorted</i>			\$ 552.00
	Engine Crossmember <i>Nml</i>			\$ 2,094.40
	ABS Sensor <i>Nml</i>			\$ 234.00
	Wiring-Engine <i>housing deformed / cracked</i>			\$ 3,326.00
	Wiring-ECM <i>Nml</i>			\$ 3,243.00
	Electric Power Steering <i>Nml</i>			\$ 3,641.00
			14169.60	
			11335.68	
	SUB TOTAL			\$ 26,600.50
	LESS 20%			\$ 5,320.10
	DISCOUNTED TOTAL			\$ 21,280.40

3326.0

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHD 3009 R

Technician:

Mileage: 325427

Time Printed 19.11.19 11:30 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°20'		-3°00' 3°00'
3°40'		-0°19' 5°41'
3°43'		-1°30' 1°30'
15°52'		
15°33'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°07'		-3°00' 3°00'
4°04'		-0°19' 5°41'
-0°01'		-1°30' 1°30'
15°02'		
14°56'		

Front

	Actual	BEFORE	Specified Range
Cross Camber	-0°13'		-3°00' 3°00'
Cross Caster	-0°24'		-3°00' 3°00'
Cross SAI	0°50'		-3°00' 3°00'
Total Toe	3°42'		-3°00' 3°00'
Cross Turn Diff.			

Rear : Left

Actual	BEFORE	Specified Range
-1°05'		-3°30' 2°30'
0°10'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°19'		-3°30' 2°30'
0°00'		-1°30' 1°30'

Rear

	Actual	BEFORE	Specified Range
Cross Camber	-0°46'		-3°00' 3°00'
Total Toe	0°11'		-3°00' 3°00'
Thrust Angle	0°05'		-3°00' 3°00'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19020506/Dvd3n2
73 BRAS BASAH ROAD Date: 13-01-2020
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556



ATTN: QUEK SWEE KENG

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMK 5648L	Veh. Inspected	SHD 3009R
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1071863-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	19/11/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU091335	Colour	BLUE
Odometer	325428 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/11/2019	Inspect Date / Time	19/11/2019 (11:24 AM)
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3009R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	BENT / DENTED	2,265.90	2,265.90
2	BONNET HINGE (LH/RH) @\$41.00	NOT NECESSARY	82.00	-
1	RADIATOR GRILLE	CUT	1,110.10	1,110.10
1	RADIATOR GRILLE H EMBLEM	SERVICEABLE	39.50	-
1	FRONT BUMPER COVER	DISTORTED	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	SERVICEABLE	99.20	-
1	FRONT BUMPER REINFORCEMENT	BENT	402.10	402.10
1	FRONT BUMPER GRILLE (LH)	CUT / DEFORMED	93.60	93.60
1	FRONT BUMPER GRILLE AIRDUCT (LH)	NOT NECESSARY	26.20	-
1	FRONT BUMPER LIP	NOT NECESSARY	54.90	-
1	FRONT BUMPER BRACKET TOP (LH)	NOT NECESSARY	22.40	-
1	FRONT BUMPER BRACKET (LH)	BROKEN	24.60	24.60
1	HEADLAMP SUPPORT TOP COVER	NOT NECESSARY	222.60	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	907.40	907.40
1	HEADLAMP (LH)	BROKEN / SCRATCHED	1,388.00	1,388.00
1	FRONT FENDER (LH)	DENTED	566.30	566.30
1	FRONT FENDER APRON PANEL (LH)	DENTED	637.00	637.00
1	FRONT FENDER SHIELD (LH)	SERVICEABLE	174.90	-
1	AIR CLEANER BOTTOM ASSY	NOT NECESSARY	325.00	-
1	FRONT WHEEL RIM (LH)	BENT	325.30	325.30
1	FRONT WHEEL HUB CAP (LH)	CUT	107.10	107.10
1	FRONT WHEEL BEARING	DAMAGED	540.50	540.50
1	FRONT SHOCK ABSORBER (ASSY)(LH)	DISTORTED	342.20	342.20
1	FRONT SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	108.80	-
1	FRONT DRIVE SHAFT (LH)	NOT NECESSARY	1,030.80	-
1	RACK & PINION ASSY	NOT NECESSARY	969.60	-
1	STG TIE END	NOT NECESSARY	62.60	-
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	529.30	529.30
1	KNUCKLE ARM (LH)	DISTORTED	552.00	552.00
1	ENGINE CROSSMEMBER	NOT NECESSARY	2,094.40	-

Report Ref No. CS/INC19020506/Dvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ABS SENSOR	NOT NECESSARY	234.00	-
1	WIRING-ENGINE	HOUSING DEFORMED / CRACKED	3,326.00	3,326.00
1	WIRING-ECM	NOT NECESSARY	3,243.00	-
1	ELECTRIC POWER STEERING	NOT NECESSARY	3,641.00	-
	LESS 20% DISCOUNT		-5,320.10	-2,833.92
			21,280.40	11,335.68
	SPECIAL NETT ITEMS			
1	FRONT TYRE (LH)(SN)	NOT NECESSARY	216.00	-
			216.00	-
	LABOUR			
	PANEL BEATING.		1,500.00	700.00
	SPRAY PAINTING CHARGE.		750.00	600.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		50.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX UNDERCARRIAGE (FRT).		200.00	120.00
	FRT WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX AIRCON & REFILL GAS.		150.00	80.00
	REMOVE/REFIX DASHBOARD.		450.00	150.00
	REMOVE/REFIX FUSE BOX.		180.00	80.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.)		480.00	150.00
	RE-SET FRT ABS SENSOR.)		200.00	-
			4,180.00	2,010.00
	GRAND TOTAL		25,676.40	13,345.68
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			10,600.00

Report Ref No. CS/INC19020506/Dvd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.