

OPTIMA WERKZ

SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg

f /OptimaWerkz

@ /OptimaWerkz

Date: 18.11.2019
Vehicle No: SLA1405L
Model: VOLKSWAGEN SPORTSVAN 1.4
Chassis: WVWZZZAUZGW552395 - 2015
Reg.Year: 2016

Third Party Insurer: NTUC
Third Party Veh No: SJU5625K
Date of Accident: 17.11.2019

Not Authorised

Assuming 134 points 7 days

ESTIMATE

89140.80

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE 1430	1		\$1,700.00
2	REAR TAILGATE INNER LOCK	1		\$280.00
3	REAR TAILGATE "TSJ" EMBLEM 75	1		\$110.00
4	REAR TAILGATE "BLUE MOTION" EMBLEM	1		\$98.00
5	REAR TAILGATE RUBBER 290	1		\$380.00
6	REAR TAILGATE INNER TRIM CLIPS	10	\$5.80	\$58.00
7	REAR TAILGATE INNER TRIM	1		\$298.00
8	REAR TAILGATE REVERSE LAMP LH 220	1		\$280.00
9	REAR WINDSCREEN MOULDING	1		\$141.60
10	REAR WINDSCREEN STOPPER	2	\$15.00	\$30.00
11	REAR TAILGATE LOCK CATCH	1		\$149.80
12	REAR END PANEL	1		\$280.00
13	REAR END PANEL UPPER COVERING	1		\$180.00
14	REAR END PANEL UPPER COVERING CLIPS	6	\$7.50	\$45.00
15	REAR LOCK CATCH TOP COVERING	1		\$34.00
16	REAR KICK SENSOR	1		\$272.00
17	REAR BUMPER	1		\$1,050.00
18	REAR BUMPER REINFORCEMENT 484	1		\$540.00
19	REAR BUMPER UPPER BRACKET CENTER	1		\$217.40
20	REAR BUMPER UPPER BRACKET LH	1		\$116.00
21	REAR BUMPER SIDE BRACKET LH	1		\$55.00
22	REAR BUMPER CLIPS	12	\$5.80	\$69.60
23	REAR BUMPER REVERSE SENSOR	1		\$205.00
24	REAR BUMPER LOWER COVER 320	1		\$350.00
25	FRONT BUMPER SIDE BRACKET LH	1		\$55.00
26	FRONT BUMPER CLIPS	10	\$5.80	\$58.00
27	FRONT BUMPER 1152.82	1		\$1,280.00
28	FRONT BUMPER INNER GUIDE LH	1		\$116.00
29	FRONT BUMPER PARKING SENSOR	1		\$205.00
30	REAR TAIL LAMP LH	1		\$250.00
31	REAR SPARE TYRE TRAY	1		\$330.00
32	REAR SPARE TYRE PANEL			REPAIR

Finalise

Parts: \$7778.16

Nett: \$125.00

Labor: \$1920.00

\$9823.16 x 7 days

SUB TOTAL \$9,233.40

LESS 10% -\$923.34

PARTS TOTAL \$8,310.06

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 Fax: (+65) 6452 9223



Date: 18.11.2019
Vehicle No: SLA1405L
Model: VOLKSWAGEN SPORTSVAN 1.4
Chassis: WVWZZZAUZGW552395 - 2015
Reg. Year: 2016

Third Party Insurer: NTUC
Third Party Veh No: SJU5625K
Date of Accident: 17.11.2019

ESTIMATE

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1	401	\$80.00
2	FRONT NUMBER PLATE	1	401	\$40.00
3	REAR NUMBER PLATE + HOLDER	1	451	\$80.00
S/N TOTAL				\$200.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST FRONT & REAR ACCIDENT AREAS & ETC

\$1,000.00 8001

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT & ETC

\$150.00 1201

LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS & ETC

\$100.00 601

LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEMS & ETC

\$80.00 401

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, REAR TAILGATE, REAR END PANEL, REAR BUMPER, REAR TYRE PANEL & ETC.

\$900.00 8001

TO DIAGNOSIS FAULTY CODE & RESET MEMORY

~ \$150.00 X

TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR ASSY, FRONT BUMPER PARKING SENSOR & ETC

\$100.00 ✓

ONG

LABOUR TOTAL \$2,480.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TOTAL \$10,990.06

11,368.06

Acknowledged by Repairer

Signature: _____

Date: _____

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 Fax: (+65) 6452 9223