

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 5750K

DATE : 16/11/2019

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door (LH) X (R)			\$ 2,256.40
	Front Door Glass (LH) SCR			\$ 228.20
	Front Door Outer Handle (LH) SCR X (R)			\$ 36.30
	Front Door Outer Moulding (LH) SCR			\$ 47.10
	Front Door Mirror Assy (LH) Br			\$ 670.00
	Rear Door (LH) Br			\$ 2,201.10
	Rear Door Glass (LH) XNN			\$ 200.20
	Rear Door Outer Moulding (LH) XNN			\$ 35.80
	Rear Door Outer Handle (LH) SCR			\$ 36.30
	Front Windscreen Moulding nec			\$ 113.30
	Front Windscreen Pillar Inner(LH/RH) XNN			\$ 310.70
	Front Windscreen Enforcement(LH/RH) XNN			\$ 1,163.30
	SUB TOTAL			\$ 7,298.70
	LESS 20%			\$ 1,459.74
	DISCOUNTED TOTAL			\$ 8,758.44
	Front Door Comfort Logo (LH) nec			\$ 75.00
	Front Door Advertisement Logo (LH) nec			\$ 100.00
	Rear Door Tel No. Sticker (LH/RH) nec			\$ 10.00
	Front Windscreen Sealant nec			\$ 46.00
				\$ 231.00
	Labour Charge			
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 750.00
	Wiring Charge			\$ 30.00
	Tuff Kote			\$ 50.00
	Towing Charge			\$ 50.00
	Remove/Refix Cushion & Upholstery Front			\$ 90.00
	TOTAL LABOUR			\$ 2,170.00
	ESTIMATE TOTAL			\$ 11,159.44
<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CMMV

Cheng

Ram (LKR)
886227784
Parasuram@lkkauto.com
get repair photo
3 repair days
LB

Nett
Nett
Nett
Nett

\$840
\$680
\$30
\$XNN
\$50

Our Job Ref No : 305349571

Date : 22/11/19

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : PARAM

: SHA5750K

15/11/2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: CHINA SMG8701S

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost


\$3,600.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name : Ram

Date : 26/11/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: