

CL Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586

TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg

RCB NO:198800292M

M/S : JFC (S) PTE LTD

3C TOH GUAN ROAD EAST

#02-01

SINGAPORE 608832

TEL: 65678238

FAX: 65670832

ATTN: Motor Claim Department \ MISS WONG LI YIN

Your Ref No: YP7346B

Claim Type: Third Party

Accident Date: 21/10/2019

TP Veh Reg No: XD3580S

Estimate No: EST1900240

Date: 25 Oct 2019

Policy No: D19MFL0000240

Veh Reg No: YP7346B

Make/Model: ISUZU NQR75UL5A

Chassis No: JAAN1R75LH7100794

Engine No: 4HK1622385

Reg. Date: 12/09/2017

Term: 30 DAYS

Estimate Repair Cost to Vehicle No : YP7346B

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
Special Net:				
1 FRONT GRILLE CLIPS		1 SET	50.00	
2 FRONT R/H SIGNAL LAMP CLIP		1 SET	30.00	
3 FRONT R/H CORNER PANEL CLIP		1 SET	40.00	
4 REAR CENTER WOODEN STEP BAR		1 PC	150.00	
5 REAR NUMBER PLATE BASE		1 SET	60.00	
6 REAR NUMBER PLATE LAMP ASSY		1 PC	50.00	
7 NUMBER PLATE		1 PC	35.00	
8 REAR BUMPER STICKER YELLOW AND BLACK		1 SET	50.00	
9 REAR CARGO WOODEN DOOR ASSY		1 SET	450.00	
10 REAR CARGO WOODEN DOOR HINGE		2 PCS	120.00	
				1,155.00

List Price:				
11 FRONT PANEL		1 PC	750.00	
12 FRONT GRILLE		1 PC	350.00	
13 FRONT BUMPER ASSY		1 PC	650.00	
14 FRONT R/H SIDE LAMP & WITH SIGNAL LAMP ASSY		1 PC	120.00	
15 FRONT R/H CORNER PANEL ASSY		1 PC	280.00	
16 FRONT PANEL STICKER - REWARD NO		1 PC	60.00	
17 ISUZU EMBLEM		1 SET	125.00	
18 FRONT RHS HEAD LAMP ASSY		1 PC	390.00	
19 FRONT RHS HEAD LAMP LOWER SEAL		1 PC	38.00	
20 REAR FLOOR BOARD CENTER AND END CROSS MEMBER SUSFRAME		1 SET	400.00	
21 60 KM STICKER		1 PC	10.00	
22 30 PAX STICKER		1 PC	10.00	
				2,705.55

Labour Charges:				
23 TO REMOVE FRONT GLASS & REPLACE FRONT GLASS		1 JOB	150.00	
24 TO CUT & WELD FRONT PANEL, KNOCKING FRONT GLASS PANEL & ADJUST R/H DOOR, REPLACE HEAD LAMP PANEL & BUMPER		1 JOB	700.00	
25 RUSTPROOFING		1 JOB	50.00	
26 TO RESPRAY PAINT FRONT PANEL & GRILLE & BUMPER & CORNER PANEL & INLET PANEL		1 JOB	400.00	
27 TO REMOVE & REFIT FRONT GLASS, REPLACE FRONT GLASS		1 JOB	150.00	
28 TO CUT & WELD FRONT PANEL, KNOCKING FRONT GLASS PAEL, ADJUST FRONT R/DOOR AND REPLACE HEAD LAMP PANEL & FRONT BUMPER		1 JOB	700.00	

C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586

TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg

RCB NO: 198800292M

M/S : JFC (S) PTE LTD

3C TOH GUAN ROAD EAST

#02-01

SINGAPORE 608832

TEL: 65678238

FAX: 65670832

ATTN: Motor Claim Department \ MISS WONG LI YIN

Your Ref No: YP7346B

Claim Type: Third Party

Accident Date: 21/10/2019

TP Veh Reg No: XD3580S

Estimate No: EST1900240

Date: 25 Oct 2019

Policy No: D19MFL0000240

Veh Reg No: YP7346B

Make/Model: ISUZU NQR75UL5A

Chassis No: JAAN1R75LH7100794

Engine No: 4HK1622385

Reg. Date: 12/09/2017

Term: 30 DAYS

Estimate Repair Cost to Vehicle No : YP7346B

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
29 TO RUSTPROOF		1 JOB	50.00 Δ	
30 TO RESPRAY PAINT FRONT PANEL, GRILLE, BUMPER, CORNER PANEL AND INLET PANEL		1 JOB	400.00 Δ	
31 TO REMOVE & REFIT CARGO FLOOR BOARD, REAR FRAME, FLOOR BOARD, CUT & WELD SUSFRAME. REFIT AND REALIGN REAR COMPANY CARGO BASE		1 JOB	800.00	
				3,400.00

Lump Sum Repair	S\$ 7,260.55
Lump Sum Less 20%	-1,452.11
Total Amount payable	<u>S\$ 5,808.44</u>

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND EIGHT HUNDRED AND EIGHT AND CENTS FORTY FOUR ONLY

For C L Auto Pte Ltd

AUTHORISED SIGNATURE