

22/02/2021

ASS. REC. BY:

REF:

CS/CTI/19020559/K00302

Special Instruction:

Signature:

Lenneth

ASSIGNMENT (Office)

From (Person):

Minimen Tan Kah Leong

of

CTI

Date/Time: 19/11/19 @ 4.12pm

Estimated Cost:

Bill to:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SQJ 16532

Insured:

XE 1978L

at Workshop n/s

Ah Him Motor

Tel:

6483 1244

of

10 AMK Ind. Park 2A #01-09

Policy No:

DMCVSN18223819011

Claim No:

SNM19D205432

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Imp

H.O.D. Endorsement:

Date/Time:

9.40am @ 20/11/19

Person Contacted:

Zila

Vehicle IN (OUT)

Date/Time

Action/Instruction

Estimate

SQJ16532-X

XE1978L-X

2/1. C1 Pump @ 2500 Ccfirmed

(\$ 2,155.05 Red - 46%)

ASS. REC. BY:

REF:

C121

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

File pass to

Veh No:

SGJ 1653 Z

Yr Regn:

06, 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Chevrolet

Aveo c.c.

1399

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

130338

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KL 1SF 4871685 90266

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/50R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

13/11/19

D.O.I.

20/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 02 JAN 2020

Date/Time, File Pass to?

02/01/20

☐ : Prel. Report

1) Tyre

☒ : Final Report

Date/Time, File Return to?

Days Of Repair:

4

Resurvey No. of Trlp:

1

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

220

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$ 2,500 - 45

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Nov 2019		19 Nov 2019 16:19 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	MUHAMMAD NAZRY BIN BAHARI, ID: S8141708C		
Vehicle Reg. No.:	SGJ1653Z	Date of Loss:	15/11/2019 15:00 - :59
Claim Type:	TP / SNM19D205432C02	Policy/Cover Note No.:	DMCVSN18223819011
Vehicle Reg. No. (Insured):	XE1978L	Policy No. (Claimant):	GA428145/1
		Excess:	S\$2,000.00
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/11/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Tuesday, 19 November 2019 4:12 PM
To: Mui Hong @ Ah Lim Motor; assignments
Subject: RE: OUR REF: SNM19D205432-XE1978L-TKL- PRS SGJ1653Z accident with China Insured - XE1978L on 15.11.2019

WITHOUT PREJUDICE

Dear Mui Hong,

We refer to your email dated 18.11.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Mui Hong @ Ah Lim Motor [mailto:muihong@ahlimmotor.com.sg]
Sent: Tuesday, November 19, 2019 4:02 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D205432-XE1978L-TKL- PRS SGJ1653Z accident with China Insured - XE1978L on 15.11.2019

Dear Kah Leong,

We are agreeable. Pls request your appointed surveyor to contact us for the survey arrangement

Best Regards,

Kee Mui Hong
Ah Lim Motor @ AMK
10, Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint S568047
Tel : 6483 1244 Fax : 6483 6170

From: Tan Kah Leong [<mailto:KahLeong.Tan@sg.cntaiping.com>]
Sent: Tuesday, 19 November 2019 3:55 PM
To: Mui Hong @ Ah Lim Motor <muihong@ahlimmotor.com.sg>
Subject: RE: OUR REF: SNM19D205432-XE1978L-TKL- PRS SGJ1653Z accident with China Insured - XE1978L on 15.11.2019

Without Prejudice

Dear Mui Hong,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Tuesday, November 19, 2019 3:52 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; muihong@ahlimmotor.com.sg
Subject: OUR REF: SNM19D205432-XE1978L-TKL- PRS SGJ1653Z accident with China Insured - XE1978L on 15.11.2019

Dear Kah Leong,

Please conduct PRS for SGJ1653Z.

Note : officer in charge- Kah Leong 63896193.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Mui Hong @ Ah Lim Motor [mailto:muihong@ahlimmotor.com.sg]

Sent: Tuesday, 19 November, 2019 3:11 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: Request for survey for our client - SGJ1653Z accident with China Insured - XE1978L on 15.11.2019

Dear claims,

Pls assist to arrange survey for our client - SGJ1653Z accident with China Insured - XE1978L on 15.11.2019.

Car is not in our workshop yet. Pls request appointed surveyor to contact us to arrange for survey

Best Regards,

Kee Mui Hong

Ah Lim Motor @ AMK

10, Ang Mo Kio Industrial Park 2A

#01-09 AMK Autopoint S568047

Tel : 6483 1244 Fax : 6483 6170

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 708C

Vehicle Details

Vehicle No.: SGJ1653Z
Vehicle to be Exported: No
Intended Deregistration Date: 16 Nov 2019
Vehicle Make: CHEVROLET
Vehicle Model: AVEO5 HB MT
Primary Colour: Black
Manufacturing Year: 2005
Engine No.: F14D3399563K
Chassis No.: KL1SF48716B590266
Maximum Power Output: 69.0 kW (92 bhp)
Open Market Value: \$9,364.00
Original Registration Date: 30 Jun 2006
First Registration Date: 30 Jun 2006
Transfer Count: 2
Actual ARF Paid: \$2,602.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 29 Jun 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$23,227.00
COE Rebate Amount: \$7,522.00
Total Rebate Amount: \$7,522.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 16 Nov 2019

OK

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : MUHAMMAD NAZRY BIN BAHARI
 303A PUNGOL CENTRAL
 #02-782
 SINGAPORE 821303

Estimate No: MC1900832
 Date: 19 Nov 2019
 Policy No: GA428145/1
 Veh Reg No: SGJ1653Z
 Make/Model: CHEVROLET AVEO5
 HB MT

ATTN:

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 15/11/2019
 TP Veh Reg No: XE1978L

LKK

1:50 PM

DUPLICATE COPY

Not Authorized
 6/11/19 @ 7
 Running After Paint
 4 days

Estimate Repair Cost to Vehicle No :SGJ1653Z

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 SIDE MIRROR ASSY	1 PC	353.50	✓
2 REAR DOOR RH	1 PC	1,482.00	✓
3 REAR DOOR RH OUTER HANDLE	1 PC	44.00	✓
4 REAR DOOR RUBBER @ DOOR	1 PC	100.00	✓
5 REAR DOOR RUBBER @ BODY & FRAME	1 PC	69.00	X
6 REAR DOOR WINDOW GEAR	1 PC	124.00	✓
7 REAR DOOR WINDOW MOTOR	1 PC	147.00	X
8 REAR DOOR WINDOW MOULDING	1 PC	25.00	X
9 REAR DOOR GARNISH RH / TAPE	1 PC	25.00	✓
10 REAR DOOR GARNISH LH / TAPE	1 PC	25.00	✓
		2,394.50	
	Less 10%	239.45	2,155.05
Special Nett			
11 BLIND SPOT MIRROR RH - CHK PRICE	1 PC	0.0000	X
12 SIDE MIRROR INNER SPEAKER RH - CHK PRICE	1 PC		X
13 FRONT DOOR SIDE GARNISH RH - CHK PRICE	1 PC	0.0000	X
14 STICKER " HKS DRIVING PERFORMANCE " - CHK PRICE	1 PC	0.0000	✓ 10
15 REAR DOOR RH RAIN VISOR - CHK PRICE	1 PC	0.0000	✓ 30
16 SEALANT	1 PC	40.00	X
17 INNER SEAL	1 PC	20.00	X
		60.00	60.00
LABOUR			
18 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	X
19 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR @ REAR DOOR RH	1 PC	120.00	60
20 TO REMOVE AND REINSTALL/REPLACE QUARTER GLASS.	1 PC	60.00	X
21 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS @ REAR FENDER RH	1 PC	60.00	✓
22 TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS.	1 PC	60.00	X
23 TO REMOVE & REINSTALL RAIN VISOR @ REAR DOOR RH - CHK PRICE	1 PC	0.0000	X
24 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	30

AH LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : MUHAMMAD NAZRY BIN BAHARI
303A PUNGGOL CENTRAL
#02-782
SINGAPORE 821303

Estimate No: MC1900832
Date: 19 Nov 2019
Policy No: GA428145/1
Veh Reg No: SGJ1653Z
Make/Model: CHEVROLET AVEO5
HB MT

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 15/11/2019
TP Veh Reg No: XE1978L

Estimate Repair Cost to Vehicle No :SGJ1653Z

Description	Quantity	List Price	Amount
		S\$	S\$
25 TO DISMANTLE ALL DAMAGED PARTS.TO KNOCK & REPAIR ROCKER PANEL RH, REAR FENDER RH, REAR BUMPER, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	700.00	450
26 TO SPRAY FRONT DOOR RH, SIDE MIRROR RH COVER, REAR DOOR RH, REAR DOOR RH OUTER HANDLE, REAR FENDER RH, ROCKER PANEL RH & REAR BUMPER	1 PC	1,300.00	550
		2,440.00	2,440.00
		Total	S\$ 4,655.05
		Add GST @ 7%	325.85
		Total Amount Payable	S\$ 4,980.90

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND NINE HUNDRED EIGHTY AND CENTS NINETY ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
601. AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19020559/KSD3N2
 Date: 09/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN18223819011
 Claimant Vehicle No: SGJ1653Z Insured Vehicle No: XE1978L
 Date of Loss: 15/11/2019 Nature of Claim: TP Claim No: SNM19D205432C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGJ1653Z Engine No: F14D3399563K
 Make & Model: CHEVROLET AVEO5, 1.4 HB (M) Chassis No: KL1SF48716B590266
 Reg. Date: 30/06/2006 (Man. Year: 2005) Odometer: 130338 km
 Colour: Metallic Black
 Engine Capacity: 1399 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50R15 Rear Tyre Size: 195/50R15
 Front Left Side: Falken 7 mm Rear Left Side: Falken 7 mm
 Front Right Side: Falken 7 mm Rear Right Side: Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,255.05	1,978.15	276.90	12.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,440.00	1,150.00	1,290.00	52.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,695.05	3,128.15	1,566.90	33.37
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	4,695.05	2,500.00	2,195.05	46.75
+ GST 7.00/7.00% (S\$)	328.65	175.00	153.65	46.75
Nett Amount (S\$)	5,023.70	2,675.00	2,348.70	46.75

INSPECTION

Date of Assignment: 19/11/2019
 Date Inspected: 20/11/2019 Inspected At: Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
 Autopoint
 Singapore 568047
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jan 2020)
Parts:	144	CHEVROLET AVEO5 1.4 HB (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGJ1653Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE MIRROR ASSY	Mtg Cracked	353.50 FL	*353.50 FL
2	1		*REAR DOOR RH	Bent	1,482.00 FL	*1,482.00 FL
3	1		*REAR DOOR RH OUTER HANDLE	Cracked	44.00 FL	*44.00 FL
4	1		*REAR DOOR RUBBER @ DOOR	Cut	100.00 FL	*100.00 FL
5	1		*REAR DOOR RUBBER @ BODY & FRAME	Serviceable	69.00 FL	*- FL
6	1		*REAR DOOR WINDOW GEAR	Bent	124.00 FL	*124.00 FL
7	1		*REAR DOOR WINDOW MOTOR	Serviceable	147.00 FL	*- FL
8	1		*REAR DOOR WINDOW MOULDING	Serviceable	25.00 FL	*- FL
9	1		*REAR DOOR GARNISH RH/TAPE	Necessary	25.00 FL	*25.00 FL
10	1		*REAR DOOR GARNISH LH/TAPE	Necessary	25.00 FL	*25.00 FL
11	1		*BLIND SPOT MIRROR RH (NPA)	Serviceable	0.00 FS	*- FS
12	1		*SIDE MIRROR INNER SPEAKER RH (NPA)	Serviceable	0.00 FS	*- FS
13	1		*FRONT DOOR SIDE GARNISH RH (NPA)	Serviceable	0.00 FS	*- FS
14	1		*STICKER HKS DRIVING PERFORMANCE	Necessary	10.00 FS	*10.00 FS
15	1		*REAR DOOR RH RAIN VISOR	Necessary	30.00 FS	*30.00 FS
16	1		*SEALANT	Not Necessary	40.00 FS	*- FS
17	1		*INNER SEAL	Not Necessary	20.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	2,494.50	2,193.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	239.45	215.35
Total Parts (\$\$)	2,255.05	1,978.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	80.00	0.00
2	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR @ REAR DOOR RH	New	120.00	60.00
3	TO REMOVE AND REINSTALL/REPLACE QUARTER GLASS	New	60.00	0.00
4	TO REMOVE AND REINSTALL CUSHIONS,SEATS,BACKREST,INNER TRIM,GARNISH,ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS @ REAR FENDER RH	New	60.00	60.00
5	TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS	New	60.00	0.00
6	TO REMOVE & REINSTALL RAIN VISOR @ REAR DOOR RH (NPA)	New	0.00	0.00
7	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
8	TO DISMANTLE ALL DAMAGED PARTS.TO KNOCK & REPAIR ROCKER PANEL RH,REAR FENDER RH,REAR BUMPER,INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME	New	700.00	450.00
9	TO SPRAY FRONT DOOR RH,SIDE MIRROR RH COVER,REAR DOOR RH,REAR DOOR RH OUTER HANDLE,REAR FENDER RH,ROCKER PANEL RH & REAR BUMPER	New	1,300.00	550.00
Gross Labour Cost (S\$)			2,440.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >