

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 495P**AAD1911-142***Not Notched**Respray B4 paint**\$ 7334.56*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 495P

VF1ABL15AUC283508

RENAULT

LATITUDE

15.11.19

AIG

30/11/2017

19 NOV 2019

PART		LIST	
1	DOOR PANEL REAR LH	\$	B ₁ 758.70 ✓
1	DOOR GUIDE REAR LH	\$	S ₂ 136.40
1	DOOR HINGE UPPER LH	\$	N 180.70
1	DOOR HINGE LOWER LH	\$	N 169.90
1	DOOR CHECK REAR LH/RH L70Y	\$	S ₂ 114.90
1	DOOR WHEATHESTRIIP REAR LH	\$	S ₂ 240.50
1	DOOR SEAL REAR LH	\$	S ₂ 119.40
1	DOOR GLASS RUNNER SEAL REAR LH	\$	S ₂ 116.10
1	DOOR MOULDING REAR LH	\$	S ₂ 100.50
1	DOOR FINISHER REAR LH	\$	S ₂ 230.30
1	DOOR HANDLE OUTER REAR LH L70Y	\$	N ₁ 42.10 ✓
1	DOOR REGULATOR REAR LH L70Y	\$	B ₂ 657.10 —
1	DOOR REGULATOR MOTOR REAR LH L70Y	\$	J ₂ 450.60 —
1	DOOR WAIST SEAL OUTER REAR LH L70Y	\$	S ₂ 169.60 X
1	DOOR BLIND REAR LH L70Y	\$	S ₂ 506.90 ✓
1	DOOR PANEL FRT LH	\$	B ₂ 2,844.66 ✓
1	DOOR HINGE UPPER LH	\$	N 274.50 X
1	DOOR HINGE LOWER LH	\$	M ₁ 300.55 ✓
1	DOOR CHECK FRT LH	\$	S ₂ 90.90
1	DOOR LOCK FRT LH	\$	N 453.80
1	DOOR CATCH FRT LH	\$	N 73.70
1	DOOR REGULATOR FRT LH	\$	N 758.10
1	DOOR REGULATOR MOTOR FRT LH	\$	S ₂ 501.40
1	DOOR REGULATOR GUIDE FRT LH	\$	S ₂ 69.00
1	DOOR MOULDING FRONT LH	\$	S ₂ 100.50
1	DOOR FINISHER FRONT LH	\$	S ₂ 258.90
1	DOOR BLIND FRONT LH	\$	S ₂ 506.90
1	DOOR WHEATHESTRIIP FRONT LH	\$	S ₂ 316.00

Trans-cab Auto Services Pte Ltd**AAD1911-142**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 495P

1	DOOR SEAL FRONT LH	\$	S\$ 69.60	} X
1	DOOR SEAL LOWER FRONT LH	\$	S\$ 93.90	
1	DOOR GLASS RUNNER SEAL FRONT LH	\$	S\$ 332.00	
1	DOOR WAIST SEAL OUTER FRONT LH	\$	S\$ 92.20	
1	DOOR HANDLE OUTER FRONT LH	\$	S\$ 169.50	
1	DOOR HANDLE CAP FRONT LH	\$	S\$ 17.30	
1	DOOR HANDLE SEAL FRT LH L70Y	\$	S\$ 1.60	
1	DOOR HANDLE COVER FRT LH L70Y	\$	S\$ 6.10	
1	DOOR HANDLE MODULE FRT LH L70Y	\$	S\$ 133.40	
1	DOOR MIRROR ASSY LH	\$	S\$ 727.90	
1	DOOR HARNESS WIRE LH	\$	S\$ 2,670.00	
1	ROCKER PANEL INNER GARNISH LH	\$	S\$ 466.51	
1	ROCKER PANEL INNER LH	\$	N\$ 1,024.79	
1	ROCKER PANEL OUTER LH	\$	N\$ 1,184.99	
1	ROCKER PANEL CENTER LH	\$	N\$ 990.25	
TOTAL		\$	18,522.65	
10%		\$	1,852.26	
		\$	16,670.39	

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	N\$ 100.00	60sn
1	FRONT DOOR STICKER 'Trans-Cab'	\$	N\$ 80.00	60sn
1	FRONT DOOR STICKER 'Classic'	\$	N\$ 80.00	15sn
1	DOOR CHECK BOLT	\$	S\$ 22.69	} X
1	DOOR GUIDE SCREW	\$	S\$ 10.85	
1	DOOR HINGE BOLT	\$	S\$ 10.85	
1	DOOR HINGE NUT LH	\$	S\$ 14.60	
1	DOOR CHECK BOLT	\$	S\$ 22.69	
1	DOOR CHECK NUT	\$	S\$ 3.75	
1	DOOR LOCK SCREW L70Y	\$	S\$ 6.12	
1	DOOR CATCH SCREW L70Y	\$	S\$ 10.06	
1	REAR LEFT TYRE	\$	S\$ 300.00	
1	REAR LEFT TYRE RIM	\$	S\$ 380.00	
1	TYRE RIM COVER LH	\$	S\$ 50.00	
2	REAR WINDSCREEN SEALANT	\$	N\$ 80.00	
1	WINDSCREEN MOULDING	\$	N\$ 100.00	
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	N\$ 100.00	

Trans-cab Auto Services Pte Ltd**AAD1911-142**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 495P**TOTAL \$ 1,371.63****TOTAL PARTS \$ 18,042.02****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 7,500.00 *6000*

Putty and spray painting of the affected portion.

\$ 7,500.00 *8800*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 *800*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *X*

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 *X*

To rust-proofing of the affected areas.

\$ 170.00 *600*

To Check Electrical Lighting Concerned.

\$ 170.00 *200*

To transfer of Rear door fittings, attachment and perform water seepage test.

\$ 170.00 *600*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 *X*

To transfer of Front door fittings, attachment and perform water seepage test.

\$ 170.00 *600*

Towing Fees

\$ *nn* 170.00 *X*

To transfer of rear windscreen glass to facilitate bodywork repair.

\$ *nn* 170.00 *X*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 495P**AAD1911-142**

TOTAL	\$	17,170.00
--------------	-----------	------------------

Over All Total	\$	35,212.02
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~25 DAYS~~

5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: