

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 495P**AAD1911-142***Not Authorised**Recovery B4 paint**\$ 7334.56*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

19 NOV 2019

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 495P

VF1ABL15AUC283508

RENAULT

LATITUDE

15.11.19

AIG

30/11/2017

PART		LIST	
1	DOOR PANEL REAR LH	\$	B ₁ 758.70 ✓
1	DOOR GUIDE REAR LH	\$	S ₁ 136.40
1	DOOR HINGE UPPER LH	\$	N 180.70
1	DOOR HINGE LOWER LH	\$	N 169.90
1	DOOR CHECK REAR LH/RH L70Y	\$	S ₁ 114.90
1	DOOR WHEATHESTRIIP REAR LH	\$	S ₁ 240.50
1	DOOR SEAL REAR LH	\$	S ₁ 119.40 } X
1	DOOR GLASS RUNNER SEAL REAR LH	\$	S ₁ 116.10
1	DOOR MOULDING REAR LH	\$	S ₁ 100.50
1	DOOR FINISHER REAR LH	\$	S ₁ 230.30
1	DOOR HANDLE OUTER REAR LH L70Y	\$	N ₁ 42.10 ✓
1	DOOR REGULATOR REAR LH L70Y	\$	B ₁ 657.10 =
1	DOOR REGULATOR MOTOR REAR LH L70Y	\$	T ₁ 450.60 =
1	DOOR WAIST SEAL OUTER REAR LH L70Y	\$	S ₁ 169.60 X
1	DOOR BLIND REAR LH L70Y	\$	S ₁ 506.90 X
1	DOOR PANEL FRT LH	\$	B ₁ 2,844.66 ✓
1	DOOR HINGE UPPER LH	\$	N 274.50 X
1	DOOR HINGE LOWER LH	\$	M ₁ 300.55 ✓
1	DOOR CHECK FRT LH	\$	S ₁ 90.90
1	DOOR LOCK FRT LH	\$	N 453.80
1	DOOR CATCH FRT LH	\$	N 73.70
1	DOOR REGULATOR FRT LH	\$	N 758.10
1	DOOR REGULATOR MOTOR FRT LH	\$	S ₁ 501.40 } X
1	DOOR REGULATOR GUIDE FRT LH	\$	S ₁ 69.00
1	DOOR MOULDING FRONT LH	\$	S ₁ 100.50
1	DOOR FINISHER FRONT LH	\$	S ₁ 258.90
1	DOOR BLIND FRONT LH	\$	S ₁ 506.90
1	DOOR WHEATHESTRIIP FRONT LH	\$	S ₁ 316.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 495P**AAD1911-142**

1	DOOR SEAL FRONT LH	\$	Sn	69.60	} X
1	DOOR SEAL LOWER FRONT LH	\$	Sn	93.90	
1	DOOR GLASS RUNNER SEAL FRONT LH	\$	Sn	332.00	
1	DOOR WAIST SEAL OUTER FRONT LH	\$	Sn	92.20	
1	DOOR HANDLE OUTER FRONT LH	\$	Sn	169.50	
1	DOOR HANDLE CAP FRONT LH	\$	Sn	17.30	
1	DOOR HANDLE SEAL FRT LH L70Y	\$	Sn	1.60	
1	DOOR HANDLE COVER FRT LH L70Y	\$	Sn	6.10	
1	DOOR HANDLE MODULE FRT LH L70Y	\$	Sn	133.40	
1	DOOR MIRROR ASSY LH	\$	Sn	727.90	
1	DOOR HARNESS WIRE LH	\$	Sn	2,670.00	
1	ROCKER PANEL INNER GARNISH LH	\$	Sn	466.51	
1	ROCKER PANEL INNER LH	\$	M	1,024.79	
1	ROCKER PANEL OUTER LH	\$	M	1,184.99	
1	ROCKER PANEL CENTER LH	\$	M	990.25	
TOTAL		\$		18,522.65	
10%		\$		1,852.26	
		\$		16,670.39	

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	M	100.00	60sn	}	X
1	FRONT DOOR STICKER 'Trans-Cab'	\$	M	80.00	60sn		
1	FRONT DOOR STICKER 'Classic'	\$	M	80.00	15sn		
1	DOOR CHECK BOLT	\$	S _n	22.69			
1	DOOR GUIDE SCREW	\$	S _n	10.85			
1	DOOR HINGE BOLT	\$	S _n	10.85			
1	DOOR HINGE NUT LH	\$	S _n	14.60			
1	DOOR CHECK BOLT	\$	S _n	22.69			
1	DOOR CHECK NUT	\$	S _n	3.75			
1	DOOR LOCK SCREW L70Y	\$	S _n	6.12			
1	DOOR CATCH SCREW L70Y	\$	S _n	10.06			
1	REAR LEFT TYRE	\$	S _n	300.00			
1	REAR LEFT TYRE RIM	\$	S _n	380.00			
1	TYRE RIM COVER LH	\$	S _n	50.00			
2	REAR WINDSCREEN SEALANT	\$	M	80.00			
1	WINDSCREEN MOULDING	\$	M	100.00			
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	M	100.00			

Trans-cab Auto Services Pte Ltd**AAD1911-142**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 495P

TOTAL	\$	1,371.63
--------------	-----------	-----------------

TOTAL PARTS	\$	18,042.02
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 7,500.00 *body*

Putty and spray painting of the affected portion.

\$ 7,500.00 *8801*

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ 380.00 *801*

To check steering geometry and computer wheel alignment

\$ *na* 220.00 *X*

To transfer of tire, rim and on wheel balancing.

\$ *na* 170.00 *X*

To rust-proofing of the affected areas.

\$ 170.00 *body*

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

To transfer of Rear door fittings, attachment and perform water seepage test.

\$ 170.00 *body*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *na* 380.00 *X*

To transfer of Front door fittings, attachment and perform water seepage test.

\$ 170.00 *body*

Towing Fees

\$ *na* 170.00 *X*

To transfer of rear windscreen glass to facilitate bodywork repair.

\$ *na* 170.00 *X*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 495P**AAD1911-142**

TOTAL	\$	17,170.00
--------------	-----------	------------------

Over All Total	\$	35,212.02
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)	25 DAYS	35,211.99#
------------------------------	---------------------------	-------------------

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: