

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 20106

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/TP/1386/2019/NS  
Date : 21-Nov-19

Vehicle NOT IN workshop. Kindly arrange for survey.  
Your insured vehicle no : **SMC 9395 G**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept  
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Lim Wenting Janell  
Address : 15 Dedap Link  
Singapore 809560  
Telephone : HP +65 96573839  
Type of Claim : Third Party Claim  
Policy No. : 1900105260  
Vehicle No : **SDP 9111 Y**  
Model Code : Audi A3 SEDAN 1.0 TFSI 8V  
Model / Year : Jun-19  
Engine No : CHZ C29277  
Chassis No : WAUZZZ8V1KA064690  
Mileage : -  
Date In : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 19-Nov-19  
Place of Accident : Entrance To CTE (From Yio Chu Kang Road)

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle SDP 9111 Y

| S/n                  | Nature of Jobs   | Estimated Charges | Surveyor's Recommendations |
|----------------------|--|-------------------|----------------------------|
| 1                    | To remove and transfer rear parking aid. Check function.   | S/N \$ 280.00 ✓   |                            |
| 2                    | To remove and transfer rear lid's convenience lock system and wire harness for tail lights.  | S/N \$ 280.00 X   |                            |
| 3                    | To dismantle and renew rear bumper and rear lid. Align to position. Re-organise rear crash management components. Reinstall all parts removed. | \$ 2,100.00 500   |                            |
| 4                    | To respray rear bumper and rear lid.   | \$ 1,700.00 1100  |                            |
| 5                    | To renew rear windscreen.  | S/N \$ 480.00 X   |                            |
| 6                    | To carry out diagnostic check.   | S/N \$ 192.00 ✓   |                            |
| TOTAL LABOUR CHARGES |  | : \$ 5,032.00     | \$ 2,072.00                |



# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SDP 9111 Y

| S/N                       | Parts Description                                     | Damaged Parts & Prices |                  |
|---------------------------|---|------------------------|------------------|
|                           |   | S/Nett                 | Remarks          |
| 1                         | REAR BUMPER / <i>BR</i>                               | \$ 1,708.00            | <i>1366.40</i>   |
| 2                         | REAR BUMPER FIXING PARTS ? <i>X NM</i>                | \$ 175.00              |                  |
| 3                         | REAR BUMPER LOCKING MECHANISM - LH / RH ? <i>X NM</i> | \$ 24.00               |                  |
| 4                         | REAR BUMPER SPOILER - LH <i>X / CUT</i>               | \$ 216.00              | <i>172.80</i>    |
| 5                         | REAR LIGHT REFLECTOR - LH / RH <i>X NM</i>            | \$ 54.00               |                  |
| 6                         | REAR PARKING AID SENSOR - INNER / OUTER <i>21</i>     | \$ 462.00              | <i>184.80</i>    |
| 7                         | REAR BUMPER SIDE REINFORCEMENT BEAM ? <i>X NM</i>     | \$ 522.00              |                  |
| 8                         | REAR BUMPER BRACKET - LH ? <i>X NM</i>                | \$ 25.00               |                  |
| 9                         | REAR BUMPER BRACKET - RH ? <i>X NM</i>                | \$ 26.00               |                  |
| 10                        | REAR BUMPER GUIDE SECTION - LH / RH ? <i>X NM</i>     | \$ 120.00              |                  |
| 11                        | REAR LID <i>X R</i>                                   | \$ 1,864.00            |                  |
| 12                        | REAR LID ATTACHMENT PARTS <i>X NM</i>                 | \$ 267.00              |                  |
| 13                        | REAR LID BALL STUD <i>X NM</i>                        | \$ 37.00               |                  |
| 14                        | PACKING ADHESIVE / <i>N/C</i>                         | \$ 18.00               | <i>13.92</i>     |
| 15                        | AUDI EMBLEM / <i>N/C</i>                              | \$ 113.00              | <i>90</i>        |
| 16                        | A3 INSCRIPTION / <i>N/C</i>                           | \$ 87.00               | <i>69.78</i>     |
| 17                        | REAR WINDSCREEN <i>X NM</i>                           | \$ 742.00              |                  |
| 18                        | PRIMER <i>X NM</i>                                    | \$ 19.00               |                  |
| 19                        | SPOILER FIXING PARTS <i>X NM</i>                      | \$ 152.00              |                  |
| 20                        | REAR WINDSCREEN SEALANT <i>X NM</i>                   | \$ 200.00              |                  |
| 21                        | REAR NO PLATE <i>X NM</i>                             | \$ 40.00               |                  |
| 22                        | SUNDRIES ? <i>X NM</i>                                | \$ 400.00              |                  |
| TOTAL SPARE PARTS CHARGES |   | \$ 7,271.00            | <i>41,897.20</i> |

TOTAL *£/P* \$ *3,969.20*

*5 DAYS*

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name  
Surveyed Date  
Authorised Date  
Excess Cost  
Liability  
Remarks

: Steve (LKK) WH Proj-L  
: 25/11/19, 1.30 pm  
: 58 days  
: P/P  
: Ry Befe sm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Please Note

: This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel: 6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant