

**MOTORWAY**

1094 Lower Delta Road Motorway Building Singapore 169205

Main +65.6468 2200 | Fax +65.6273 5535

INDIA INTERNATIONAL INSURANCE PTE LTD
 MOTOR CLAIMS DEPARTMENT
 64 Cecil Street
 #04 / #05 IOB Building
 SINGAPORE 047911

ESTIMATES

VEHICLE NO. : SKZ8233A
 CHASSIS NO : KPT30B1VSFP042083
 ENGINE NO : 17391002028296
 MAKE / MODEL : SSANGYONG / TIVOLI 1.6G 6AT ABS 2WD3
 YEAR : 2005
 DATE OF ACCIDENT : 10.11.2019 @ 1830HRS

YOUR INSURED VEHICLE NUMBER : SHA2411J

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	<u>PARTS DISCRPTION</u>	<u>QTY</u>	<u>List Price</u>	<u>Total List Price</u>
1	FRONT BONNET	1	\$ 1,200.00	\$ 1,200.00 X nn
2	FRONT RADIATOR GRILLE	1	\$ 180.00	\$ 180.00 X nn
3	FRONT SSANGYONG LOGO	1	\$ 110.00	\$ 110.00 X nn
4	FRONT BUMPER UPPER	1	\$ 1,100.00	\$ 1,100.00 de
5	FRONT LOWER BUMPER LH	1	\$ 120.00	\$ 120.00 X nn
6	FRONT LOWER BUMPER RH	1	\$ 120.00	\$ 120.00 ?
7	FRONT BUMPER TOW COVER	1	\$ 75.00	\$ 75.00 X
8	FRONT BUMPER RETAINER LH	1	\$ 89.00	\$ 89.00 ?
9	FRONT BUMPER RETAINER RH	1	\$ 89.00	\$ 89.00 ?
10	FRONT BUMPER CENTER REINFORCEMENT	1	\$ 95.00	\$ 95.00 ?
11	FRONT BUMPER INNER FOAM	1	\$ 150.00	\$ 150.00 ?
12	FRONT BUMPER REINFORCEMENT	1	\$ 550.00	\$ 550.00 ?
13	FRONT BUMPER LOWER GRILLE	1	\$ 145.00	\$ 145.00 de
14	FRONT HEADLAMP LH	1	\$ 1,900.00	\$ 1,900.00 X
15	FRONT HEADLAMP RH	1	\$ 1,900.00	\$ 1,900.00 X
16	FOGLAMP LH	1	\$ 175.00	\$ 175.00 X
17	FOGLAMP RH	1	\$ 175.00	\$ 175.00 X
18	SKID PLATE	1	\$ 95.00	\$ 95.00 X
19	FRONT SUPPORT PANEL	1	\$ 1,100.00	\$ 1,100.00 X
20	REAR BOOTLID	1	\$ 1,200.00	\$ 1,200.00 de
21	REAR BOOT LOCK	1	\$ 280.00	\$ 280.00 X nn
22	REAR BOOT SSANG YONG LOGO	1	\$ 110.00	\$ 110.00 de
23	REAR BOOT TIVOLI EMBLEM	1	\$ 89.00	\$ 89.00 de
24	REAR BOOT SSANGYONG EMBLEM	1	\$ 89.00	\$ 89.00 de
25	REAR WINDSCREEN MOULDING	1	\$ 250.00	\$ 250.00 de
26	REAR BUMPER UPPER	1	\$ 1,000.00	\$ 1,000.00 Gpa
27	REAR LOWER BUMPER LH	1	\$ 145.00	\$ 145.00 de
28	REAR LOWER BUMPER RH	1	\$ 145.00	\$ 145.00 de
29	REAR BUMPER RETAINER LH	1	\$ 89.00	\$ 89.00 X nn
30	REAR BUMPER RETAINER RH	1	\$ 89.00	\$ 89.00 X nn

4380

31	REAR BUMPER TOW COVER	1	\$	75.00	\$	75.00	xm.
32	REAR BUMPER LOWER BRACKET	1	\$	89.00	\$	89.00	del
33	REAR BUMPER REINFORCEMENT	1	\$	580.00	\$	580.00	? crm
34	REAR TAILLAMP LH	1	\$	850.00	\$	850.00	xm
35	REAR TAILLAMP RH	1	\$	850.00	\$	850.00	xm
36	REAR FOGLAMP	1	\$	450.00	\$	450.00	cm
37	REAR BUMPER REFLECTOR LENS LH	1	\$	120.00	\$	120.00	? x
38	REAR BUMPER REFLECTOR LENS RH	1	\$	120.00	\$	120.00	? x
39	REAR BOOT LICENSE PLATE GARNISH	1	\$	350.00	\$	350.00	? x

Total \$ 16,338.00
 LESS 10% \$ 163.38
 Total \$ 16,174.62

5392
 10% - 4852.80.

SPECIAL NETT ITEM

1	FRONT BUMPER CLIPS	1	\$	40.00	\$	30 40.00	new
2	FRONT NUMBER PLATE W FRAME	1	\$	40.00	\$	40.00	cm
3	FRONT BUMPER CLIPS	1	\$	40.00	\$	40.00	* Rejected
4	REAR WINDSCREEN SEALANT	1	\$	60.00	\$	60.00	new
5	REAR NUMBER PLATE W FRAME	1	\$	40.00	\$	40.00	cm
6	REAR BUMPER CLIPS	1	\$	40.00	\$	30 40.00	new
TOTAL SPECIAL NETT					\$	260.00	200.

LABOUR

1	TO DISMANTLE FRONT DAMAGE PARTS, CUT AND WELD FRONT SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S FRONT CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.	\$	1,200.00	400
2	TO PUTTY & SPRAY PAINTING ON FRONT AFFECTED AREAS	\$	1,000.00	450
3	TO REMOVE, REARRANGE ELECTRICAL WIRING, CHECK LIGHTING & RESET HEADLAMP FOCUSING	\$	180.00	30
4	TO DISMANTLE REAR DAMAGE PARTS, CUT AND WELD REAR SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.	\$	1,600.00	1000
5	TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS	\$	1,000.00	900
6	REMOVE & REFIT REAR WINDSCREEN GLASS	\$	180.00	120
7	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	\$	180.00	60
8	TO CARRY OUT DIAGNOSTIC TEST	\$	400.00	200
9	TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS	\$	180.00	30
Total Labour		\$	5,920.00	3190
SUB ToTal		\$	22,354.62	
GST @ 7%		\$	1,564.82	
Grand Total		\$	23,919.44	

LABOUR PER DAY - \$400
 SPRAY PAINT - \$450

Prepared By :-
 ANNIE TEW
 Motor Claims
 TEL: 6571 9642 FAX: 6278 5535
 EMAIL: ainee@motorway.com.sg

Parts - 4852.80.

SN - 200

Labour - 3190

8242.80.

1/5 @ 6600

8 days #

Taufik 97495749/67418434
 WP'

21/11/19 @ 945.

8 days.

taufik@lkkauto.com

sur@lkkauto.com

Lumpsum

Resumey after repair

17/12 Email to Ainee

4/5 @ 6600, 8 days