

ASS. REC. BY:

REF:

AIG/

20577/11/14

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 File pass to

81201 \$900.00

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Veh No:

S110 98421

Yr Regn:

04, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude c.c

1995

Colour

M-White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

510384

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VIFIABL15AUC 277508

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S / Rim / STD A / Rim or

Tyre Size:

F: Bailun 215/60R16

R: Giti

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

15/11/19

D.O.I.

19/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rear body

The UIC / Chassis frame / Body Structure affected due to collision.

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9842L**AAD1911-125***Not Authorised**SHD 9842L**L/S = \$ 900.00*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 9842L

VF1ABL15AUC277508

RENAULT

LATITUDE

15.11.19

AIG

25/4/2014

PART		LIST	
1	DOOR PANEL REAR RH	\$	758.70
1	DOOR HANDLE OUTER REAR RH	\$	42.10
1	DOOR LOCK REAR RH	\$	467.30
1	ROCKER PANEL INNER GARNISH RH	\$	466.51
1	ROCKER PANEL INNER RH	\$	1,024.79
1	ROCKER PANEL OUTER RH	\$	1,184.99
1	ROCKER PANEL CENTER RH	\$	990.25
1	FENDER PANEL REAR RH	\$	1,933.20
1	FENDER PANEL INNER TRIM REAR RH	\$	671.45
1	WHEELARCH REAR RH	\$	275.40
1	BUMPER COVER REAR	\$	561.70
1	BUMPER LOWER REAR	\$	411.90
1	BUMPER BRACKET CTR REAR	\$	98.10
1	BUMPER BRACKET SIDE RH REAR	\$	82.10
1	BUMPER RETAINER RH REAR	\$	59.80
1	BUMPER REFLECTOR RH	\$	16.60
1	TAILLAMP RH	\$	313.10
1	EXHAUST CAP REAR	\$	125.40
TOTAL		\$	9,483.39
10%		\$	948.34
		\$	8,535.05

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	80.00	<i>60.00</i>
1	FENDER INNER TRIM CLIP RH	\$	28.00	<i>X</i>
1	TAILLAMP CLIP RH	\$	5.00	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1911-125**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9842L

1SET	FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00
2	REAR WINDSCREEN SEALANT	\$	nn	80.00
1	WINDSCREEN MOULDING	\$	nn	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00
1	REAR RIGHT TYRE	\$	pu	300.00
1	REAR RIGHT TYRE RIM	\$	pu	380.00
1SET	PARKING AID	\$	pu	700.00
1SET	REAR BUMPER CLIP	\$	nn	66.00
1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00
1SET	BUMPER RETAINER CLIP RH RR	\$	nn	20.00
1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00
1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00
1	EXHAUST MOUNTING REAR	\$	nn	16.00
TOTAL		\$		2,041.00

TOTAL PARTS	\$	10,576.05
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$

6,000.00

6,000.00 4000

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$

nn 380.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$

nn 380.00 X

To check steering geometry and computer wheel alignment

\$

nn 220.00 X

To transfer of rear windscreen glass to facilitate bodywork repair.

\$

nn 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1911-125**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9842L

To transfer of Rear door fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To rust-proofing of the affected areas.	\$	~ 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	101
To reinstall rear bumper parking sensor.	\$	~ 170.00	X
Putty and spray painting of the affected portion.	\$	6,000.00	6601
To repair and realign rear exhaust pipe.	\$	~ 170.00	X
TOTAL	\$	15,140.00	
Over All Total	\$	25,716.05	

LUMP SUM (REPAIR DAY)~~20 DAYS~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: