

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5789P****AAD1911-146***Not Authored**C/Sing @ 3400h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

20 NOV 2019

**SHC 5789P**

VF1ABL15AUC281613

RENAULT

LATITUDE

18.11.19

**III**

16/7/2015

**PART****LIST**

|   |                               |    |            |
|---|-------------------------------|----|------------|
| 1 | DOOR PANEL REAR LH            | \$ | 758.70 X   |
| 1 | DOOR PANEL FRT LH             | \$ | 2,844.66 ✓ |
| 1 | DOOR HINGE UPPER LH           | \$ | 274.50     |
| 1 | DOOR HINGE LOWER LH           | \$ | 300.55     |
| 1 | DOOR CHECK FRT LH             | \$ | 90.90      |
| 1 | DOOR REGULATOR FRT LH         | \$ | 758.10     |
| 1 | DOOR REGULATOR MOTOR FRT LH   | \$ | 501.40     |
| 1 | DOOR REGULATOR GUIDE FRT LH   | \$ | 69.00      |
| 1 | DOOR BLIND FRONT LH           | \$ | 506.90     |
| 1 | DOOR WHEATHESTRIIP FRONT LH   | \$ | 316.00     |
| 1 | DOOR SEAL FRONT LH            | \$ | 69.60      |
| 1 | DOOR SEAL LOWER FRONT LH      | \$ | 93.90      |
| 1 | DOOR HANDLE OUTER FRT LH      | \$ | 169.50     |
| 1 | DOOR FINISHER FRT LH          | \$ | 258.90     |
| 1 | DOOR MOULDING FRT LH          | \$ | 100.50     |
| 1 | DOOR MIRROR ASSY LH           | \$ | 727.90     |
| 1 | DOOR HARNESS WIRE LH          | \$ | 2,670.00   |
| 1 | ROCKER PANEL INNER GARNISH LH | \$ | 466.51     |
| 1 | ROCKER PANEL INNER LH         | \$ | 1,024.79   |
| 1 | ROCKER PANEL OUTER LH         | \$ | 1,184.99   |
| 1 | ROCKER PANEL CENTER LH        | \$ | 990.25     |
| 1 | FENDER PANEL FRT LH           | \$ | 414.40 ✓   |
| 1 | WHEELARCH FRT LH              | \$ | 112.30 X   |
| 1 | FENDER BRACKET LOWER LH       | \$ | 11.80 X    |
| 1 | FENDER INSULATOR LH           | \$ | 65.50 X    |
| 1 | FENDER BRACKET FRT LH         | \$ | 38.90 X    |
| 1 | AIR CLEANER BOX               | \$ | 464.20 X   |
| 1 | AIR CLEANER HOSE              | \$ | 175.85 X   |

**Trans-cab Auto Services Pte Ltd****AAD1911-146**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5789P**

|   |                                 |    |          |
|---|---------------------------------|----|----------|
| 1 | AIR CLEANER LOWER               | \$ | 271.26   |
| 1 | BUMPER COVER FRT                | \$ | 747.20   |
| 1 | BUMPER SPOILER FRT              | \$ | 344.70   |
| 1 | BUMPER ABSORBER FRT             | \$ | 394.68   |
| 1 | BUMPER RETAINER FRT LH          | \$ | 101.40   |
| 1 | BUMPER SUPPORT FRT              | \$ | 10.70    |
| 1 | BUMPER UNDERTRAY FRT            | \$ | 292.50   |
| 1 | BUMPER GRILLE LOWER FRT         | \$ | 147.00   |
| 1 | BUMPER FOG LAMP GRILLE LH       | \$ | 207.21   |
| 1 | BONNET                          | \$ | 1,312.70 |
| 1 | BONNET INSULATOR                | \$ | 294.30   |
| 1 | BONNET STRUT LH                 | \$ | 53.30    |
| 1 | BONNET HINGE LH                 | \$ | 236.50   |
| 1 | RADIATOR GRILLE                 | \$ | 969.90   |
| 1 | RADIATOR GRILLE BADGE 'RENAULT' | \$ | 225.36   |
| 1 | RADIATOR GRILLE FRAME           | \$ | 686.00   |
| 1 | FRAME FULL SUPPORT PANEL        | \$ | 592.70   |
| 1 | FRAME FULL SUPPORT BRACKET      | \$ | 41.60    |
| 1 | HEADLAMP LH                     | \$ | 743.60   |
| 1 | HEADLAMP PANEL FRT LH           | \$ | 127.70   |
| 1 | LOWER ARM LH L70Y               | \$ | 192.70   |
| 1 | KNUCKLE ARM LH L70Y             | \$ | 481.50   |
| 1 | ABSORBER FRT LH L70Y            | \$ | 274.10   |
| 1 | DRIVESHAFT LH                   | \$ | 1,355.70 |
| 1 | STABILIZER BAR FRT              | \$ | 427.90   |

**TOTAL \$ 25,992.71****10% \$ 2,599.27****\$ 23,393.44****Special Nett**

|   |                                |    |                                  |
|---|--------------------------------|----|----------------------------------|
| 1 | REAR DOOR STICKER '6555-3333'  | \$ | <i>nn na</i> 100.00 <i>655 X</i> |
| 1 | FRONT DOOR STICKER 'Trans-Cab' | \$ | <i>nn</i> 80.00 <i>605n</i>      |
| 1 | FRONT DOOR STICKER 'Classic'   | \$ | <i>nn</i> 80.00 <i>155n</i>      |
| 1 | DOOR GUIDE SCREW               | \$ | <i>nn</i> 10.85 <i>X</i>         |
| 1 | DOOR CHECK BOLT                | \$ | <i>nn</i> 22.69 <i>X</i>         |
| 1 | DOOR HINGE BOLT                | \$ | <i>nn</i> 10.85 <i>X</i>         |
| 1 | DOOR HINGE NUT LH              | \$ | <i>nn</i> 14.60 <i>X</i>         |

**Trans-cab Auto Services Pte Ltd****AAD1911-146**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5789P**

|              |                                 |           |    |                 |
|--------------|---------------------------------|-----------|----|-----------------|
| 1            | DOOR CHECK NUT                  | \$        | nn | 3.75            |
| 1            | FRONT LEFT TYRE                 | \$        | Sh | 300.00          |
| 1            | FRONT LEFT TYRE RIM             | \$        | Sh | 380.00          |
| 1            | BUMPER CLIP FRT                 | \$        | nn | 66.00           |
| 1            | BUMPER BRACKET CLIP FRT LH      | \$        | nn | 12.00           |
| 1            | BUMPER SUPPORT CLIP FRT LH      | \$        | nn | 10.50           |
| 1            | BUMPER GRILLE LOWER CLIP        | \$        | nn | 69.00           |
| 1            | WHEELARCH CLIP FRT LH           | \$        | nn | 30.50           |
| 1            | FRAME FULL SUPPORT PANEL CLIP   | \$        | nn | 70.00           |
| 1SET         | FRAME FULL SUPPORT PANEL NUT    | \$        | nn | 20.00           |
| 2            | FRAME FULL SUPPORT PANEL STUD   | \$        | nn | 30.00           |
| 1SET         | RADIATOR GRILLE SCREW           | \$        | nn | 16.00           |
| 1SET         | RADIATOR GRILLE FRAME CLIP      | \$        | nn | 52.00           |
| 1SET         | Front licence plate with holder | \$        | Sh | 80.00           |
| 6            | BONNET INSULATOR CLIP L70Y      | \$        | nn | 7.30            |
| 2            | BONNET CABLE CLIP L70Y          | \$        | nn | 6.31            |
| 2            | BONNET CABLE COVER SCREW L70Y   | \$        | nn | 10.85           |
| <b>TOTAL</b> |                                 | <b>\$</b> |    | <b>1,483.22</b> |

**TOTAL PARTS \$ 24,876.66****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 7,500.00 400

Putty and spray painting of the affected portion.

\$ 7,500.00 700

To rust-proofing of the affected areas.

\$ 170.00 60

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

To check steering geometry and computer wheel alignment

\$ nn 220.00 X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5789P****AAD1911-146**

|                                                                                               |           |                  |     |
|-----------------------------------------------------------------------------------------------|-----------|------------------|-----|
| To transfer of tire, rim and on wheel balancing.                                              | \$        | na 170.00        | X   |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.               | \$        | na 380.00        | X   |
| To transfer of Rear door fittings, attachment and perform water seepage test.                 | \$        | 170.00           | X   |
| To Check Electrical Lighting Concerned.                                                       | \$        | 170.00           | 201 |
| To transfer of Front door fittings, attachment and perform water seepage test.                | \$        | 170.00           | 601 |
| To dismantle and refit front end suspension, undercarriage parts, final checking and testing. | \$        | na 380.00        | X   |
| To transfer of front bumper fittings, attachment and perform water seepage test.              | \$        | na 170.00        | X   |
| To transfer of front fender fittings, attachment and perform water seepage test.              | \$        | na 170.00        | X   |
| To transfer of front bonnet fittings, attachment and perform water seepage test.              | \$        | na 170.00        | X   |
| <b>TOTAL</b>                                                                                  | <b>\$</b> | <b>17,720.00</b> |     |
| <b>Over All Total</b>                                                                         | <b>\$</b> | <b>42,596.66</b> |     |

**LUMP SUM (REPAIR DAY)**~~25 DAYS~~

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: