

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : QBE INSURANCE (SINGAPORE) PTE LTD
1 RAFFLES QUAY
#29-10 SOUTH TOWER
SINGAPORE 048583

TEL: 62246633

FAX: 65345356

ATTN: Motor Claim Department

Claim Type: Third Party

Accident Date: 18/11/2019

TP Veh Reg No: SLF4834K

Estimate No: EST1900388

Date: 19 Nov 2019

Veh Reg No: SMN248A

Make/Model: TOYOTA WISH 1.8CVT

Chasis No: JTDGG20W80J002227

Reg. Date: 16/03/2015

Your Ref No: SLF4834K

Estimate Repair Cost to Vehicle No :SMN248A

Quantity	Description	List Price S\$	Amount S\$
	List Price		
1	1 PC BOOT LID <i>Dented</i>	1,175.90	✓
2	1 PC BOOT LID LOGO <i>new</i>	66.20	✓
3	1 PC BOOTLID "ELEGANCE" EMBLEM <i>new</i>	53.20	✓
4	1 PC BOOTLID "VALVE MATIC" EMBLEM <i>new</i>	58.30	✓
5	1 PC BOOT LID CHROME <i>Replaced</i>	347.60	2 ✓
6	1 PC BOOT LID LAMP LH <i>new new</i>	288.40	+
7	1 PC BOOT LID LAMP RH <i>Replaced</i>	288.40	✓ ✓
8	1 PC BOOT LID OUTER OPENER HANDLE <i>new</i>	61.60	+
9	1 PC BOOT LID LOCK <i>new</i>	361.60	✓
10	1 PC BOOT LID LOCK CHECKER <i>new</i>	51.60	+
11	1 PC BOOT LID RUBBER <i>new</i>	314.60	✓
12	1 PC BOOT LID TRIM <i>Replaced</i>	328.20	2 ✓
13	1 PC REAR WINDSCREEN RUBBER <i>new</i>	125.50	✓
14	1 PC REAR FENDER INNER TRIM RH <i>Dented</i>	724.30	✓ 681.40
15	1 PC SPARE TYRE TOP HARDBOARD <i>Replaced</i>	562.90	446. ✓
16	1 PC REAR PANEL <i>Dented</i>	453.90	✓
17	1 PC REAR PANEL TRIM <i>Replaced</i>	253.20	✓
18	1 PC REAR PANEL LOWER MEMBER <i>Best</i>	268.40	✓
19	1 PC TAIL LAMP LH <i>new</i>	472.60	+
20	1 PC TAIL LAMP - RH <i>Replaced</i>	472.60	2 ✓
21	1 PC REAR BUMPER <i>Dishled</i>	562.90	✓
22	2 PCS REAR BUMPER BRACKET <i>Dented RH Dented</i>	104.80	52.40 ✓
23	2 PCS REAR BUMPER SIDE RETAINER <i>3m</i>	179.80	✓
24	2 PCS REAR BUMPER SMALL RETAINER	117.80	✓
25	1 PC REAR BUMPER REFLECTOR - RH <i>new</i>	52.40	+
26	2 PCS REVERSE SENSOR <i>new</i>	764.40	✓
27	1 PC REAR ANTENNA SENSOR RELAY <i>Replaced</i>	187.70	2 ✓
28	1 PC EXHAUST PIPE <i>new new</i>	892.60	+
29	1 PC BONNET <i>Replaced</i>	698.80	✓

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S: QBE INSURANCE (SINGAPORE) PTE LTD
1 RAFFLES QUAY
#29-10 SOUTH TOWER
SINGAPORE 048583

TEL: 62246633 FAX: 65345356
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 18/11/2019
TP Veh Reg No: SLF4834K

Estimate No: EST1900388

Date: 19 Nov 2019

Veh Reg No: SMN248A

Make/Model: TOYOTA WISH 1.8CVT

Chasis No: JTDGG20W80J002227

Reg. Date: 16/03/2015

Your Ref No: SLF4834K

Estimate Repair Cost to Vehicle No :SMN248A

Quantity	Description	List Price	Amount
		SS	SS
30	2 PCS BONNET HINGE <i>Neu</i>	103.40 <i>+</i>	
31	1 PC BONNET EMBLEM <i>Neu</i>	98.90 <i>✓</i>	
32	1 PC BONNET RUBBER <i>Neu</i>	71.90 <i>+</i>	
33	1 PC BONNET LOCK <i>Best</i>	94.60 <i>✓</i>	
34	1 PC FRT BRACE PANEL <i>Best</i>	84.60 <i>✓</i>	
35	1 PC FRT SUPPORT PANEL <i>Best</i>	1,179.50 <i>+</i>	
36	1 PC FRT SUPPORT PANEL TRIM <i>Best</i>	115.70 <i>✓</i>	
37	1 PC FRT GRILLE <i>Best</i>	462.70 <i>✓</i>	
38	1 PC HEADLAMP LH <i>Best</i>	1,150.70 <i>✓</i>	
39	1 PC HEADLAMP RH <i>Best</i>	1,150.70 <i>✓</i>	
40	1 PC FRT BUMPER <i>Best</i>	574.90 <i>✓</i>	
41	1 PC FRT BUMPER REINFORCEMENT <i>Best</i>	275.30 <i>✓</i>	
42	1 PC FRT BUMPER SPONGE <i>Best</i>	99.60 <i>✓</i>	
43	2 PCS FRT BUMPER BRACKET <i>Neu</i>	148.80 <i>+</i>	
44	2 PCS FRT BUMPER SIDE RETAINER <i>Neu</i>	199.20 <i>✓</i>	
45	1 PC FRT FOG LAMP RH <i>Best</i>	278.10 <i>+</i>	
46	1 PC FRT FOG LAMP COVER RH <i>Best</i>	75.70 <i>+</i>	
47	1 PC FRT FOG LAMP SIDE COVER <i>Best</i>	66.80 <i>+</i>	
48	1 PC AIRCON CONDENSER <i>Best</i>	1,404.40 <i>✓</i>	
49	1 PC RADIATOR <i>Best</i>	1,608.40 <i>✓</i>	
		19,534.10	
	Less 25%	4,883.53	14,650.67

Special Net

50	1 PC REAR NUMBER PLATE <i>Best</i>	50.00 <i>✓</i>
51	1 SET BOOT LID TRIM CLIPS <i>Neu</i>	50.00 <i>30.00</i>
52	1 PC REVERSE CAMERA <i>Neu</i>	500.00 <i>+</i>
53	1 PC REAR WINDSCREEN SEAL <i>3pc</i>	60.00 <i>✓</i>
54	1 PC REAR WINDSCREEN SEALANT <i>3pc</i>	60.00 <i>✓</i>
55	1 SET REAR FENDER INNER TRIM CLIPS RH <i>Neu</i>	48.00 <i>30.00</i>
56	1 SET REAR PANEL TRIM CLIPS <i>Neu</i>	48.00 <i>10.00</i>

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6 #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201306201N

M/S: QBE INSURANCE (SINGAPORE) PTE LTD
1 RAFFLES QUAY
#29-10 SOUTH TOWER
SINGAPORE 048583
TEL: 62246633 FAX: 65345356
ATTN: Motor Claim Department

Estimate No: EST1900388

Date: 19 Nov 2019

Veh Reg No: SMN248A

Make/Model: TOYOTA WISH 1.8CVT

Chasis No: JTDGG20W80J002227

Reg. Date: 16/03/2015

Your Ref No: SLF4834K

Claim Type: Third Party

Accident Date: 18/11/2019

TP Veh Reg No: SLF4834K

Estimate Repair Cost to Vehicle No :SMN248A

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
57	1 SET REAR BUMPER CLIPS <i>ne</i>	40.00 30	
58	1 SET BONNET TRIM CLIPS <i>not a</i>	48.00 +	
59	1 SET FRT SUPPORT PANEL TRIM CLIPS <i>ne</i> 380	40.00 10	
60	1 SET FRT GRILLE CLIPS <i>ne</i>	30.00 20	
61	1 SET FRT BUMPER CLIPS <i>ne</i>	40.00 30	
62	1 PC FRT NUMBER PLATE <i>Del</i>	50.00 ✓	
		1.064.00	1.064.00
	Labour		
63	1 TO CHECK WIRING	50.00 30 ✓	
64	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00 ✓	
65	1 TO REMOVE AND REFIT INNER TRIM	150.00 80	
66	1 TO REFIX THIRD BRAKE LIGHT	100.00 x	
67	1 TO REMOVE AND REFIT REVERSE CAMERA	100.00 50	
68	1 TO REMOVE AND REFIT REVERSE SENSOR	100.00 50	
69	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	150.00 x	
70	1 TO SPRAY UNDERSEAL	120.00 60	
71	1 (REAR) TO SPRAY PAINTING	1,400.00 1000	
72	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,500.00 900	
73	1 TO CHECK WIRING	50.00 30	
74	1 TO REFILL AIRCON GAS	120.00 ✓	
75	1 TO SPRAY UNDERSEAL	100.00 x	
76	1 (FRONT) TO SPRAY PAINTING	1,200.00 700	
77	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00 700	
		6.460.00	6.460.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : QBE INSURANCE (SINGAPORE) PTE LTD
1 RAFFLES QUAY
#29-10 SOUTH TOWER
SINGAPORE 048583

TEL: 62246633 FAX: 65345356
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 18/11/2019
TP Veh Reg No: SLF4834K

Estimate No: EST1900388
Date: 19 Nov 2019

Veh Reg No: SMN248A
Make/Model: TOYOTA WISH 1.8CVT
Chasis No: JTDGG20W80J002227
Reg. Date: 16/03/2015
Your Ref No: SLF4834K

Estimate Repair Cost to Vehicle No :SMN248A

Quantity	Description	List Price SS	Amount SS
		Total	S\$ 22,174.67
		Add GST @ 7%	1,552.23
		Total Amount Payable	S\$ 23,726.90

TOTAL: SINGAPORE DOLLAR TWENTY THREE THOUSAND SEVEN HUNDRED TWENTY SIX AND CENTS NINETY ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 16175.60

L/S 12.9K

12.9K

Adrian Lj
L/S 19/11/19.

11 Dyp